

Vehicle:
Customer:
Operator:
Date (D/M/Y):09-06-2020

=====
BENZ_EN_TEST_00009>ML(164)>Diesel>164.122 - ML 320-350 CDI 4MATIC>Smart Scan>
ESP - Electronic Stability Program>Read Fault Code:
Total Number : 1

7286 1/1
State: Historic
CAN signal 'N72/1s24(Downhill Speed Regulation switch) ' from control module N72/1(Upper control panel control module) is unreasonable

=====
BENZ_EN_TEST_00009>ML(164)>Diesel>164.122 - ML 320-350 CDI 4MATIC>Smart Scan>
ECM - Engine Control Module(CDI4)>Read Fault Code:
Total Number : 2

2013-4 1/2
State: Historic
Check component B14(Ambient temperature display temperature sensor), CAN signal faulty

2267-1 2/2
State: Current
LIN message from component 'N14/3(Glow time output stage) ' faulty Faulty message or timeout

=====
BENZ_EN_TEST_00009>ML(164)>Diesel>164.122 - ML 320-350 CDI 4MATIC>Smart Scan>
DCM_RF - Door Control Module Right Front>Read Fault Code:
Total Number : 1

9014 1/1
State: Historic
S85/6(Right interior CL [ZV] switch): The component remains in the switched state(contact sticking) or has Short circuit to ground