

VIN	WDD1714561A001234	Model series/model designation	164
Order number		License plate	

Full list of fault codes and events

0607	The control unit has a malfunction.
9432	The Bluetooth antenna has a short circuit to ground.
9434	The Bluetooth antenna has an open circuit.
943B	Microphone 1 has a short circuit to ground.
943C	Microphone 1 has a short circuit to positive.
943E	Microphone 2 has a short circuit to ground.
943F	Microphone 2 has a short circuit to positive.
9461	Speaker channel 1 has a short circuit to ground.
9462	Speaker channel 1 has a short circuit to positive.
9463	Speaker channel 1 has an open circuit.
9464	Speaker channel 1 has a short circuit.
9466	Speaker channel 2 has a short circuit to ground.
9467	Speaker channel 2 has a short circuit to positive.
9468	Speaker channel 2 has an open circuit.
9469	Speaker channel 2 has a short circuit.
946B	Speaker channel 3 has a short circuit to ground.
946C	Speaker channel 3 has a short circuit to positive.
946D	Speaker channel 3 has an open circuit.
946E	Speaker channel 3 has a short circuit.
9470	Speaker channel 4 has a short circuit to ground.
9471	Speaker channel 4 has a short circuit to positive.
9472	Speaker channel 4 has an open circuit.
9473	Speaker channel 4 has a short circuit.
94B7	Microphone 1 has an open circuit.

94B8	Microphone 2 has an open circuit.
94D0	Radio antenna 1 has a short circuit to ground.
94D2	Radio antenna 1 has an open circuit.
94D3	Radio antenna 2 has a short circuit to ground.
94D5	Radio antenna 2 has an open circuit.
94D6	The GPS antenna has a short circuit to ground.
94D8	The GPS antenna has an open circuit.
94D9	The internal hard disk has a malfunction.
94DA	One or more function keys are jammed.
A19C	The wake-up line has a short circuit to ground.
A19D	The wake-up line has a short circuit to positive.
A38A	Fan 2 of the control unit has a malfunction.
D016	MOST communication has a malfunction (position of ring break cannot be identified).
D017	MOST communication has a malfunction (MOST master reporting ring break).
D018	MOST communication has a malfunction (ring break at position 1).
D019	MOST communication has a malfunction (ring break at position 2).
D020	MOST communication has a malfunction (ring break at position 3).
D021	MOST communication has a malfunction (ring break at position 4).
D022	MOST communication has a malfunction (ring break at position 5).
D023	MOST communication has a malfunction (ring break at position 6).
D024	MOST communication has a malfunction (ring break at position 7).
D157	Communication with the gyro sensor has a malfunction.
D180	The display screen is faulty.
D181	The background illumination of control unit COMAND or AUDIO is defective.
D308	Communication with mobile phone cradle has a malfunction.
DA00	Enabling of the Audio or COMAND is not possible due to a CAN fault.
DA01	Anti-theft protection is activated (control unit is disabled).
Event 1614	An internal control unit reset was performed.
Event 9422	There is an internal fault in the CD/DVD drive.
Event 942A	The radio receiver has overtemperature.
Event 94DB	The satellite radio receiver has overtemperature.
Event 94DD	The external audio amplifier has overtemperature.
Event 94DE	The media interface has overtemperature.
Event 94F8	The CD/DVD cannot be ejected.
Event 94F9	The internal hard disk is full.
Event 9536	An unauthorized mobile phone cradle is installed.
Event A10A	The power supply in the system is too low.
Event A10B	The power supply in the system is too high.
Event A10D	The power supply is too low.
Event A10E	The power supply is too high.
Event A27B	The specified and actual configurations of the MOST components are different.
Event A27D	The watchdog function has detected an internal software error.

Event C020	Interior CAN bus OFF fault
Event C146	Communication with the central gateway has a malfunction.
Event C155	Communication with the instrument cluster has a malfunction.
Event C168	Communication with the electronic ignition lock has a malfunction.
Event D005	The control unit is overheated.
Event D013	The MOST transmitter and receiver unit has overtemperature.
Event D178	Communication with the mobile phone has a malfunction.
Event D309	Communication with the Bluetooth module has a malfunction.
Event D850	An unknown MOST component is installed.

Filename: C:\Program
Files\Mercedes-Benz\DAS\bin\..\trees\pkw\most\tgw3\menues\mnTGW001.s

Cell co-ordinate: 19 , 36