VIN	WDB2110701A128450	Model series/model designation	164.
Order number		License plate	

Full list of fault codes and events

9000 Control unit N69/5 (Keyless Go control unit) is defective. 9040 M14/6 (Left front door central locking motor), Engine opening assists: Limit switch PERMANENTLY ACTUATED 9045 M14/6 (Left front door central locking motor), Engine opening assists: Limit switch NOT OPERATED 9060 M14/8 (CL left rear door motor), Engine opening assists: Limit switch PERMANENTLY ACTUATED 9065 M14/8 (CL left rear door motor), Engine opening assists: Limit switch NOT **OPERATED** 9080 M14/5 (Right front door central locking motor), Engine opening assists: Limit switch PERMANENTLY ACTUATED 9085 M14/5 (Right front door central locking motor), Engine opening assists: Limit switch NOT OPERATED 9100 M14/9 (CL right rear door motor), Engine opening assists: Limit switch PERMANENTLY ACTUATED 9105 M14/9 (CL right rear door motor), Engine opening assists: Limit switch NOT **OPERATED** 9110 A17/1 (Left front Keyless Go door handle): PERMANENTLY ACTUATED 9111 A17/3 (Left rear Keyless Go door handle): PERMANENTLY ACTUATED 9112 A17/2 (Right front Keyless Go door handle) : PERMANENTLY ACTUATED 9113 A17/4 (Right rear Keyless Go door handle) : PERMANENTLY ACTUATED 9118 A17/1 (Left front Keyless Go door handle): Short circuit to positive 9119 A17/3 (Left rear Keyless Go door handle): Short circuit to positive

Tuesday, June 20, 2017 03:12:17 Page 1/2 12/2016 (2016-10-06)\AddOns: ([6988) (7160) (7258) (6755) (6933) (7418) (7176) (6765) (7292) (6726) (6832) (7030) (6815) (6961) (6892) (6927) (6642) (6882) (6977) (6604) (7100) (7128) (6819) (7134) (7069) (6785) (7229) (6669) (6658) (7309) (7188) (6728) (6569) (6843) (6826) (6818) (6997) (6896) (7172) (7092) (6931) (7084) (6951) (6835) (6691) (7014) (6622) (6792) (6828) (6768) (6985) (6721) (6745) (7154) (6677) (7143) (6817) (6919) (6780) (6707) (6686) (6863) (7002) (6991) (6700) (6615) (6803) (6880) (6580) (6646) (6576) (6986) (6814) (6670) (7009) (7018) (6781) (6673) (6877) (6864) (6872) (7033) (7256) (7318) (6730) (7104) (6663) (7147) (6798) (6994) (6858) (6898) (6871) (7386) (6704) (7029) (6822) (6850) (6796) (7065) (6802) (6971) (6874) (7072) (7082) (6746) (7239) (6772) (6857) (6949) (7180) (6831) (7086) (6627) (6916) (7206) (6742) (7042) (6964) (6870) (7166) (7138) (7080) (7398) (6848) (6975) (7001) (6760) (6679) (6845) (6732) (6565) (6941) (6902) (6890) (6847) (6842) (6846) (7359) (6578) (7007) (7185) (7158) (7026) (6894) (6980) (6739) (7119) (6684) (6995) (6816) (6809) (6784) (6972) (6633) (6952) (6648) (6943) (6793) (6981) (7135) (7036) (6608) (6907) (7023) (6861) (7113) (7433) (7209) (7324) (6954) (7097) (6705) (6825) (6968) (6885) (6616) (6573) (6759) (6676) (6682) (6887) (6910) (7226) (6914) (6866) (7360) (6886) (7233) (7108) (6953) (5226) (7267) (7121) (7201) (7063) (6599) (7049) (7216) (6649) (7055) (6774) (6724) (7225) (6990) (6833) (6965) (6906) (6800) (7251) (6962) (6958) (7068) (7071) (6900) (7316) (7289) (6788) (6851) (6709) (6948) (6983) (6769) (6714) (7190) (6924) (6889) (6921) (6911) (7012) (7150) (5225) (7164) (7198) (6588) (6903) (6697) (6596) (6839) (7058) (6790) (7109) (6787) (7052) (6868) (7300) (6653) (7248) (6884) (7032) (6735) (7046) (6876) (6630) (6806) (6904) (6659) (7458) (6867) (7008) (6946) (7184) (6879) (6841) (6912) (6570) (7142) (7077) (6801) (6618) (6976) (73131)

911A A17/2 (Right front Keyless Go door handle): Short circuit to positive 911B A17/4 (Right rear Keyless Go door handle): Short circuit to positive

911C A17/1 (Left front Keyless Go door handle): Short circuit to ground / Signal faulty

Diagnosis Assistance System	Copyright 1999 Daimlei AG
911D A17/3 (Left rear Keyless Go door handle	e) : Short circuit to ground / Signal faulty
911E A17/2 (Right front Keyless Go door hand	dle) : Short circuit to ground / Signal faulty
911F A17/4 (Right rear Keyless Go door hand	le) : Short circuit to ground / Signal faulty
9220 Tailgate, "Lock" button: PERMANENTL	Y ACTUATED
9350 Antenna not or not correctly connected	
9361 A2/39 (Keyless Go antenna, left rear do	or) : Open circuit
9362 A2/41 (Keyless Go antenna, right rear d	oor) : Open circuit
9363 A2/60 (Cockpit Keyless Go antenna): O	pen circuit
9364 A2/35 (Keyless Go antenna, trunk) (W22	21), Tailgate (W164, X164, W251) : Open
circuit	
9371 A2/39 (Keyless Go antenna, left rear do	or) : Short circuit
9372 A2/41 (Keyless Go antenna, right rear d	oor) : Short circuit
9373 A2/60 (Cockpit Keyless Go antenna): S	hort circuit
9374 A2/35 (Keyless Go antenna, trunk) (W22	21), Tailgate (W164, X164, W251) : Short circuit
9381 At least one of the Keyless Go antennas	has Short circuit to positive.
9382 At least one of the Keyless Go antennas	has Short circuit to ground.
93A9 M14/6 (Left front door central locking me	otor) : Output 'Engine opening assists' is
overloaded.	
93AA M14/8 (CL left rear door motor): Output	'Engine opening assists' is overloaded.
93AB M14/5 (Right front door central locking i	notor) : Output 'Engine opening assists' is
overloaded.	
93AC M14/9 (CL right rear door motor) : Outp	
93AD At least one of the door handles is not p	olugged in or cannot be tested.
93AE A2/61 (Keyless Go antenna, interior): 0	Open circuit

93AF A2/61 (Keyless Go antenna, interior): Short circuit

Event 9010 Undervoltage supply:

Event 9011 Overvoltage supply:

Event 93B0 No CAN message was received from control unit EZS.

Filename: C:\Program

Files\Mercedes-Benz\DAS\bin\..\trees\pkw\fahrber\kg2\menues\mnfclistkg2.s

Cell co-ordinate: 1,6