

Vehicle Diagnostic Report

Car Information

Brand : BENZ

Read codes

Fault Code	Status	Description
9601	Stored	LIN bus error: Not within the valid voltage range
9803	Stored	Button 'Defrost mode (DEFROST)' sticks.
9804	Stored	Button 'Recirculated air' sticks.