


[Repair](#)
[TSB](#)
[Maint.](#)
[Estimator](#)
[Worksheet](#)

 You are here: [2014 Mercedes-Benz ML350 Bluetec 4Matic](#) > [TSB](#) > [Show All](#)
[TSBs](#) > [Choose Title](#)



## Choose TSB Title

### All TSBs - 421 Titles

OEM REF NO	TITLE	PUB DATE
<a href="#">VERSION 2</a>	<a href="#">PARKTRONIC SYSTEM HAS A MALFUNCTION</a>	<a href="#">2016-10-15</a>
<a href="#">VERSION 1</a>	<a href="#">ENGINE INDICATOR LAMP LIGHTS UP AND/OR PRESAFE, BLIND SPOT ASSIST AND DISTRONIC ERROR MESSAGES IN INSTRUMENT CLUSTER</a>	<a href="#">2016-11-01</a>
<a href="#">VERSION 1</a>	<a href="#">ENGINE SHAKES OR RUNS ROUGHLY - "COMBUSTION MISFIRE IN CYLINDER X" FAULTS ARE STORED IN THE ENGINE CONTROL UNIT</a>	<a href="#">2016-11-29</a>
<a href="#">VERSION 1</a>	<a href="#">GARMIN MAP PILOT: AFTER A NAVIGATION SOFTWARE UPDATE, THE USER IS INSTRUCTED TO CONNECT THE SD CARD WITH THE VEHICLE</a>	<a href="#">2016-10-25</a>
<a href="#">VERSION 1</a>	<a href="#">GARMIN MAP PILOT: TEST SD CARDS W 000 589 03 22 00 AND W 000 589 04 22 00 CANNOT BE USED</a>	<a href="#">2016-12-19</a>
<a href="#">TT 12/14</a>	<a href="#">"PRESAFE FUNCTIONS LIMITED, SEE OPERATORS MANUAL" DISPLAYED IN IC, FAULT CODE C10C700 "CONTROL UNIT A90 (COLLISION PREVENTION ASSIST CONTROLLER UNIT) IS DEFECTIVE" STORED IN CPA CONTROL UNIT</a>	<a href="#">2014-12-18</a>
<a href="#">TT 12/14</a>	<a href="#">"PRE-SAFE UNAVAILABLE" MESSAGE IN IC AND/OR CHECK ENGINE LIGHT ON; NORMALLY INTERMITTENT</a>	<a href="#">2014-12-18</a>
<a href="#">TT 12/14</a>	<a href="#">CUSTOMER STATES THAT VEHICLE FROM ANOTHER MANUFACTURER RECEIVES ADDITIONAL SIRIUSXM CHANNELS AS COMPARED TO THEIR MERCEDES-BENZ</a>	<a href="#">2014-12-18</a>
<a href="#">TT 12/14</a>	<a href="#">ERRATIC KEYLESS GO FUNCTION FOLLOWING REPLACEMENT OF KEYLESS GO KEYS</a>	<a href="#">2014-12-18</a>
<a href="#">TT 12/14</a>	<a href="#">LIFT GATE OCCASIONALLY DOES NOT OPEN/CLOSE COMPLAINT: SOMETIMES INTERMITTENT</a>	<a href="#">2014-12-18</a>
<a href="#">TT 12/11</a>	<a href="#">CHECK ADDITIVE MESSAGE IN IC "ADBLUE LEVEL TOO LOW" DTCS IN CDI 16CE00, 16CF00 AND/OR 16CC00 &amp; 16CD00</a>	<a href="#">2011-12-01</a>
<a href="#">TT 11/14</a>	<a href="#">166 TRANSFER CASE BREATHER</a>	<a href="#">2014-11-01</a>
<a href="#">TT 11/14</a>	<a href="#">CRANKSHAFT MAIN BEARING FAILURE FOLLOWING OIL COOLER SEAL REPLACEMENTS</a>	<a href="#">2014-11-01</a>

<a href="#">TT 11/14</a>	<a href="#">PHONE COMPLAINTS OF DROPPED CALLS / DIFFICULTY IN HEARING OR BEING UNDERSTOOD BY THE OTHER PARTY</a>	<a href="#">2014-11-01</a>
<a href="#">TT 11/14</a>	<a href="#">WHEN SELECTING VOICE CONTROL, RESPONSE IS IMMEDIATELY "CANCEL"</a>	<a href="#">2014-11-01</a>
<a href="#">TT 10/14</a>	<a href="#">AC BLOWER INOPERATIVE DTC 912F87 IN ACC "THE FRONT BLOWER REGULATOR HAS A MALFUNCTION, THE MESSAGE IS MISSING"</a>	<a href="#">2014-10-01</a>
<a href="#">TT 10/14</a>	<a href="#">GARAGE DOOR OPENER LED LIGHT ON BOTTOM OF INSIDE REARVIEW MIRROR PUSHED IN AND NO LONGER VISIBLE</a>	<a href="#">2014-10-01</a>
<a href="#">TT 10/14</a>	<a href="#">NOISE FROM BELT TENSIONER AREA</a>	<a href="#">2014-10-01</a>
<a href="#">TT 10/14</a>	<a href="#">PROPERLY IDENTIFYING TRANSFER CASE LEAKS</a>	<a href="#">2014-10-01</a>
<a href="#">TT 09/15</a>	<a href="#">CHIRPING NOISE THAT SOUNDS LIKE SLIPPING ENGINE BELT</a>	<a href="#">2015-09-15</a>
<a href="#">TT 09/15</a>	<a href="#">CORNERING LIGHT FUNCTION WITH SA CODE 615 OR 640</a>	<a href="#">2015-09-15</a>
<a href="#">TT 09/15</a>	<a href="#">WATER LEAK INTO VEHICLE FROM AREA OF HEADLINER NEAR SUNROOF</a>	<a href="#">2015-09-15</a>
<a href="#">TT 09/15</a>	<a href="#">WORK TO BE PERFORMED AFTER HIGH PRESSURE FUEL SYSTEM REPAIRS</a>	<a href="#">2015-09-15</a>
<a href="#">TT 09/14</a>	<a href="#">AFTERMARKET REMOTE START KITS</a>	<a href="#">2014-09-01</a>
<a href="#">TT 09/14</a>	<a href="#">SATELLITE RADIO DISPLAYS "UPDATING CHANNELS" INTERMITTENTLY</a>	<a href="#">2014-09-01</a>
<a href="#">TT 09/11</a>	<a href="#">722.9 TORQUE CONVERTER LOCKUP ISSUES AFTER CONDUCTOR PLATE (VGS) INSTALLATION. SHIFTING IS ROUGH</a>	<a href="#">2011-09-01</a>
<a href="#">TT 09/11</a>	<a href="#">CEL, CAMSHAFT ADJUSTMENT DTC P054C00 AND OTHER</a>	<a href="#">2011-09-01</a>
<a href="#">TT 09/11</a>	<a href="#">EHS NUMBER LOST DURING PROGRAMMING</a>	<a href="#">2011-09-01</a>
<a href="#">TT 09/11</a>	<a href="#">ON VEHICLES OVER 100000KM (62136MLS) IT IS POSSIBLE ON CERTAIN ECU (I.E, ETC) TO NOTE A DISCREPANCY BETWEEN FREEZE FRAME DATA AND ACTUAL VEHICLE ODOMETER</a>	<a href="#">2011-09-01</a>
<a href="#">TT 09/11</a>	<a href="#">REPLACING VALVE BODY SOLENOIDS</a>	<a href="#">2011-09-01</a>
<a href="#">TT 09/11</a>	<a href="#">TORQUE CONVERTER LOCK-UP CLUTCH - DIAGNOSIS AND ADAPTATION</a>	<a href="#">2011-09-01</a>
<a href="#">TT 08/15</a>	<a href="#">OIL FILTER HOUSING COVERS</a>	<a href="#">2015-08-18</a>
<a href="#">TT 08/14</a>	<a href="#">AIR CONDITIONING - INSUFFICIENT COOLING</a>	<a href="#">2014-08-01</a>
<a href="#">TT 08/14</a>	<a href="#">CAMSHAFT PULSE WHEEL LASER MARKS</a>	<a href="#">2014-08-01</a>
<a href="#">TT 08/14</a>	<a href="#">CHECK ENGINE LIGHT WITH CODE P001685 "THE POSITION OF THE INTAKE CAMSHAFT (CYLINDER BANK 1) IS IMPLAUSIBLE RELATIVE TO THE POSITION OF THE CRANKSHAFT"</a>	<a href="#">2014-08-01</a>
<a href="#">TT 08/14</a>	<a href="#">NOISES FROM THE AREA OF THE FRONT AXLE WHILE DRIVING</a>	<a href="#">2014-08-01</a>
<a href="#">TT 08/14</a>	<a href="#">OUTPUT SPEED SENSOR FAULT CODES ON 2014 AND LATER VEHICLES W/ LOW MILES</a>	<a href="#">2014-08-01</a>
<a href="#">TT 08/14</a>	<a href="#">REPAIRS RELATED TO DTC'S FOR PREAIR SENSORS</a>	<a href="#">2014-08-01</a>
<a href="#">TT 07/14</a>	<a href="#">COMPATIBILITY OF TRANSMISSION FLUIDS "GOLD," "RED," &amp; "BLUE"</a>	<a href="#">2014-07-01</a>

<a href="#"><u>TT 06/15</u></a>	<a href="#"><u>BECKER MAP PILOT VOICE CONTROL IS NOT UNDERSTOOD BY THE UNIT</u></a>	<a href="#"><u>2015-06-16</u></a>
<a href="#"><u>TT 06/15</u></a>	<a href="#"><u>DIAGNOSING COMPLAINTS OF BRAKE PULSATION</u></a>	<a href="#"><u>2015-06-16</u></a>
<a href="#"><u>TT 06/15</u></a>	<a href="#"><u>ENGINE DIAGNOSIS LAMP ILLUMINATED W/CODE U145400 - IMPLAUSIBLE DATA RECEIVED FROM ETHANOL SENSOR</u></a>	<a href="#"><u>2015-06-16</u></a>
<a href="#"><u>TT 06/14</u></a>	<a href="#"><u>CLARIFICATION OF LI83,30-P-059119</u></a>	<a href="#"><u>2014-06-01</u></a>
<a href="#"><u>TT 06/14</u></a>	<a href="#"><u>TORQUE CONVERTER SERVICE LIFE DATA</u></a>	<a href="#"><u>2014-06-01</u></a>
<a href="#"><u>TT 05/15</u></a>	<a href="#"><u>BLINDSPOT ASSIST UNAVAILABLE MESSAGE ON WITH NO FAULT CODES SET</u></a>	<a href="#"><u>2015-05-19</u></a>
<a href="#"><u>TT 05/15</u></a>	<a href="#"><u>TPM LIGHT ON, ONE PRESSURE VALUE SHOWING AS DASHES IN CLUSTER, CURRENT OR STORED SENSOR COMMUNICATION CODES</u></a>	<a href="#"><u>2015-05-19</u></a>
<a href="#"><u>TT 05/14</u></a>	<a href="#"><u>ALL NEW RED/PINK COOLANT VERSUS BLUE COOLANT</u></a>	<a href="#"><u>2014-05-01</u></a>
<a href="#"><u>TT 05/14</u></a>	<a href="#"><u>CLOTHING AND BAGGAGE THAT BLOCKS RADIO FREQUENCY SIGNALS</u></a>	<a href="#"><u>2014-05-01</u></a>
<a href="#"><u>TT 05/14</u></a>	<a href="#"><u>CORRECT SPARK PLUG INDEXING</u></a>	<a href="#"><u>2014-05-01</u></a>
<a href="#"><u>TT 05/14</u></a>	<a href="#"><u>ENGINES WITH CAMSHAFT POSITION CODES</u></a>	<a href="#"><u>2014-05-01</u></a>
<a href="#"><u>TT 05/14</u></a>	<a href="#"><u>ERRONEOUS WARNINGS IN DRIVER ASSISTANCE SYSTEMS</u></a>	<a href="#"><u>2014-05-01</u></a>
<a href="#"><u>TT 05/14</u></a>	<a href="#"><u>EXHAUST BACK PRESSURE SENSOR</u></a>	<a href="#"><u>2014-05-01</u></a>
<a href="#"><u>TT 05/14</u></a>	<a href="#"><u>FRONT SHOCK INSTALLATION (STEEL SPRING SUSPENSION)</u></a>	<a href="#"><u>2014-05-01</u></a>
<a href="#"><u>TT 05/14</u></a>	<a href="#"><u>REPAIRS MADE TO VALVE TRAIN: TIMING CHAIN, SPROCKETS, CAMSHAFT ADJUSTERS</u></a>	<a href="#"><u>2014-05-01</u></a>
<a href="#"><u>TT 05/12</u></a>	<a href="#"><u>HUMMING / DRONING / RATTLING / OR BUZZING NOISES DETERMINED TO BE COMING FROM THE EXHAUST SYSTEM</u></a>	<a href="#"><u>2012-05-01</u></a>
<a href="#"><u>TT 04/15</u></a>	<a href="#"><u>CDI ECU WILL NOT LEARN THE CMP SENSORS DUE TO TIMING CHAIN STRETCH</u></a>	<a href="#"><u>2015-04-01</u></a>
<a href="#"><u>TT 04/15</u></a>	<a href="#"><u>DELAYED UPSHIFT DURING DPF REGENERATION</u></a>	<a href="#"><u>2015-04-01</u></a>
<a href="#"><u>TT 04/15</u></a>	<a href="#"><u>PROPER APPLICATION OF DIFFERENT MATERIAL FUSES</u></a>	<a href="#"><u>2015-04-01</u></a>
<a href="#"><u>TT 03/14</u></a>	<a href="#"><u>INFORMATION GATHERING TO DIAGNOSE COMPLAINTS RELATED TO DRIVER ASSISTANCE SYSTEMS</u></a>	<a href="#"><u>2014-03-01</u></a>
<a href="#"><u>TT 03/14</u></a>	<a href="#"><u>INTERMITTENT BATTERY CURRENT DRAW THAT IS UNABLE TO BE DUPLICATED IN THE WORKSHOP</u></a>	<a href="#"><u>2014-03-01</u></a>
<a href="#"><u>TT 03/14</u></a>	<a href="#"><u>POWERTRAIN CAN WIRING GOING FROM TRANSMISSION ECU TO DRIVETRAIN CAN BUS BAR</u></a>	<a href="#"><u>2014-03-01</u></a>
<a href="#"><u>TT 03/14</u></a>	<a href="#"><u>SIGNS OF INCORRECT INSTALLATION OF HIGH PRESSURE FUEL PUMP</u></a>	<a href="#"><u>2014-03-01</u></a>
<a href="#"><u>TT 02/15</u></a>	<a href="#"><u>ADBLUE DELIVERY MODULES - BROKEN NIPPLES</u></a>	<a href="#"><u>2015-02-01</u></a>
<a href="#"><u>TT 02/15</u></a>	<a href="#"><u>INDEXING AND PROPER TORQUE OF SPARK PLUGS</u></a>	<a href="#"><u>2015-02-01</u></a>
<a href="#"><u>TT 02/15</u></a>	<a href="#"><u>REPLACEMENT ROD BEARINGS IN CONJUNCTION WITH REPLACEMENT OF RODS WITH PISTONS</u></a>	<a href="#"><u>2015-02-01</u></a>
<a href="#"><u>TT 02/14</u></a>	<a href="#"><u>INTERMITTENT DRIVE ASSYST SYSTEMS MALFUNCTIONS DISPLAYED IN IC AND/OR INTERMITTENTLY VEHICLE WILL NOT SHIFT FROM PARK</u></a>	<a href="#"><u>2014-02-01</u></a>
<a href="#"><u>TT 02/11</u></a>	<a href="#"><u>ENGINE HYDROLOCK REPAIRS / DIAGNOSIS</u></a>	<a href="#"><u>2011-02-01</u></a>

<a href="#">TT 01/15</a>	<a href="#">CEL POSSIBLY W/ RUN ABILITY COMPLAINTS</a>	<a href="#">2015-01-01</a>
<a href="#">TT 01/15</a>	<a href="#">M276 W/ CEL - DTC U145400 "IMPLAUSIBLE DATA FROM B4/31" - FLEX FUEL SENSOR</a>	<a href="#">2015-01-01</a>
<a href="#">TT 01/14</a>	<a href="#">ENGINE MISFIRES</a>	<a href="#">2014-01-01</a>
<a href="#">TT 01/14</a>	<a href="#">ENGINE OVERHEATING</a>	<a href="#">2014-01-01</a>
<a href="#">TT 01/14</a>	<a href="#">TAIL GATE MOTOR BURNS OUT DUE TO CONSTANT POWER SUPPLY WHEN AMBIENT LIGHTING SET TO 1 OR 2 AND IS "ACTIVE"</a>	<a href="#">2014-01-01</a>
<a href="#">TT 01/11</a>	<a href="#">REPLACEMENT OF VGS CONTROL UNIT (CONDUCTOR PLATE) VS. THE COMPLETE VALVE BODY</a>	<a href="#">2011-01-01</a>
<a href="#">TT 01/11</a>	<a href="#">TEST PINS FOR ME-SFI 9.7 , ME 17.7 AND CDI WIRE HARNESSES</a>	<a href="#">2011-01-01</a>
<a href="#">S-0473-08B</a>	<a href="#">FACTORY APPROVED SERVICE PRODUCTS</a>	<a href="#">2007-10-01</a>
<a href="#">LI98.00-P-058914</a>	<a href="#">CLEARCOAT PEELING/FLAKING/BUBBLING</a>	<a href="#">2016-05-10</a>
<a href="#">LI91.60-P-058226</a>	<a href="#">SUPPLEMENTAL RESTRAINT SYSTEM (SRS) LAMP IN INSTRUMENT CLUSTER LIGHTS UP; FAULT CODE B000213 AND/OR B000113 IS LOGGED IN THE SRS CONTROL UNIT</a>	<a href="#">2015-12-15</a>
<a href="#">LI91.40-P-060559</a>	<a href="#">FRONT SEAT BELT ROLLS UP TOO QUICKLY</a>	<a href="#">2015-01-12</a>
<a href="#">LI91.40-P-060104</a>	<a href="#">VEHICLES WITH REVERSIBLE SEAT BELT RETRACTOR (REVAS)/ACTIVE BELT BUCKLE (AGS)</a>	<a href="#">2014-10-31</a>
<a href="#">LI91.40-P-051830</a>	<a href="#">DRIVER AND/OR FRONT PASSENGER SEAT BELT CATCHES WHEN PULLED OUT</a>	<a href="#">2013-09-04</a>
<a href="#">LI91.29-P-053247</a>	<a href="#">ELECTRIC SEAT ADJUSTMENT, SEAT HEATER/SEAT VENTILATION OF FRONT SEAT, OR REAR MONITOR NONFUNCTIONAL</a>	<a href="#">2014-07-10</a>
<a href="#">LI91.18-P-053842</a>	<a href="#">DAMAGES TO SEAT COVERS</a>	<a href="#">2016-02-23</a>
<a href="#">LI91.18-P-053442</a>	<a href="#">CLEANING OF SOILED SEAT COVERS</a>	<a href="#">2016-04-14</a>
<a href="#">LI91.16-P-063435</a>	<a href="#">VIBRATION NOISE ON DRIVER HEAD RESTRAINT IN 1ST SEAT ROW</a>	<a href="#">2016-02-22</a>
<a href="#">LI91.12-P-063995</a>	<a href="#">BACKREST FLAP MECHANISM ON 2ND SEAT ROW NONFUNCTIONAL OR SLUGGISH</a>	<a href="#">2025-05-13</a>
<a href="#">LI91.12-P-063995</a>	<a href="#">BACKREST FLAP MECHANISM ON 2ND SEAT ROW NONFUNCTIONAL OR SLUGGISH</a>	<a href="#">2016-07-25</a>
<a href="#">LI91.12-P-055796</a>	<a href="#">SEAT CUSHION FRAME AND BACKREST FRAME OF REAR SEAT CORRODED</a>	<a href="#">2016-02-16</a>
<a href="#">LI91.10-P-063393</a>	<a href="#">SPLITTING OF SEAT COVERS</a>	<a href="#">2016-04-29</a>
<a href="#">LI91.10-P-063385</a>	<a href="#">NOISE IN DRIVER OR FRONT PASSENGER SEAT WHEN PRESSURE APPLIED TO BACKREST</a>	<a href="#">2016-02-22</a>
<a href="#">LI91.10-P-053601</a>	<a href="#">PLAY OR NOISES IN FRONT SEAT FRAME</a>	<a href="#">2015-06-22</a>
<a href="#">LI88.70-P-063310</a>	<a href="#">LEFT/RIGHT OUTSIDE MIRROR GLASS CANNOT BE ADJUSTED TO OUTER LIMIT STOP</a>	<a href="#">2016-02-18</a>
<a href="#">LI88.70-P-056690</a>	<a href="#">OUTSIDE MIRRORS FOGGED</a>	<a href="#">2014-08-22</a>
<a href="#">LI88.40-P-058355</a>	<a href="#">MESSAGE IN INSTRUMENT CLUSTER "DISTRONIC PLUS-CURRENTLY UNAVAILABLE - SEE OWNER'S MANUAL"</a>	<a href="#">2016-03-23</a>
<a href="#">LI88.00-P-063728</a>	<a href="#">LICENSE PLATE ADAPTER MOUNTING SCREWS</a>	<a href="#">2016-04-01</a>

<a href="#"><u>LI83.30-P-064672</u></a>	<a href="#"><u>ENGINE FAN RUNS CONTINUOUSLY, A/C OPERATION NONFUNCTIONAL OR ENGINE INDICATOR LAMP LIGHTS UP SPORADICALLY</u></a>	<a href="#"><u>2016-08-19</u></a>
<a href="#"><u>LI83.30-P-060551</u></a>	<a href="#"><u>FUNCTION COMPLAINTS/IMPLAUSIBLE CONTROL OF AIR CONDITIONING</u></a>	<a href="#"><u>2015-09-10</u></a>
<a href="#"><u>LI83.30-P-059119</u></a>	<a href="#"><u>ODOR FROM THE AIR CONDITIONING</u></a>	<a href="#"><u>2016-06-23</u></a>
<a href="#"><u>LI83.30-P-054343</u></a>	<a href="#"><u>AIR CONDITIONING INOPERATIVE, FAULT CODE 91E815 LOGGED, AAC CONTROL UNIT FUSE DEFECTIVE, INTERMITTENTLY FAILS TO COOL, SWITCHES OFF AFTER BRIEF PERIOD, A/C OPERATING UNIT INOPERATIVE</u></a>	<a href="#"><u>2016-03-24</u></a>
<a href="#"><u>LI83.30-P-054342</u></a>	<a href="#"><u>AIR CONDITIONING IS INOPERATIVE, FAULT CODE 91EB11 OR 91EB15 IS STORED IN THE FAULT MEMORY, AIR CONDITIONING DOES NOT COOL OR SWITCHES OFF AUTOMATICALLY AFTER A SHORT TIME</u></a>	<a href="#"><u>2016-02-19</u></a>
<a href="#"><u>LI83.10-P-063859</u></a>	<a href="#"><u>HVAC BLOWER MOTOR INOPERATIVE AND DTC 912F87</u></a>	<a href="#"><u>2016-08-08</u></a>
<a href="#"><u>LI83.10-P-057727</u></a>	<a href="#"><u>VENT GRILLES OF VENTILATION OUTLET AT REAR BROKEN/LOOSE</u></a>	<a href="#"><u>2013-11-05</u></a>
<a href="#"><u>LI83.00-P-055425</u></a>	<a href="#"><u>FLAPPING/RATTLING NOISE IN AREA OF CENTER TUNNEL</u></a>	<a href="#"><u>2015-05-01</u></a>
<a href="#"><u>LI83.00-P-052510</u></a>	<a href="#"><u>MALFUNCTIONS OF VARIOUS CONTROL UNITS AND/OR ON-BOARD POWER SUPPLY PROBLEMS CAUSED BY WATER IN THE CONTROL UNIT TRAY UNDER THE DRIVER/FRONT PASSENGER SEAT (DISLOCATED, PINCHED OR LEAKING CONDENSATION HOSE)</u></a>	<a href="#"><u>2014-02-20</u></a>
<a href="#"><u>LI82.95-P-064353</u></a>	<a href="#"><u>AUTOMATIC EMERGENCY CALL TRIGGERED FOR NO OBVIOUS REASON</u></a>	<a href="#"><u>2016-06-22</u></a>
<a href="#"><u>LI82.95-P-060072</u></a>	<a href="#"><u>MBRACE I-CALL MAY NOT COMPLETE</u></a>	<a href="#"><u>2014-10-22</u></a>
<a href="#"><u>LI82.95-P-059571</u></a>	<a href="#"><u>TROUBLESHOOTING MERCEDES-BENZ MBRACE ISSUES PRIOR TO REPLACEMENT</u></a>	<a href="#"><u>2014-07-31</u></a>
<a href="#"><u>LI82.95-P-059559</u></a>	<a href="#"><u>"SOS MBRACE SERVICE NOT ACTIVATED" DISPLAYED PERSISTENTLY IN INSTRUMENT CLUSTER</u></a>	<a href="#"><u>2016-02-18</u></a>
<a href="#"><u>LI82.95-P-056655</u></a>	<a href="#"><u>BATTERY DRAIN BUS KEEPAWAKE DETECTED - MBRACE CONTROL UNIT CAUSES BUS KEEPAWAKE</u></a>	<a href="#"><u>2015-09-09</u></a>
<a href="#"><u>LI82.95-P-056646</u></a>	<a href="#"><u>TROUBLESHOOTING MBRACE ISSUES PRIOR TO REPLACEMENT</u></a>	<a href="#"><u>2013-09-06</u></a>
<a href="#"><u>LI82.95-P-054406</u></a>	<a href="#"><u>"SOS MBRACE SERVICE NOT ACTIVATED" DISPLAYED PERSISTENTLY IN INSTRUMENT CLUSTER</u></a>	<a href="#"><u>2013-10-11</u></a>
<a href="#"><u>LI82.85-P-065461</u></a>	<a href="#"><u>GARMIN MAP PILOT: TEST SD CARDS W 000 589 03 22 00 AND W 000 589 04 22 00 CANNOT BE USED</u></a>	<a href="#"><u>2016-12-19</u></a>
<a href="#"><u>LI82.85-P-065110</u></a>	<a href="#"><u>GARMIN MAP PILOT: AFTER A NAVIGATION SOFTWARE UPDATE, THE USER IS INSTRUCTED TO CONNECT THE SD CARD WITH THE VEHICLE</u></a>	<a href="#"><u>2016-10-25</u></a>
<a href="#"><u>LI82.85-P-064765</u></a>	<a href="#"><u>GARMIN MAP PILOT: TRAFFIC INFORMATION SERVICE AND POSSIBLY VOICE CONTROL INOPERATIVE AFTER NAVIGATION SOFTWARE UPDATE USING DOWNLOAD MANAGER VERSION 2.0.29 OR 2.0.30</u></a>	<a href="#"><u>2016-09-22</u></a>
<a href="#"><u>LI82.85-P-064311</u></a>	<a href="#"><u>GARMIN MAP PILOT: GENERAL INFORMATION IN THE EVENT OF COMPLAINTS</u></a>	<a href="#"><u>2016-06-17</u></a>

<a href="#">LI82.85-P-064225</a>	<a href="#">GARMIN MAP PILOT: NOTES ON VOICE INPUT</a>	<a href="#">2016-06-13</a>
<a href="#">LI82.85-P-063619</a>	<a href="#">COMAND ONLINE: LIVE TRAFFIC/FREE BROWSING INOPERATIVE, INCORRECT DATE IN SYSTEM SETTINGS</a>	<a href="#">2016-10-06</a>
<a href="#">LI82.85-P-063235</a>	<a href="#">GARMIN MAP PILOT: MESSAGE "UPDATE CARD NOT SUPPORTED" AFTER UPDATE USING DOWNLOAD MANAGER</a>	<a href="#">2016-02-01</a>
<a href="#">LI82.85-P-063158</a>	<a href="#">GARMIN MAP PILOT - DOWNLOAD MANAGER: SOFTWARE UPDATE CANNOT BE ACTIVATED</a>	<a href="#">2016-01-20</a>
<a href="#">LI82.85-P-063081</a>	<a href="#">DEACTIVATION OF SELECTED MB APPS</a>	<a href="#">2016-02-02</a>
<a href="#">LI82.85-P-062889</a>	<a href="#">AUDIO/COMAND DISPLAY: WARNING MESSAGE WITH ACTIVE REVERSING CAMERA/360 CAMERA IS OVERLAID</a>	<a href="#">2016-02-02</a>
<a href="#">LI82.85-P-061613</a>	<a href="#">FACEBOOK APP CANNOT BE OPENED</a>	<a href="#">2015-06-26</a>
<a href="#">LI82.85-P-060002</a>	<a href="#">DRIVE KIT PLUS: DIGITAL DRIVESTYLE APP DOES NOT LAUNCH AUTOMATICALLY WITH IOS8.0.X</a>	<a href="#">2014-11-10</a>
<a href="#">LI82.85-P-059437</a>	<a href="#">COMAND/AUDIO50/AUDIO20: THE PIN FOR THE THEFT PROTECTION FUNCTION CANNOT BE GENERATED IN VEDOC</a>	<a href="#">2014-08-26</a>
<a href="#">LI82.85-P-059083</a>	<a href="#">AUDIO/COMAND DISPLAY: SPORADIC FAILURES OF CENTRAL DISPLAY</a>	<a href="#">2015-09-02</a>
<a href="#">LI82.85-P-058928</a>	<a href="#">COMAND ONLINE: "SIRIUS" SATELLITE RADIO "SIRIUS" CONSTANTLY DISPLAYS THE MESSAGE "UPDATING CHANNELS"</a>	<a href="#">2015-05-18</a>
<a href="#">LI82.85-P-058859</a>	<a href="#">DRIVE KIT PLUS: CAR-TO-X FUNCTION ISSUES</a>	<a href="#">2014-04-09</a>
<a href="#">LI82.85-P-058582</a>	<a href="#">COMAND ONLINE: APPLE PRODUCTS (IPHONE OR IPOD) ARE NOT CHARGED VIA THE SERIAL USB INTERFACE OF THE COMAND ONLINE</a>	<a href="#">2014-10-15</a>
<a href="#">LI82.85-P-058185</a>	<a href="#">COMAND ONLINE/AUDIO 20: THE CENTRAL DISPLAY INTERMITTENTLY DISPLAYS THE MESSAGE "ANTI-THEFT PROTECTION ACTIVATED"</a>	<a href="#">2016-08-16</a>
<a href="#">LI82.85-P-057407</a>	<a href="#">NTG4.5: THE FUEL CONSUMPTION INDICATOR IN THE SYSTEM MENU IS INCORRECTLY SCALED OR NOT PRESENT</a>	<a href="#">2013-11-04</a>
<a href="#">LI82.85-P-057192</a>	<a href="#">COMAND ONLINE: INTERMITTENTLY NO AUDIO OUTPUT AFTER ENGINE START</a>	<a href="#">2013-09-09</a>
<a href="#">LI82.85-P-057191</a>	<a href="#">COMAND ONLINE: MUTE FUNCTION NO LONGER ACTIVE AFTER A RESTART</a>	<a href="#">2015-09-18</a>
<a href="#">LI82.85-P-057169</a>	<a href="#">DRIVE KIT PLUS: DISPLAY FLICKERS OR TURNS GREEN, RED OR BLACK; DIGITAL DRIVESTYLE APP PERFORMS A RESET</a>	<a href="#">2014-08-14</a>
<a href="#">LI82.85-P-055695</a>	<a href="#">COMAND: DOES NOT START, CANNOT BE OPERATED, COMAND DISPLAY REMAINS DARK</a>	<a href="#">2013-08-28</a>
<a href="#">LI82.85-P-048667</a>	<a href="#">SPLITVIEW FEATURE NOT ACTIVATED IN COMAND/COMAND ONLINE</a>	<a href="#">2014-02-12</a>
<a href="#">LI82.70-P-062003</a>	<a href="#">IPHONE 4S/5/5C/5S AND 6/6 PLUS MOBILE PHONE: ADDRESS BOOK NOT TRANSFERRED</a>	<a href="#">2015-10-08</a>
<a href="#">LI82.70-P-060004</a>	<a href="#">IPHONE MOBILE PHONE: VARIOUS COMPLAINTS AFTER SOFTWARE UPDATE TO IOS8</a>	<a href="#">2014-10-15</a>
<a href="#">LI82.70-P-056963</a>	<a href="#">COMAND ONLINE: THE MOBILE PHONE CONNECTION THROUGH BLUETOOTH IS TEMPORARILY NOT POSSIBLE</a>	<a href="#">2016-02-22</a>
<a href="#">LI82.70-P-055572</a>	<a href="#">MOBILE PHONES IN GENERAL: ADDRESS BOOK ENTRIES</a>	<a href="#">2013-08-28</a>



<u>(CONTACTS) ARE NOT TRANSFERRED COMPLETELY</u>		
<u>LI82.70-P-054227</u>	<u>MOBILE PHONE IN GENERAL: THE CALLED PARTY IS SOMETIMES DIFFICULT TO UNDERSTAND IN THE VEHICLE. INTERFERENCE NOISE INTERMITTENTLY AUDIBLE IN THE VEHICLE</u>	<u>2015-08-19</u>
<u>LI82.62-P-059885</u>	<u>INTERFERENCE NOISES AT SPEAKERS</u>	<u>2014-09-25</u>
<u>LI82.62-P-058583</u>	<u>SOUND SYSTEM: INTERMITTENT LOSS OF SOUND AFTER ENGINE START</u>	<u>2014-07-15</u>
<u>LI82.62-P-056934</u>	<u>INTERFERENCE NOISES FROM BASS BOX (RATTLING) AT LEFT REAR</u>	<u>2013-09-05</u>
<u>LI82.61-P-063753</u>	<u>BECKER MAP PILOT GEN 3: MESSAGE "THE INTERNAL BATTERY IS MISSING OR FAULTY" APPEARS IN THE DISPLAY</u>	<u>2016-07-22</u>
<u>LI82.61-P-061420</u>	<u>BECKER MAP PILOT GEN 3: MESSAGE "NO NAVIGATION MODULE CONNECTED" APPEARS IN THE DISPLAY</u>	<u>2016-04-22</u>
<u>LI82.61-P-061310</u>	<u>BECKER MAP PILOT: NAVIGATION DISPLAY FREEZES BRIEFLY IN THE CASE OF PHYSICAL SHOCKS</u>	<u>2015-04-20</u>
<u>LI82.61-P-058186</u>	<u>BECKER MAP PILOT: CANNOT BE OPERATED, NAVIGATION DISPLAY FREEZES</u>	<u>2013-12-23</u>
<u>LI82.61-P-055954</u>	<u>BECKER MAP PILOT GEN 1.0 TO 2.5 (2.6 IN CHINA): MESSAGE "NO NAVIGATION MODULE CONNECTED" APPEARS IN THE DISPLAY</u>	<u>2016-01-12</u>
<u>LI82.61-P-055130</u>	<u>BECKER MAP PILOT GEN 1.0 TO 2.5 (2.6 IN CHINA): MESSAGE "THE INTERNAL BATTERY IS MISSING OR FAULTY" APPEARS IN THE DISPLAY</u>	<u>2016-08-09</u>
<u>LI82.60-P-064168</u>	<u>AUDIO 20: MUSIC DOES NOT CONTINUE AUTOMATICALLY AFTER A CALL</u>	<u>2016-05-27</u>
<u>LI82.60-P-057275</u>	<u>MEDIA INTERFACE: OPERATION/MUSIC PLAYBACK NOT POSSIBLE</u>	<u>2013-11-18</u>
<u>LI82.30-P-059239</u>	<u>COMPLAINTS ABOUT WIPING EFFECT OF WINDSHIELD WIPER</u>	<u>2016-03-01</u>
<u>LI82.10-P-064405</u>	<u>RUNNING BOARD ILLUMINATION INOPERATIVE</u>	<u>2016-07-01</u>
<u>LI82.10-P-062056</u>	<u>HEADLAMPS FOGGED</u>	<u>2022-05-13</u>
<u>LI82.10-P-058239</u>	<u>XENTRY WILL NOT ACCEPT HEADLAMP CODING STRING</u>	<u>2014-02-25</u>
<u>LI82.10-P-051769</u>	<u>LAMP UNIT FOGGED/DROPLETS FORMING</u>	<u>2014-01-24</u>
<u>LI82.10-P-050139</u>	<u>HEADLAMPS/FRONT FOG LAMPS LEAKING OR FOGGED</u>	<u>2013-11-19</u>
<u>LI80.61-P-061174</u>	<u>VEHICLE CANNOT BE OPENED VIA KEYLESS-GO AND RADIO REMOTE CONTROL</u>	<u>2015-05-14</u>
<u>LI80.61-P-060558</u>	<u>OPENING VIA RADIO REMOTE CONTROL OR KEYLESS-GO AND/OR KEYLESS START INTERMITTENTLY INOPERATIVE</u>	<u>2016-09-13</u>
<u>LI80.50-P-053813</u>	<u>ATA, RANDOM ALARM TRIGGERING</u>	<u>2014-12-10</u>
<u>LI80.45-P-064913</u>	<u>CONVENIENCE FEATURE OF POWER WINDOWS AND SLIDING ROOF OR VARIO ROOF/SOFT TOP INOPERATIVE</u>	<u>2016-09-20</u>
<u>LI80.35-P-063677</u>	<u>BATTERY IN TRANSMITTER KEY DISCHARGES WITHIN A SHORT TIME AND/OR VEHICLE CANNOT BE STARTED; ONLY VEHICLES WITH CODE 889, 893, P17 AS OF DAS4</u>	<u>2016-04-27</u>
<u>LI77.20-P-063070</u>	<u>WATER ENTRY AT SLIDING ROOF IN HEAVY RAIN</u>	<u>2016-03-02</u>
<u>LI77.00-P-063165</u>	<u>WATER INGRESS AT A-PILLAR</u>	<u>2016-01-20</u>

<a href="#">LI72.20-P-059553</a>	<a href="#">MALFUNCTION OF LIFTGATE CONTROL (HKS)</a>	<a href="#">2014-08-04</a>
<a href="#">LI72.20-P-055301</a>	<a href="#">AUTOMATIC LIFTGATE OCCASIONALLY FAILS TO OPEN</a>	<a href="#">2013-12-20</a>
<a href="#">LI72.00-P-063146</a>	<a href="#">DOOR ENTRY EDGE PROTECTION LOOSE</a>	<a href="#">2016-01-21</a>
<a href="#">LI72.00-P-058635</a>	<a href="#">CRACKING NOISES AT DOORS IN AREA OF WINDOW FRAME</a>	<a href="#">2015-09-23</a>
<a href="#">LI72.00-P-058237</a>	<a href="#">CREAKING, TICKING NOISE FROM DOOR AREA</a>	<a href="#">2014-01-16</a>
<a href="#">LI68.30-P-058750</a>	<a href="#">REPLACE BELT HOLDER/BELT RETAINING TAB ON TRUNK SIDE PANEL, MODEL SERIES 166</a>	<a href="#">2014-03-25</a>
<a href="#">LI68.20-P-063996</a>	<a href="#">MODEL SERIES 166 CHAFE MARK ON WIRING HARNESS - BRACKET IN CENTER CONSOLE IS SHARP-EDGED</a>	<a href="#">2016-05-02</a>
<a href="#">LI68.20-P-057931</a>	<a href="#">NOISES AT CENTER CONSOLE ON MODEL SERIES 166 WITH THERMO CUP HOLDER (CODE 311)</a>	<a href="#">2013-12-20</a>
<a href="#">LI68.10-P-058925</a>	<a href="#">MODEL SERIES 166 DESIGNO LEATHER INSTRUMENT PANEL</a>	<a href="#">2014-04-21</a>
<a href="#">LI68.05-P-059193</a>	<a href="#">SENTEX GATE OPERATOR WITH CLIK CARD REMOTE NOT COMPATIBLE WITH HOMELINK</a>	<a href="#">2014-06-20</a>
<a href="#">LI67.30-P-059214</a>	<a href="#">SQUEAKING NOISES FROM TOP OF B-PILLAR WHEN RAISING AND LOWERING FRONT DOOR SIDE WINDOW</a>	<a href="#">2014-06-16</a>
<a href="#">LI67.30-P-052837</a>	<a href="#">SIDE WINDOWS MAY MAKE NOISES WHEN CLOSING AND OPENING, OR REVERSE DIRECTION WHEN CLOSING</a>	<a href="#">2015-06-26</a>
<a href="#">LI54.71-P-056477</a>	<a href="#">BLIND SPOT ASSIST INOPERATIVE</a>	<a href="#">2015-07-02</a>
<a href="#">LI54.65-P-065038</a>	<a href="#">PARKTRONIC SYSTEM HAS A MALFUNCTION</a>	<a href="#">2016-10-15</a>
<a href="#">LI54.65-P-059114</a>	<a href="#">NIGHT PERFORMANCE OF 360 CAMERA DARK</a>	<a href="#">2014-12-09</a>
<a href="#">LI54.65-P-057403</a>	<a href="#">PARKTRONIC TRIGGERS WITHOUT OBVIOUS CAUSE DUE TO LICENSE PLATE WIDTH</a>	<a href="#">2013-10-29</a>
<a href="#">LI54.65-P-057398</a>	<a href="#">NOISE WHEN REVERSING CAMERA IS ACTIVATED/DEACTIVATED</a>	<a href="#">2013-10-22</a>
<a href="#">LI54.65-P-057140</a>	<a href="#">PARKTRONIC SYSTEM AND/OR BLIND SPOT ASSIST NONFUNCTIONAL</a>	<a href="#">2013-09-03</a>
<a href="#">LI54.50-P-053950</a>	<a href="#">TRIP COMPUTER "AFTER RESET" DISPLAYS DASHES OR IMPLAUSIBLE VALUES FOR AVERAGE CONSUMPTION</a>	<a href="#">2015-11-11</a>
<a href="#">LI54.30-P-064548</a>	<a href="#">INSTRUMENT CLUSTER: ALWAYS BOOTS IN MAIN MENU (TRIP/TOTAL MILEAGE) / LAST MODE INOPERATIVE</a>	<a href="#">2016-07-26</a>
<a href="#">LI54.30-P-063675</a>	<a href="#">INSTRUMENT CLUSTER: NO DISPLAY IN INSTRUMENT CLUSTER</a>	<a href="#">2016-08-29</a>
<a href="#">LI54.30-P-060206</a>	<a href="#">INSTRUMENT CLUSTER DISPLAYS MESSAGE "ATTENTION ASSIST INOPERATIVE"</a>	<a href="#">2014-11-12</a>
<a href="#">LI54.30-P-058923</a>	<a href="#">SEGMENTS IN SPEEDOMETER NO LONGER DISPLAYED WHEN DISTRONIC PLUS IS ACTIVE</a>	<a href="#">2014-04-21</a>
<a href="#">LI54.25-P-056472</a>	<a href="#">KEY IN ELECTRONIC IGNITION SWITCH (EVS) IS NOT RECOGNIZED, AUTOMATIC TRANSMISSION SHIFTS TO PARK BEFORE VEHICLE COMES TO A STOP</a>	<a href="#">2015-03-10</a>
<a href="#">LI54.21-P-065146</a>	<a href="#">ENGINE INDICATOR LAMP LIGHTS UP AND/OR PRESAFE, BLIND SPOT ASSIST AND DISTRONIC ERROR MESSAGES IN INSTRUMENT CLUSTER</a>	<a href="#">2016-11-01</a>
<a href="#">LI54.21-P-057930</a>	<a href="#">REAR SEAT HEATING CANNOT BE ACTIVATED</a>	<a href="#">2015-01-21</a>
<a href="#">LI54.18-P-061568</a>	<a href="#">INTERMITTENTLY REDUCED POWER, FAULTS INCLUDING</a>	<a href="#">2016-03-22</a>



**SOME REFERRING TO EXHAUST BACK PRESSURE SENSOR LOGGED**

<a href="#"><u>LI54.18-P-058937</u></a>	<a href="#"><u>GROUND POINTS WITH PAINT-STRIPPING NUT</u></a>	<a href="#"><u>2014-04-21</u></a>
<a href="#"><u>LI54.18-P-058597</u></a>	<a href="#"><u>CHECK ENGINE LIGHT (CEL) ON, DTC FAULT CODE(S) CONCERNING THROTTLE VALVE ACTUATOR</u></a>	<a href="#"><u>2015-04-20</u></a>
<a href="#"><u>LI54.18-P-057840</u></a>	<a href="#"><u>CORROSION AT ELECTRICAL CONNECTING POINT BETWEEN FRONT BUMPER AND INTERIOR (X174/1) USA</u></a>	<a href="#"><u>2013-12-04</u></a>
<a href="#"><u>LI54.18-P-056220</u></a>	<a href="#"><u>CORROSION AT ELECTRICAL CONNECTING POINT BETWEEN FRONT BUMPER AND INTERIOR (X174/1) BR166 UP TO END NUMBER 260394</u></a>	<a href="#"><u>2016-04-06</u></a>
<a href="#"><u>LI54.15-P-057929</u></a>	<a href="#"><u>LIFTGATE CANNOT BE OPENED</u></a>	<a href="#"><u>2014-09-29</u></a>
<a href="#"><u>LI54.15-P-057754</u></a>	<a href="#"><u>COVER OF REVERSING CAMERA IS NOT ACTUATED</u></a>	<a href="#"><u>2015-03-02</u></a>
<a href="#"><u>LI54.10-P-058943</u></a>	<a href="#"><u>FAULT MESSAGE IN INSTRUMENT CLUSTER "ADDITIONAL BATTERY - SERVICE REQUIRED" - FC B11C11B</u></a>	<a href="#"><u>2015-12-14</u></a>
<a href="#"><u>LI49.20-P-062882</u></a>	<a href="#"><u>ADBLUE FAULT MESSAGE</u></a>	<a href="#"><u>2016-03-08</u></a>
<a href="#"><u>LI49.20-P-062140</u></a>	<a href="#"><u>ADBLUE METERING VALVE</u></a>	<a href="#"><u>2015-09-01</u></a>
<a href="#"><u>LI49.20-P-057632</u></a>	<a href="#"><u>SOOT TRACES ON TAILPIPE OR DIESEL PARTICULATE FILTER FAULT IN ENGINE CONTROL UNIT</u></a>	<a href="#"><u>2015-12-16</u></a>
<a href="#"><u>LI49.20-P-057101</u></a>	<a href="#"><u>FAULT CODE 20B91B, 20B913 (THE OUTPUT FOR THE HEATING ELEMENT OF THE ADBLUE PRESSURE LINE HAS AN ELECTRICAL FAULT OR AN OPEN CIRCUIT) IS STORED IN THE SCR CONTROL UNIT</u></a>	<a href="#"><u>2014-04-17</u></a>
<a href="#"><u>LI49.20-P-056353</u></a>	<a href="#"><u>HEATING ELEMENT OF ADBLUE TANK HAS MALFUNCTION, FAULT CODE 20BE1B AND/OR 20BD1B LOGGED IN BLUETEC CONTROL UNIT</u></a>	<a href="#"><u>2015-06-01</u></a>
<a href="#"><u>LI49.20-P-053539</u></a>	<a href="#"><u>ENGINE DIAGNOSIS WARNING LAMP LIGHTS UP - "CHECK ADBLUE" OR "NO START IN XXX KM/MILES" APPEARS IN INSTRUMENT CLUSTER - FAULT CODES CONCERNING ADBLUE SYSTEM STORED IN ENGINE CONTROL UNIT</u></a>	<a href="#"><u>2016-02-29</u></a>
<a href="#"><u>LI47.40-P-053871</u></a>	<a href="#"><u>FAULT CODE P045600 OR P044200 WITHOUT COMPLAINTS ABOUT ENGINE RUNNING CHARACTERISTICS</u></a>	<a href="#"><u>2016-04-08</u></a>
<a href="#"><u>LI47.30-P-060423</u></a>	<a href="#"><u>CHECK ENGINE LIGHT IS ILLUMINATED DUE TO ME CONTROL UNIT DTC P045100</u></a>	<a href="#"><u>2015-04-30</u></a>
<a href="#"><u>LI47.20-P-054958</u></a>	<a href="#"><u>COMBINATION MESSAGE: "CLEAN FUEL FILTER" AS WELL AS FAULT CODE (FC) 162500, P226997 OR 171600 STORED IN ENGINE CONTROL UNIT</u></a>	<a href="#"><u>2016-02-29</u></a>
<a href="#"><u>LI47.10-P-046862</u></a>	<a href="#"><u>PROCEDURE FOR WHEN DIESEL FUEL TANK IS FILLED WITH INCORRECT FUEL TYPE</u></a>	<a href="#"><u>2016-04-04</u></a>
<a href="#"><u>LI47.00-P-063719</u></a>	<a href="#"><u>ALS DIESEL FUEL TEST INFORMATION</u></a>	<a href="#"><u>2016-04-08</u></a>
<a href="#"><u>LI47.00-P-058235</u></a>	<a href="#"><u>FILLING STATION NOZZLE TURNS OFF PREMATURELY WHEN REFUELING</u></a>	<a href="#"><u>2016-04-26</u></a>
<a href="#"><u>LI46.35-P-062292</u></a>	<a href="#"><u>VEHICLE WANDERS TO THE LEFT OR RIGHT</u></a>	<a href="#"><u>2016-08-02</u></a>
<a href="#"><u>LI46.15-P-063353</u></a>	<a href="#"><u>HEIGHT ADJUSTMENT OF ELECTRIC STEERING COLUMN ADJUSTMENT INOPERATIVE</u></a>	<a href="#"><u>2016-02-23</u></a>
<a href="#"><u>LI46.15-P-058505</u></a>	<a href="#"><u>CREAKING NOISE WHEN ADJUSTING ELECTRICAL STEERING COLUMN</u></a>	<a href="#"><u>2014-06-30</u></a>

<a href="#">LI46.10-P-057961</a>	<a href="#">REPLACE STEERING WHEEL TRIM</a>	<a href="#">2015-09-02</a>
<a href="#">LI46.10-P-054699</a>	<a href="#">NOISE WHEN BRAKING OR MOVING OFF, WHEN THE SUSPENSION COMPRESSES AND REBOUNDS AT THE FRONT AXLE</a>	<a href="#">2015-07-23</a>
<a href="#">LI42.20-P-061327</a>	<a href="#">ELECTRIC PARKING BRAKE INOPERATIVE</a>	<a href="#">2015-04-22</a>
<a href="#">LI42.10-P-061801</a>	<a href="#">VIBRATION OR NOISE WHEN BRAKING</a>	<a href="#">2016-08-17</a>
<a href="#">LI42.10-P-058839</a>	<a href="#">SQUEAKING NOISES FROM AREA OF FRONT AXLE BRAKE</a>	<a href="#">2016-05-16</a>
<a href="#">LI42.10-P-058641</a>	<a href="#">MODEL SERIES 166 - UNEVEN WEAR ON BRAKE LININGS OF REAR AXLE</a>	<a href="#">2014-03-14</a>
<a href="#">LI33.30-P-056665</a>	<a href="#">THROTTLE LIFT-OFF CLUNKING NOISES AT DRIVE SHAFTS OF FRONT AXLE</a>	<a href="#">2016-09-06</a>
<a href="#">LI33.30-P-055908</a>	<a href="#">SQUEAKING NOISE EMANATING FROM AREA OF FRONT AXLE AT FULL STEERING LOCK</a>	<a href="#">2015-11-09</a>
<a href="#">LI33.20-P-054920</a>	<a href="#">CREAKING/CRACKLING NOISES FROM AREA OF FRONT AXLE WHEEL BEARING</a>	<a href="#">2015-09-01</a>
<a href="#">LI32.34-P-064466</a>	<a href="#">JERKY MOVEMENTS OF BODY</a>	<a href="#">2016-07-14</a>
<a href="#">LI32.34-P-058736</a>	<a href="#">ACTIVE CURVE SYSTEM MALFUNCTION IN INSTRUMENT CLUSTER</a>	<a href="#">2014-03-21</a>
<a href="#">LI32.34-P-058735</a>	<a href="#">RUMBLING NOISES FROM AREA OF FRONT AXLE</a>	<a href="#">2014-03-20</a>
<a href="#">LI32.22-P-058735</a>	<a href="#">RUMBLING NOISES FROM THE AREA OF THE FRONT AXLE</a>	<a href="#">2016-06-20</a>
<a href="#">LI31.19-P-047216</a>	<a href="#">INSTALLING ELECTRIC TRAILER BRAKE CONTROLLER</a>	<a href="#">2016-05-19</a>
<a href="#">LI30.30-P-062554</a>	<a href="#">COLLISION PREVENTION ASSIST HAS A MALFUNCTION</a>	<a href="#">2015-11-06</a>
<a href="#">LI28.00-P-063340</a>	<a href="#">WHINING NOISE IN REVERSE</a>	<a href="#">2016-08-19</a>
<a href="#">LI28.00-P-060078</a>	<a href="#">HUMMING/HOWLING/DRONING NOISE FROM DRIVETRAIN</a>	<a href="#">2014-10-24</a>
<a href="#">LI28.00-P-051499</a>	<a href="#">VIBRATIONS WHEN CORNERING AND SHUDDERING DURING CIRCULAR-COURSE DRIVING - 4MATIC</a>	<a href="#">2015-08-07</a>
<a href="#">LI27.60-P-060724</a>	<a href="#">GEAR RANGE D OR R CANNOT BE ENGAGED. FAULT CODE B226600 LOGGED IN SHIFT MODULE (A80)</a>	<a href="#">2015-05-18</a>
<a href="#">LI27.55-P-060088</a>	<a href="#">PROCEDURE IN CASE OF SLIGHT OIL TRACES ON TRANSMISSION 722.9</a>	<a href="#">2015-09-10</a>
<a href="#">LI27.55-P-058976</a>	<a href="#">PROCEDURE IN CASE OF SLIGHT OIL TRACES ON TRANSMISSION 722.9</a>	<a href="#">2014-08-14</a>
<a href="#">LI27.50-P-056467</a>	<a href="#">SHIFT QUALITY COMPLAINTS AND/OR AUTOMATIC TRANSMISSION IN LIMP-HOME MODE IN COMBINATION WITH FAULT CODES P060600, P072000, P072200, P072300, P072364, P072900, P073000 P073100, P073200, P073300, P073400, P073500, P076F00</a>	<a href="#">2015-07-13</a>
<a href="#">LI27.50-P-049710</a>	<a href="#">AUTOMATIC TRANSMISSION LIMP-HOME MODE, FAULT CODES 0717, 0718, 0722, 0723, 2200, 2201, 2204, 2205, 2206, 2207, 2767, 2768, P071700, P071800, P072200, P072300, P276700, P276800</a>	<a href="#">2016-02-23</a>
<a href="#">LI27.50-P-049281</a>	<a href="#">HARSH ENGAGEMENT WHEN CHANGING GEAR RANGE FROM P TO D</a>	<a href="#">2016-10-10</a>
<a href="#">LI27.20-P-061496</a>	<a href="#">TORQUE CONVERTER DRAIN PLUG NOT ALIGNED WITH DRAIN PLUG ACCESS IN BELL HOUSING</a>	<a href="#">2015-05-21</a>
	<a href="#">JOLTING DURING VEHICLE OPERATION AND/OR VEHICLE</a>	

<a href="#">LI27.20-P-057339</a>	<a href="#">DOES NOT ACCELERATE ADEQUATELY; NO RELEVANT FAULT CODES PRESENT</a>	<a href="#">2013-11-19</a>
<a href="#">LI27.20-P-055758</a>	<a href="#">FRICTION POWER OF TORQUE CONVERTER LOCKUP CLUTCH IS TOO HIGH (FC 2783) OR ACTUATION OF TORQUE CONVERTER LOCKUP CLUTCH NOT POSSIBLE (FC 0741)</a>	<a href="#">2015-10-07</a>
<a href="#">LI27.19-P-059057</a>	<a href="#">MODIFIED PROCEDURE FOR ISM OR DSM REPLACEMENT IN MODEL 166 (ML) WITH THE FAULT CODES P179A12, P179A16, P179C16, B210A00 AND B210D00</a>	<a href="#">2015-08-11</a>
<a href="#">LI27.19-P-057340</a>	<a href="#">TRANSMISSION CONTROL UNIT Y3/8N4 (FULLY INTEGRATED TRANSMISSION CONTROL UNIT (VGS)) NOT LISTED IN QUICK TEST; NO COMMUNICATION POSSIBLE WITH VGS</a>	<a href="#">2013-11-19</a>
<a href="#">LI27.19-P-056610</a>	<a href="#">M276 MY2013 AND MY2014 - HARSH SHIFTS: 4-3, 4-5</a>	<a href="#">2014-06-13</a>
<a href="#">LI27.10-P-057361</a>	<a href="#">HUMMING, DRONING, VIBRATIONS, SHUDDERING, JOLTING, SLIP</a>	<a href="#">2014-06-12</a>
<a href="#">LI27.00-P-060968</a>	<a href="#">UNCOMFORTABLE 1-2 AND 3-2 SHIFTS IN MODEL 166 (ML) WITH ENGINE 276.955</a>	<a href="#">2015-06-22</a>
<a href="#">LI27.00-P-060097</a>	<a href="#">FAULT CODE P089300 ON 722.9 TRANSMISSION WITH VGS4NAG2</a>	<a href="#">2015-08-26</a>
<a href="#">LI27.00-P-059110</a>	<a href="#">UNCOMFORTABLE 1-2, 2-3 AND/OR 3-4 ACCELERATION UPSHIFTS WITH COLD TRANSMISSION OIL IN MODEL 166 WITH ENGINE 642</a>	<a href="#">2015-06-08</a>
<a href="#">LI27.00-P-051451</a>	<a href="#">SHIFT QUALITY COMPLAINTS ON TRANSMISSION 722.9 (7G-TRONIC AND 7G-TRONIC PLUS)</a>	<a href="#">2014-07-14</a>
<a href="#">LI18.30-P-059712</a>	<a href="#">SEAL FOR HEAT EXCHANGER FOR THE ENGINE OIL HAS A SLIGHT LEAK</a>	<a href="#">2016-08-05</a>
<a href="#">LI18.30-P-055434</a>	<a href="#">TRACES OF OIL IN AREA OF OIL COOLER (INNER V) ON ENGINE 642</a>	<a href="#">2014-02-19</a>
<a href="#">LI14.20-P-060882</a>	<a href="#">EXHAUST GAS RECIRCULATION LINE - INNER TUBE DISTORTED</a>	<a href="#">2015-02-17</a>
<a href="#">LI13.20-P-054857</a>	<a href="#">DRIVE BELT AREA NOISES</a>	<a href="#">2014-05-22</a>
<a href="#">LI09.40-P-063552</a>	<a href="#">REPAIR GUIDELINES FOR TURBOCHARGER FAILURES</a>	<a href="#">2016-03-11</a>
<a href="#">LI09.40-P-061542</a>	<a href="#">RATTLING NOISE FROM TURBOCHARGER</a>	<a href="#">2015-09-09</a>
<a href="#">LI09.40-P-054329</a>	<a href="#">EXTERNAL COOLANT LOSS AND/OR OIL LOSS BETWEEN TURBOCHARGER AND CARRIER</a>	<a href="#">2016-09-30</a>
<a href="#">LI09.20-P-063238</a>	<a href="#">OIL LOSS AT ENGINE AIR INTAKE DUCT DOWNSTREAM OF AIR FILTER TO TURBOCHARGER</a>	<a href="#">2016-02-04</a>
<a href="#">LI07.16-P-055799</a>	<a href="#">FAULT CODE(S) 13BA00, 13BB00, 13BC00, 13BD00, 13BE00, 13BF00 - MAXIMUM ACTUATION PERIOD EXCEEDED DURING ZERO QUANTITY CALIBRATION FOR INJECTOR OF CYLINDER X STORED IN ENGINE CONTROL UNIT</a>	<a href="#">2016-02-23</a>
<a href="#">LI07.08-P-060993</a>	<a href="#">ENGINE DIAGNOSIS WARNING LAMP LIGHTS UP IN INSTRUMENT CLUSTER, FAULT CODE U145400: "IMPLAUSIBLE DATA WERE RECEIVED FROM THE ETHANOL SENSOR"</a>	<a href="#">2015-12-03</a>
<a href="#">LI07.08-P-060917</a>	<a href="#">ENGINE DOES NOT START AFTER AUTOMATIC ECO STOP, THE FAULT CODE P1CE200 OR 16F400 IS LOGGED IN THE FAULT MEMORY OF THE ENGINE CONTROL UNIT</a>	<a href="#">2015-12-14</a>

<a href="#">LI07.08-P-057357</a>	<a href="#">FAULT CODE P061194 -THE FUEL INJECTOR CONTROL UNIT HAS A MALFUNCTION (OUTPUT STAGE FAULT OF ENGINE CONTROL UNIT)-IS STORED IN ENGINE CONTROL UNIT (SOMETIMES WITH ACTIVE ENGINE DIAGNOSIS WARNING LAMP)</a>	<a href="#">2013-10-03</a>
<a href="#">LI07.08-P-056434</a>	<a href="#">ENGINE SHUTS OFF AFTER VEHICLE COMES TO A STOP IN TRAFFIC AND IDLES AT A STANDSTILL</a>	<a href="#">2016-04-01</a>
<a href="#">LI07.08-P-056245</a>	<a href="#">FAULT CODE U040208 - IMPLAUSIBLE DATA RECEIVED FROM CONTROL UNIT "TRANSMISSION" - IS STORED IN THE ENGINE CONTROL UNIT (SOMETIMES WITH ACTIVE ENGINE DIAGNOSIS WARNING LAMP)</a>	<a href="#">2016-02-01</a>
<a href="#">LI07.08-P-055310</a>	<a href="#">ENGINE DIES IMMEDIATELY AFTER STARTING</a>	<a href="#">2015-05-29</a>
<a href="#">LI07.04-P-061777</a>	<a href="#">ENGINE DIAGNOSIS WARNING LAMP ACTIVE, MALFUNCTION AT EXHAUST BACK PRESSURE SENSOR</a>	<a href="#">2015-07-06</a>
<a href="#">LI07.02-P-054717</a>	<a href="#">TICKING OR PULSING NOISE FROM HIGH-PRESSURE PUMP AND FUEL INJECTORS</a>	<a href="#">2014-12-15</a>
<a href="#">LI05.10-P-062031</a>	<a href="#">RATTLING NOISE AFTER ENGINE START FOR SEVERAL SECONDS</a>	<a href="#">2015-08-12</a>
<a href="#">LI05.10-P-056435</a>	<a href="#">RATTLING NOISE AFTER ENGINE START FOR SEVERAL SECONDS</a>	<a href="#">2016-07-21</a>
<a href="#">LI05.10-P-049909</a>	<a href="#">ENGINE NOISES AFTER ENGINE START</a>	<a href="#">2016-04-18</a>
<a href="#">LI03.10-P-054702</a>	<a href="#">KNOCKING NOISES IN CRANK ASSEMBLY</a>	<a href="#">2016-03-08</a>
<a href="#">LI01.30-P-058630</a>	<a href="#">ENGINE OIL LEAK AT OIL DUCT OF LEFT OR RIGHT CYLINDER HEAD</a>	<a href="#">2015-12-15</a>
<a href="#">LI01.10-P-065345</a>	<a href="#">ENGINE SHAKES OR RUNS ROUGHLY - "COMBUSTION MISFIRE IN CYLINDER X" FAULTS ARE STORED IN THE ENGINE CONTROL UNIT</a>	<a href="#">2016-11-29</a>
<a href="#">GI58.40-P-057711</a>	<a href="#">DAS/XD ADD-ON 2013-10-28-3170 FOR PASSENGER CARS</a>	<a href="#">2013-11-07</a>
<a href="#">GI58.40-P-057698</a>	<a href="#">DAS/XD ADD-ON 2013-10-28-3169 FOR PASSENGER CARS</a>	<a href="#">2013-11-07</a>
<a href="#">GI58.40-P-057695</a>	<a href="#">DAS/XD ADD-ON 2013-10-21-3152 FOR PASSENGER CARS</a>	<a href="#">2013-11-07</a>
<a href="#">GI58.40-P-057694</a>	<a href="#">DAS/XD ADD-ON 2013-10-21-3153 FOR PASSENGER CARS</a>	<a href="#">2013-11-07</a>
<a href="#">GI58.40-P-057556</a>	<a href="#">DAS/XD ADD-ON 2013-10-14-3139 FOR PASSENGER CARS</a>	<a href="#">2013-11-07</a>
<a href="#">GI58.40-P-057555</a>	<a href="#">DAS/XD ADD-ON 2013-10-14-3138 FOR PASSENGER CARS</a>	<a href="#">2013-11-07</a>
<a href="#">GI58.40-P-057508</a>	<a href="#">DAS/XD ADD-ON 2013-10-07-3124 FOR PASSENGER CARS</a>	<a href="#">2013-11-07</a>
<a href="#">GI58.40-P-057502</a>	<a href="#">DAS/XD ADD-ON 2013-10-08-3127 FOR PASSENGER CARS</a>	<a href="#">2013-11-07</a>
<a href="#">GI58.40-P-057501</a>	<a href="#">DAS/XD ADD-ON 2013-10-07-3123 FOR PASSENGER CARS</a>	<a href="#">2013-11-07</a>
<a href="#">GI58.40-P-057475</a>	<a href="#">DAS/XD ADD-ON 2013-10-02-3120 FOR PASSENGER CARS</a>	<a href="#">2013-11-07</a>
<a href="#">GI58.40-P-057474</a>	<a href="#">DAS/XD ADD-ON 2013-09-30-3102 FOR PASSENGER CARS</a>	<a href="#">2013-11-07</a>
<a href="#">GI58.40-P-057473</a>	<a href="#">DAS/XD ADD-ON 2013-09-30-3101 FOR PASSENGER CARS</a>	<a href="#">2013-11-07</a>
<a href="#">GI58.40-P-057470</a>	<a href="#">DAS/XD ADD-ON 2013-10-01-3107 FOR PASSENGER CARS</a>	<a href="#">2013-11-07</a>
<a href="#">GI58.40-P-057445</a>	<a href="#">DAS/XD ADD-ON 2013-09-24-3095 FOR PASSENGER CARS</a>	<a href="#">2013-11-07</a>
<a href="#">GI58.40-P-057444</a>	<a href="#">DAS/XD ADD-ON 2013-09-24-3094 FOR PASSENGER CARS</a>	<a href="#">2013-11-07</a>
<a href="#">GI58.40-P-057439</a>	<a href="#">DAS/XD ADD-ON 2013-09-25-3097 FOR PASSENGER CARS</a>	<a href="#">2013-11-07</a>
<a href="#">GI58.40-P-057438</a>	<a href="#">DAS/XD ADD-ON 2013-09-25-3096 FOR PASSENGER CARS</a>	<a href="#">2013-11-07</a>

<a href="#">GI58.40-P-057320</a>	<a href="#">DAS/XD ADD-ON 2013-09-09-3050 FOR PASSENGER CARS</a>	<a href="#">2013-11-07</a>
<a href="#">GI58.40-P-057310</a>	<a href="#">DAS/XD ADD-ON 2013-09-09-3051 FOR PASSENGER CARS</a>	<a href="#">2013-11-07</a>
<a href="#">GI58.40-P-057262</a>	<a href="#">DAS/XD ADD-ON 2013-09-02-3033 FOR PASSENGER CARS</a>	<a href="#">2013-11-07</a>
<a href="#">GI58.40-P-057260</a>	<a href="#">DAS/XD ADD-ON 2013-09-02-3032 FOR PASSENGER CARS</a>	<a href="#">2013-11-07</a>
<a href="#">GI58.40-P-057210</a>	<a href="#">DAS/XD ADD-ON 2013-08-29-3028 FOR PASSENGER CARS</a>	<a href="#">2013-08-30</a>
<a href="#">GI58.40-P-057196</a>	<a href="#">DAS/XD ADD-ON 2013-08-26-3014 FOR PASSENGER CARS</a>	<a href="#">2013-08-30</a>
<a href="#">GI58.40-P-057195</a>	<a href="#">DAS/XD ADD-ON 2013-08-26-3013 FOR PASSENGER CARS</a>	<a href="#">2013-08-30</a>
<a href="#">GI58.40-P-057149</a>	<a href="#">DAS/XD ADD-ON 2013-08-19-2985 FOR PASSENGER CARS</a>	<a href="#">2013-08-30</a>
<a href="#">GI58.40-P-057129</a>	<a href="#">DAS/XD ADD-ON 2013-08-19-2984 FOR PASSENGER CARS</a>	<a href="#">2013-08-30</a>
<a href="#">GI58.40-P-057094</a>	<a href="#">DAS/XD ADD-ON 2013-08-14-2975 FOR PASSENGER CARS</a>	<a href="#">2013-08-30</a>
<a href="#">GI58.40-P-057093</a>	<a href="#">DAS/XD ADD-ON 2013-08-14-2973 FOR PASSENGER CARS</a>	<a href="#">2013-08-30</a>
<a href="#">GI58.40-P-057091</a>	<a href="#">DAS/XD ADD-ON 2013-08-12-2968 FOR PASSENGER CARS</a>	<a href="#">2013-08-30</a>
<a href="#">GI58.40-P-057090</a>	<a href="#">DAS/XD ADD-ON 2013-08-12-2967 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056998</a>	<a href="#">DAS/XD ADD-ON 2013-08-02-2948 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056997</a>	<a href="#">DAS/XD ADD-ON 2013-08-06-2959 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056990</a>	<a href="#">DAS/XD ADD-ON 2013-08-05-2955 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056988</a>	<a href="#">DAS/XD ADD-ON 2013-08-05-2954 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056965</a>	<a href="#">DAS/XD ADD-ON 2013-08-02-2952 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056956</a>	<a href="#">DAS/XD ADD-ON 2013-07-29-2939 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056954</a>	<a href="#">DAS/XD ADD-ON 2013-07-29-2938 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056953</a>	<a href="#">DAS/XD ADD-ON 2013-07-30-2942 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056881</a>	<a href="#">DAS/XD ADD-ON 2013-07-22-2926 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056880</a>	<a href="#">DAS/XD ADD-ON 2013-07-22-2925 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056879</a>	<a href="#">DAS/XD ADD-ON 2013-07-19-2923 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056878</a>	<a href="#">DAS/XD ADD-ON 2013-07-19-2922 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056877</a>	<a href="#">DAS/XD ADD-ON 2013-07-19-2921 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056861</a>	<a href="#">DAS/XD ADD-ON 2013-07-15-2910 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056822</a>	<a href="#">DAS/XD ADD-ON 2013-07-15-2909 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056821</a>	<a href="#">DAS/XD ADD-ON 2013-07-15-2908 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056820</a>	<a href="#">DAS/XD ADD-ON 2013-07-11-2904 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056819</a>	<a href="#">DAS/XD ADD-ON 2013-07-11-2903 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056816</a>	<a href="#">DAS/XD ADD-ON 2013-07-09-2895 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056813</a>	<a href="#">DAS/XD ADD-ON 2013-07-08-2893 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056808</a>	<a href="#">DAS/XD ADD-ON 2013-07-08-2892 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056800</a>	<a href="#">DAS/XD ADD-ON 2013-07-03-2887 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056796</a>	<a href="#">DAS/XD ADD-ON 2013-07-01-2884 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056649</a>	<a href="#">DAS/XD ADD-ON 2013-06-25-2868 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056648</a>	<a href="#">DAS/XD ADD-ON 2013-06-24-2866 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056597</a>	<a href="#">DAS/XD ADD-ON 2013-06-17-2856 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056595</a>	<a href="#">DAS/XD ADD-ON 2013-06-06-2830 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056594</a>	<a href="#">DAS/XD ADD-ON 2013-06-17-2854 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>



<a href="#">GI58.40-P-056593</a>	<a href="#">DAS/XD ADD-ON 2013-06-17-2853 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056592</a>	<a href="#">DAS/XD ADD-ON 2013-06-10-2840 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056591</a>	<a href="#">DAS/XD ADD-ON 2013-06-10-2839 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056582</a>	<a href="#">DAS/XD ADD-ON 2013-06-13-2843 FOR PASSENGER CARS</a>	<a href="#">2013-08-30</a>
<a href="#">GI58.40-P-056564</a>	<a href="#">DAS/XD ADD-ON 2013-06-10-2838 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056561</a>	<a href="#">DAS/XD ADD-ON 2013-06-06-2830 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056560</a>	<a href="#">DAS/XD ADD-ON 2013-06-07-2834 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056552</a>	<a href="#">DAS/XD ADD-ON 2013-06-03-2828 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056549</a>	<a href="#">DAS/XD ADD-ON 2013-06-03-2827 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056544</a>	<a href="#">DAS/XD ADD-ON 2013-05-29-2821 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056543</a>	<a href="#">DAS/XD ADD-ON 2013-05-27-2817 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056542</a>	<a href="#">DAS/XD ADD-ON 2013-05-27-2816 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056541</a>	<a href="#">DAS/XD ADD-ON 2013-05-21-2808 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056540</a>	<a href="#">DAS/XD ADD-ON 2013-05-21-2807 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056405</a>	<a href="#">DAS/XD ADD-ON 2013-05-16-2806 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056404</a>	<a href="#">DAS/XD ADD-ON 2013-05-16-2805 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056378</a>	<a href="#">DAS/XD ADD-ON 2013-05-16-2804 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056377</a>	<a href="#">DAS/XD ADD-ON 2013-05-13-2800 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056376</a>	<a href="#">DAS/XD ADD-ON 2013-05-13-2799 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056375</a>	<a href="#">DAS/XD ADD-ON 2013-05-13-2798 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056331</a>	<a href="#">DAS/XD ADD-ON 2013-05-06-2791 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056314</a>	<a href="#">DAS/XD ADD-ON 2013-04-29-2786 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056272</a>	<a href="#">DAS/XD ADD-ON 2013-04-23-2775 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056268</a>	<a href="#">DAS/XD ADD-ON 2013-04-22-2773 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056267</a>	<a href="#">DAS/XD ADD-ON 2013-04-22-2771 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056266</a>	<a href="#">DAS/XD ADD-ON 2013-04-22-2770 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056251</a>	<a href="#">DAS/XD ADD-ON 2013-04-15-2759 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056250</a>	<a href="#">DAS/XD ADD-ON 2013-04-15-2758 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056134</a>	<a href="#">DAS/XD ADD-ON 2013-04-08-2748 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056127</a>	<a href="#">DAS/XD ADD-ON 2013-04-08-2747 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-056115</a>	<a href="#">DAS/XD ADD-ON 2013-04-02-2740 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">GI58.40-P-049529</a>	<a href="#">DAS/XD ADD-ON 2013-06-07-2833 FOR PASSENGER CARS</a>	<a href="#">2013-09-02</a>
<a href="#">DTB 05M/01; MB-NET 101</a>	<a href="#">HEADLAMPS/FRONT FOG LAMPS LEAKING OR FOGGED</a>	<a href="#">2013-11-19</a>
<a href="#">98.00/32</a>	<a href="#">MY-ALL, MODELS ALL, PAINT DRYING IN DRYING FACILITY</a>	<a href="#">2015-04-15</a>
<a href="#">98.00/13V</a>	<a href="#">MBUSA APPROVED REFINISHING PRODUCTS</a>	<a href="#">2015-02-05</a>
<a href="#">98.00/13U</a>	<a href="#">MBUSA APPROVED REFINISHING PRODUCTS</a>	<a href="#">2015-02-05</a>
<a href="#">98.00/13T</a>	<a href="#">MBUSA APPROVED REFINISHING PRODUCTS</a>	<a href="#">2015-02-05</a>
<a href="#">98.00/13S</a>	<a href="#">MBUSA APPROVED REFINISHING PRODUCTS</a>	<a href="#">2015-02-05</a>
<a href="#">98.00/13R</a>	<a href="#">MBUSA APPROVED REFINISHING PRODUCTS</a>	<a href="#">2015-02-05</a>
<a href="#">98.00/13P</a>	<a href="#">MBUSA APPROVED REFINISHING PRODUCTS</a>	<a href="#">2015-02-05</a>



<a href="#"><u>98.00/13O</u></a>	<a href="#"><u>MBUSA APPROVED REFINISHING PRODUCTS</u></a>	<a href="#"><u>2015-02-05</u></a>
<a href="#"><u>98.00/13M</u></a>	<a href="#"><u>MBUSA APPROVED REFINISHING PRODUCTS</u></a>	<a href="#"><u>2015-02-05</u></a>
<a href="#"><u>98.00/13I</u></a>	<a href="#"><u>MBUSA APPROVED REFINISHING PRODUCTS</u></a>	<a href="#"><u>2015-02-05</u></a>
<a href="#"><u>98.00/13H</u></a>	<a href="#"><u>MBUSA APPROVED REFINISHING PRODUCTS</u></a>	<a href="#"><u>2015-02-05</u></a>
<a href="#"><u>88.40/90</u></a>	<a href="#"><u>PERMANENTLY ILLUMINATED STAR INSTALLATION INSTRUCTIONS</u></a>	<a href="#"><u>2013-11-26</u></a>
<a href="#"><u>82.85/693L</u></a>	<a href="#"><u>SPLITVIEW ACTIVATION/DEACTIVATION</u></a>	<a href="#"><u>2014-08-20</u></a>
<a href="#"><u>82.85/693K</u></a>	<a href="#"><u>SPLITVIEW ACTIVATION/DEACTIVATION</u></a>	<a href="#"><u>2014-08-20</u></a>
<a href="#"><u>82.85/693J</u></a>	<a href="#"><u>SPLITVIEW ACTIVATION/DEACTIVATION</u></a>	<a href="#"><u>2014-08-20</u></a>
<a href="#"><u>82.85/693H</u></a>	<a href="#"><u>SPLITVIEW ACTIVATION/DEACTIVATION</u></a>	<a href="#"><u>2014-08-20</u></a>
<a href="#"><u>82.85/693G</u></a>	<a href="#"><u>SPLITVIEW ACTIVATION/DEACTIVATION</u></a>	<a href="#"><u>2014-08-20</u></a>
<a href="#"><u>82.85/693C</u></a>	<a href="#"><u>SPLITVIEW ACTIVATION/DEACTIVATION</u></a>	<a href="#"><u>2014-08-20</u></a>
<a href="#"><u>82.85/693A</u></a>	<a href="#"><u>SPLITVIEW ACTIVATION/DEACTIVATION</u></a>	<a href="#"><u>2014-08-20</u></a>
<a href="#"><u>82.61/702</u></a>	<a href="#"><u>HANDLING NAVIGATION MODULE BECKER MAP PILOT</u></a>	<a href="#"><u>2013-06-26</u></a>
<a href="#"><u>82.10/334</u></a>	<a href="#"><u>HEADLAMPS/FRONT FOG LAMPS LEAKING OR FOGGED</u></a>	<a href="#"><u>2013-11-19</u></a>
<a href="#"><u>80.61/63</u></a>	<a href="#"><u>SMARTKEY FUNCTIONS USING KEYLESS GO</u></a>	<a href="#"><u>2015-01-12</u></a>
<a href="#"><u>80.57/62E</u></a>	<a href="#"><u>ORDERING A PROGRAMMED KEY WHEN NO KEYS ARE PRESENT -\ "THE FALLBACK PROCESS"</u></a>	<a href="#"><u>2015-06-22</u></a>
<a href="#"><u>80.57/62D</u></a>	<a href="#"><u>ORDERING A PROGRAMMED KEY WHEN NO KEYS ARE PRESENT -\ "THE FALLBACK PROCESS"</u></a>	<a href="#"><u>2015-06-22</u></a>
<a href="#"><u>80.57/62B</u></a>	<a href="#"><u>ORDERING A PROGRAMMED KEY WHEN NO KEYS ARE PRESENT -\ "THE FALLBACK PROCESS"</u></a>	<a href="#"><u>2015-06-22</u></a>
<a href="#"><u>80.57/62A</u></a>	<a href="#"><u>ORDERING A PROGRAMMED KEY WHEN NO KEYS ARE PRESENT -\ "THE FALLBACK PROCESS"</u></a>	<a href="#"><u>2015-06-22</u></a>
<a href="#"><u>80.57/62</u></a>	<a href="#"><u>ORDERING A PROGRAMMED KEY WHEN NO KEYS ARE PRESENT -\ "THE FALLBACK PROCESS"</u></a>	<a href="#"><u>2015-06-22</u></a>
<a href="#"><u>68.30/83</u></a>	<a href="#"><u>NOTES ON ATTACHING MAGNETS TO HEADLINER</u></a>	<a href="#"><u>2014-02-20</u></a>
<a href="#"><u>67.10/30</u></a>	<a href="#"><u>CHANGE TO SINGLE COMPONENT WINDSHIELD BONDING SYSTEM</u></a>	<a href="#"><u>2014-04-11</u></a>
<a href="#"><u>60.00/23</u></a>	<a href="#"><u>INTRODUCTION OF TWO-COMPONENT EPOXY BODY FILLER</u></a>	<a href="#"><u>2015-07-06</u></a>
<a href="#"><u>60.00/22</u></a>	<a href="#"><u>HANDLING LEAD-FREE FILLING SOLDER</u></a>	<a href="#"><u>2013-07-02</u></a>
<a href="#"><u>6/19/14</u></a>	<a href="#"><u>SPARK PLUG INDEXING FOR DIRECT INJECTION ENGINES</u></a>	<a href="#"><u>2014-06-19</u></a>
<a href="#"><u>58.40-P-057368</u></a>	<a href="#"><u>DAS/XD ADD-ON 2013-09-16-3075 FOR PASSENGER CARS</u></a>	<a href="#"><u>2013-11-07</u></a>
<a href="#"><u>58.20/167</u></a>	<a href="#"><u>SPECIAL TOOL RETURN DUE TO INTERFERENCE ISSUE</u></a>	<a href="#"><u>2015-03-06</u></a>
<a href="#"><u>54.21/257</u></a>	<a href="#"><u>INITIAL STARTUP OF STEERING COLUMN TUBE SWITCH MODULE</u></a>	<a href="#"><u>2013-07-18</u></a>
<a href="#"><u>54.10/264</u></a>	<a href="#"><u>BATTERY CARE FOR HV BATTERIES IN AFTER-SALES</u></a>	<a href="#"><u>2014-07-08</u></a>
<a href="#"><u>5/20/14</u></a>	<a href="#"><u>BIODIESEL INFORMATION FOR MERCEDES-BENZ VEHICLES 2014 EDITION</u></a>	<a href="#"><u>2014-05-20</u></a>
<a href="#"><u>47.10/30E</u></a>	<a href="#"><u>PROCEDURE FOR WHEN DIESEL FUEL TANK IS FILLED WITH INCORRECT FUEL TYPE</u></a>	<a href="#"><u>2016-04-04</u></a>
<a href="#"><u>47.10/30D</u></a>	<a href="#"><u>PROCEDURE FOR WHEN DIESEL FUEL TANK IS FILLED WITH INCORRECT FUEL TYPE</u></a>	<a href="#"><u>2016-04-04</u></a>

<a href="#"><u>47.10/30B</u></a>	<a href="#"><u>PROCEDURE FOR WHEN DIESEL FUEL TANK IS FILLED WITH INCORRECT FUEL TYPE</u></a>	<a href="#"><u>2016-04-04</u></a>
<a href="#"><u>47.10/30A</u></a>	<a href="#"><u>PROCEDURE FOR WHEN DIESEL FUEL TANK IS FILLED WITH INCORRECT FUEL TYPE</u></a>	<a href="#"><u>2016-04-04</u></a>
<a href="#"><u>42.10/125</u></a>	<a href="#"><u>MY-ALL, MODELS ALL, BRAKE CALIPER WITH MERCEDES-BENZ BRAND COVER</u></a>	<a href="#"><u>2014-10-20</u></a>
<a href="#"><u>42.10/123A</u></a>	<a href="#"><u>CLEANING AXLE HUBS WHEN INSTALLING BRAKE DISCS</u></a>	<a href="#"><u>2014-12-11</u></a>
<a href="#"><u>42.10/123</u></a>	<a href="#"><u>CLEANING AXLE HUBS WHEN INSTALLING BRAKE DISCS</u></a>	<a href="#"><u>2014-12-11</u></a>
<a href="#"><u>42.10/119</u></a>	<a href="#"><u>FABRICATION OF BRAKE LINES</u></a>	<a href="#"><u>2013-10-29</u></a>
<a href="#"><u>32.34/84</u></a>	<a href="#"><u>CHECK ACTIVE CURVE SYSTEM HYDRAULIC PUMP</u></a>	<a href="#"><u>2014-02-11</u></a>
<a href="#"><u>32.25/82C</u></a>	<a href="#"><u>SHOCK ABSORBER REPLACEMENT</u></a>	<a href="#"><u>2013-06-04</u></a>
<a href="#"><u>32.25/82B</u></a>	<a href="#"><u>SHOCK ABSORBER REPLACEMENT</u></a>	<a href="#"><u>2013-06-04</u></a>
<a href="#"><u>32.25/82A</u></a>	<a href="#"><u>SHOCK ABSORBER REPLACEMENT</u></a>	<a href="#"><u>2013-06-04</u></a>
<a href="#"><u>31.19/07D</u></a>	<a href="#"><u>INSTALLING ELECTRIC TRAILER BRAKE CONTROLLER</u></a>	<a href="#"><u>2016-05-19</u></a>
<a href="#"><u>31.19/07C</u></a>	<a href="#"><u>INSTALLING ELECTRIC TRAILER BRAKE CONTROLLER</u></a>	<a href="#"><u>2016-05-19</u></a>
<a href="#"><u>28.00/13</u></a>	<a href="#"><u>TRANSFER CASE BREATHER DESIGN CHANGE</u></a>	<a href="#"><u>2014-11-13</u></a>
<a href="#"><u>27.30/127</u></a>	<a href="#"><u>TRANSMISSION SEAL CHANGE</u></a>	<a href="#"><u>2015-03-26</u></a>
<a href="#"><u>15.40/73</u></a>	<a href="#"><u>ALTERNATOR DIAGNOSIS</u></a>	<a href="#"><u>2014-12-09</u></a>
<a href="#"><u>15.10/74</u></a>	<a href="#"><u>SPARK PLUG CONNECTOR GREASE</u></a>	<a href="#"><u>2015-02-09</u></a>
<a href="#"><u>00.40/89D</u></a>	<a href="#"><u>OPERATING FLUID SPECIFICATION CHANGES FOR AUTOMATIC TRANSMISSION</u></a>	<a href="#"><u>2013-11-06</u></a>
<a href="#"><u>00.40/89C</u></a>	<a href="#"><u>OPERATING FLUID SPECIFICATION CHANGES FOR AUTOMATIC TRANSMISSION</u></a>	<a href="#"><u>2013-11-06</u></a>
<a href="#"><u>00.40/89A</u></a>	<a href="#"><u>OPERATING FLUID SPECIFICATION CHANGES FOR AUTOMATIC TRANSMISSION</u></a>	<a href="#"><u>2013-11-06</u></a>
<a href="#"><u>00.40/89</u></a>	<a href="#"><u>OPERATING FLUID SPECIFICATION CHANGES FOR AUTOMATIC TRANSMISSION</u></a>	<a href="#"><u>2013-11-06</u></a>
<a href="#"><u>00.00/111</u></a>	<a href="#"><u>VEHICLE ON-BOARD DIAGNOSTIC SYSTEMS AND EMISSIONS CONTROL TAMPERING</u></a>	<a href="#"><u>2015-12-21</u></a>

**[:: TOP ::](#)**

[For Additional Professional Auto Repair Services, Click Here](#)

Copyright 2017 Mitchell Repair Information Company, LLC. All Rights Reserved. [Legal Notices](#)  
| [Privacy Policy](#)