

XENTRY

Brake squeal just before standstill

Topic number	LI42.10-P-055571
Version	1
Design group	42.10 Service brake
Date	01-25-2013
Validity	166.074 / 874
Reason for change	

Complaint:
 Brake squeal
Note:

Brake squeal occurs frequently with cold and cooling brakes.

This can also occur in isolated case with brake systems at operating temperature.

The complaint occurs primarily in cold outside temperatures.

Cause:

Frictional vibrations

Remedy:**Note:**

The noise comes from the front axle

Replacing the brake pads does not provide a remedy.

We will shortly make a remedy available to you and update this TIPS.

Until then, do not perform any other work.

Symptoms
Chassis/suspension / Brake system / Service brake / Brake noise / Squeaking
Chassis/suspension / Brake system / Service brake / Brake noise / Whirring/howling

Work units				
Op. no.	Operation text	Time	Damage code	Note
			42214 36	

XENTRY

WIS-References			
Document number	Title	Note	Allocation
SI00.00-P-0086A	Guidelines for queries relating to technical complaints		Remedy