

[Back To Article](#)**NIGHT PERFORMANCE OF 360° CAMERA DARK****TECHNICAL SERVICE BULLETIN**

Reference Number(s): LI54.65-P-059114 Version 5, Date of Issue: December 9, 2014

MERCEDES- 166 with code 501 produced up to 10/2014; 212 with code 501 produced up to 10/2014; 217 with BENZ: code 501 produced up to 05/2014; 222 with code 501 produced up to 05/2014

DESIGN GROUP: 54.65 Parking assist

REASON

FOR Model X166 added

CHANGE:

COMPLAINT

At night, the picture from the 360° camera in the display on the head unit can appear dark.

CAUSE

Image processing software

REMEDY

Software update with optimized parameters.

Model series 217/222:

The software update is available for XENTRY with DVD 09/2014.

Model series 166/212

The software update is provided for XENTRY via

- Add-on 4018 DVD 07/2014
- Add-on 4039 DVD 09/2014.

CONTROL UNIT/FAULT CODE**CONTROL UNIT/FAULT CODE**

| Control unit | Fault code | Fault text |
|--|------------|------------|
| 360° camera - 360° camera (N148) (SVS166) (E (212), M (166), GL (166)) | - | - |
| 360° camera - 360° camera (N148) (SVS222) (S (222), S (217)) | - | - |