

Mercedes Benz TSB Listing - R Class (W251) Highlighted in Yellow - All Model Years

Issue Date	DTB Number	Title
May 2009		<p>For updates and full text subscribe at STAR TekInfo.</p> <p>Since most initial bugs seem to be resolved now, there wont be further updates on this page. Revision: Warranty (Model Indicators) Information Updated</p>
May 07, 2009	S-B-01.30/23a	<p>All Passenger and Light Truck Models Equipped with Engine M272 / 273 Oil Seepage from Back of Cylinder Head Revision: WIS Document Reference Added (211.2) All Model 164, 211, 219, 221 and 251 Vehicles Equipped with Airmatic Suspension (Sales Code 489)</p>
May 06, 2009	S-B-32.22/78a	<p>"Airmatic - Visit Workshop" Displayed Within Instrument Cluster</p>
May 06, 2009	S-B-18.20/43	<p>All AMG Models Equipped with M156 Engine Engine Oil Leak at Oil Filter Housing</p> <p>Revision: Warranty Information Updated - Op Code 02-3472 Included</p> <p>Model 164.122/175/186, Model 171.454/456/473, Model 203.052/054/056</p> <p>Model 209.356/375/456/475, Model 211.056/070/256, Model 215.375 Model 219.375, Model 220.170/175, Model 230.475, Model 251.122/165/175</p> <p>Equipped with 7G-Tronic Transmission (NAG2), Serial Numbers Between 7229xx 00 327088 and 7229xx 00 338693</p>
May 05, 2009	S-B-27.50/59g	<p>Transmission in Limp Home Mode with Fault Codes 2200, 2201, 2767 and 2768</p> <p>All Model 164, 211, 219 and 251 Vehicles, MY 2006 - MY 2008 All Model 221 Vehicles, MY 2007 - 2009</p> <p>Equipped with Hands-free Telephone System and Dealer Retrofit iPod Interface Kit</p>
May 05, 2009	S-B-82.70/687	<p>iPhone/iPhone 3G Music is Audible During an Active Phone Call Revision: Warranty Information Updated</p> <p>Model 164.177 Model 204.077 Model 209.377/477 Model 211.077/277 Model 216.377 Model 219.377 Model 221.177 Model 230.470 Model 251.177</p>
May 01, 2009	S-B-01.20/24a	<p>Equipped with M156 Engine, Up to Engine Number 15698x 60 022000 Whistling Sound from Engine Compartment MY2005 to Present, Models All</p>
Apr 30, 2009	S-B-82.70/686	<p>Telephone and Bluetooth Adapter Diagnosis and Test Tool W203 589 07 63 00 and Warranty Return Requirements</p> <p>Applicable Models (216 Added), Local Purchase and Warranty Information Updated All Model 164, 171, 203, 204, 209, 211, 215, 216, 219, 220, 221, 230 and 251</p>
Apr 29, 2009	S-B-83.30/74o	<p>Air Conditioning Musty/Moldy Odor Complaints Revision P: Approved Products Added MY-All All Models</p>
April 28, 2009	S-B-98.00/13P	<p>MBUSA-Approved Refinishing Products Recall: Model 164, Model Year 2009</p>
April 24, 2009	2009030003	<p>Reposition Power Lift Gate Control Module and Replace Right and Left Tail Lamp Unit Seals</p> <p>Revision: Applicable Models Updated / Technical Content Revised Model 164.172/186/871/886, Model 171.454/456 Model 203.052/054/056/087/092, Model 204.054/056/061 Model 209.356/372/456/472</p> <p>Model 211.056/072/087/090/256/287, Model 216.371, Model 219.372 Model 221.171/186, Model 230.471, Model 251.156/165 Equipped with M272 Engine or M273 Engine</p>
April 23, 2009	S-B-03.30/08i	<p>Check Engine Light On / Fault Codes Current and/or Stored in ME-SFI</p> <p>Control Module / Oil Leaking at Camshaft Adjustment Solenoid Revision: VIN Information within Warranty Table Corrected All Model 164 and 251 Vehicles</p>
Apr 22, 2009	T-B-72.20/59d	<p>Message "Liftgate Open" in Instrument Cluster Display or Liftgate Will Not Engage Completely Revision: Operation Code Typo Corrected Model 164.122/172/175/177/186, up to Model Year 2008 Model 203.052/054/056/076/087/092, up to Model Year 2007</p>

		Model 204.054/056/081, up to Model Year 2008 Model 209.356/372/377/456/472/477, up to Model Year 2008 Model 251.122/156/165/175/177, up to Model Year 2008
		Equipped with COMAND Head Unit (Code 512, 527, 530, 528)
		Central Display Opening/Closing Errors or Inoperative, Voice Control Does
Apr 17, 2009	S-B-82.85/615b	Not Respond To User's Commands (Hands-free Conversation) and/or Other Party May Not Hear Driver's Conversation Model 164.125/825, Model 251.125
Apr 16, 2009	T-B-47.10/55	Check Engine Light Illuminated with DTC 205C21 Revision: Local Purchase Information Included for Wynns Part Number
Apr 15, 2009	S-B-83.30/74n	All Model 164, 171, 203, 204, 209, 211, 215, 219, 220, 221, 230 and 251 Vehicles Air Conditioning Musty/Moldy Odor Complaints Model 164.172/886 Model 209.372/472 Model 211.072/090 Model 216.371/386 Model 221.171/186 Model 230.471 Model 463.237
Apr 15, 2009	S-B-01.40/25a	Equipped with M273 5.5L Engine Up to number D273.9xx 30 27007 (Approx. June 08) Coolant Loss Revision: Applicable Models Updated (164.156 Added) Model 164.156/172/186/871/886, Model 251.156/165
Apr 03, 2009	T-B-46.30/63b	Power Steering Pump Noise Revision: Updated WIS Document Numbers Model 211.022/026, Model 164.122/822, Model 251.122
Apr 02, 2009	S-B-07.16/80d	Work on Pressure Regulator Valve (as of CDI3, 1600 bar system) Revision: Notes Added (Page 2) Pertaining to Correct Parts Information Model 164.172/183/871/886, Up to VIN A360677 Model 251.156/165, Up to VIN A076568
Mar 31, 2009	T-B-54.21/204b	Battery Not Charging and/or Vehicle Cranks Slow and/or Failed Alternator Test Revision: Remedy Updated All Model 164 / 251 Vehicles
Mar 26, 2009	T-B-82.35/606b	Windshield Washer System Inoperative After Front SAM Flash Revision: Damage Code Revised Model 164.122/175/177/186/822/871, Model 251.122/165/175/177
Mar 24, 2009	T-B-83.00/81c	Malfunctions of Various Control Units and/or On-Board Power Supply Problems Revision: Damage Code Revised Model 164.122/125/172/175/177/186/822/825/871/886 Model 251.122/125/156/165/175/177
Mar 23, 2009 Mar 23, 2009	T-B-54.10/178c S-B-98.00/24	Message in Instrument Cluster: Battery Symbol and "Visit Workshop" in White All Models, Paint Repairs Revision: Root Cause and Additional Diagnostic Information Added Model 164.122/125/172/175/177/186, Model 171.454/458/473/476 Model 211.022/056/072/077/087/090/277/287, Model 219.372/377 Model 230.470/471/472/477/479, Model 251.122/125/156/165, Model 463.237/271
		All Model Year 2009 Equipped with Satellite Radio / HD Tuner
Mar 23, 2009	S-B-82.60/681a	Satellite Radio Not Available and "Device Unavailable" Displaying on the Head Unit May Cause Current Draw Model 164.122/125/172/175/177/186/822/825/871/886
Mar 23, 2009	T-B-65.10/05	Indentations/Dings In The Roof Panel Revision: Parts List Updated to Include Heater Box Assembly as of April 6, 2009 All Model 163, 164, 170, 171, 199, 203, 204, 209, 211, 215, 216, 219, 220, 221, 230, 240, 251 and 463 Vehicles
Mar 23, 2009	P-B-83.00/109c	Diagnostic Enhancement: Climate Control -- Enhanced Diagnostic Assistance Center "EDAC" for Repairs Under Warranty Revision: Applicable Models Updated
Mar 20, 2009	S-B-82.70/475a	All Passenger Car and Light Truck Models Telephone Calls Being Cut Off or Dropped Installation Bulletin Revision B MY2009 Model 164/251 and MY2010 Model X204 with Option Code 866 RSE Pre-Wiring
Mar 20, 2009	SCN CODING	Supplemental SCN and Variant Coding for COMAND and Rear Seat Entertainment System for WIS documents

		Revision to repair procedure regarding subscriber status in Subject E, step 6.
Mar 20, 2009	2009020004	Models 164/164.8/171/204/204.9/209/211/216/219/221/230/251 Model Years 2008 and 2009 Replace Tele Aid Control Module Revision: Parts Information Updated
Mar 19, 2009	S-B-91.40/130a	All Model 164, 171, 203, 209, 211, 219, 220, 221, 230 and 251 Seat Belt Does Not Roll Up Correctly Revised for All Models with TPMS and for One Time Use of Aluminum Valve Assembly MY-All, Models All with TPMS
Mar 18, 2009	P-B-40.15/53a	Notes on Tire Mounting/Dismounting with Tire Pressure Monitoring Systems Revision: Remedy 3 Added Model 164.122/172/177/186/822/871/886, 251.122/156/165, Model Year 2008
Mar 11, 2009	T-B-54.21/198f	Battery Discharging - Increased Rest Current in the Rear SAM / CAN Bus Awake Mode Software in Steering column Module (SCM) MY-All, Models All
Mar 10, 2009	S-B-40.10/69	Radial Crack in Light Alloy Disk Wheel All Passenger and Light Truck Models
Mar 10, 2009	S-B-83.55/118	Defective Refrigeration Circuit / Refrigerant Compressor MY- All, Models 164 and 251
Mar 08, 2009	T-B-54.10/216	Simplified Battery Replacement Model 164.122/125/172/175/177/186/822/825/871/886
Mar 06, 2009	T-B-77.20/78	Glass Panel of Tilting/Sliding Roof Can Reverse During Automatic Closing Revision: Applicable Production Added to Remedy 1 Model 164.122/175/177/186/822/871, Model 251.122/165/175/177
Mar 05, 2009	T-B-83.00/89c	Climate System Temperature Setting Not Possible / LED Indicator Does Not Change When Turning Temperature Selector Wheel Model 164.122/125/172/175/177/186, Model 171.454/456/458/473 Model 211.056/065/072/077/087/090/277/287, Model 219.372/377 Model 230.470/471/472/477/479, Model 251.122/125/156/165, Model 463.237/271 All Model Year 2009, Equipped with Audio 20, Base Unit (COMAND without Navi) or COMAND Head Unit
Feb 25, 2009	S-B-82.85/679	Radio Station Display Error, Telephone Bluetooth Connection Terminates, Various Navigation and System Errors Revision: Step 1 and Damage Type Updated Model 164.175/186/871, as of MY 06 Model 171.454/456/473, as of MY 05 - 08 with COMAND Head Unit Only Model 203.040/052/054/056/0...2/261/264/281/284/740/764, as of MY 05 - 07 Model 209.356/365/375/376/456/465/475/476, as of MY 05 - 08 Model 211.026/056/065/070/07...087/256/265/276/282/287, as of MY 04 - 08 Model 219.375/376, as of MY 06 - 08, Model 251.165/175, as of MY 06 Equipped with iPod Interface Kit
Feb 12, 2009	S-B-82.85/544a	iPod Intermittently Cannot Be Operated or Controlled Using Steering Wheel Controls, Delayed Response on Instrument Cluster Display, iPod Volume Too Low Compared to Other Audio Sources All Models Equipped with Engine M272 and M273
Feb 11, 2009	S-B-54.21/215	Engine Cannot Be Started When Engine is Hot but Will Start After Engine has Cooled MY-All, Models All
Feb 05, 2009	S-B-67.00/25	New Window Glazing One-Component Adhesive Repair Kit MY-All, Models All
Feb 05, 2009	S-B-40.10/66	Approved Alkaline MB Wheel Cleaner for Light Alloy Disk Wheel Revision: Remedy Revised, All Models Equipped with Diesel Engines
Feb 04, 2009	S-B-47.20/48b	Check Engine Lamp Illuminated and Engine Will Not Start or Stalls After Starting at Low Ambient Temperatures (-15 C / 5 F) Models 164, 171, 203, 209, 211, 215, 216, 219, 220, 221, 230, 251 with code 213 (Speed Sensitive Power Steering - Parameter Steering)

Feb 04, 2009	S-B-46.50/34a	Speed Sensitive Power Steering (Parameter Steering) Malfunction MY-All, Models All with Engine 272 with Transmission 722.6/9, Engine 273 with Transmission 722.9, Engine 272 with Transmission 722.6
Jan 29, 2009	S-B-03.30/11	Flywheel/Flexplate Replacement Procedure MY-2001 - Present Models All (With Tire Pressure Monitoring System)
Jan 29, 2009	S-B-40.15/65	Steel Valve Caps on Vehicles with Tire Pressure Monitoring Systems MY-All, Models 164, 171, 199, 203, 204, 209, 211, 216, 219, 221, 230, 251, and 463
Jan 28, 2009	S-B-54.10/213	Battery Maintenance Revision: Note Added / Warranty Table Removed All Model 164 and 251 Vehicles
Jan 28, 2009	T-B-83.00/124a	No Air from Rear Center Outlets in Heating Mode Model 164, 204 and 251 Vehicles, as of Model Year 2007
Jan 28, 2009	T-B-82.60/676	Diagnostic Enhancement: Rear Seat Entertainment System (RSE) Diagnostic Assistance Center "EDAC" Distribution Notice, MY-All, Models All,
Jan 27, 2009	S-B-99.00/340	Technical Data Manual for Passenger Cars, Edition 2008/2009 Revision: Correct Pinout for 251 Model 164.122/125/172/175/177/186 Model 251.122/156/165/175/177
Jan 23, 2009	T-B-82.10/632b	Stop/Tail Light not Illuminating with 9102, 9103, 9106, 9107, 9126, 9127 or 9136 Recall: Models 164/164.8/251, Model Year 2008
Jan 21, 2009	2008120011	Replace Power Steering Rack (Approximately 577 vehicles are involved.) Model 164.125/825, Model 251.125
Jan 20, 2009	T-B-14.40/27	Dosing Valve and Heated Line Model 164.122/822, Model 211.022, Model 251.122
Jan 20, 2009	S-B-83.55/126	No Cooling Output / Refrigerant Compressor Malfunctioning Revision: Note Added - Page 2 (mounting post) Model 164.122/172/175/177/186/822/871/886, as of VIN A298504 up to VIN A407859 Model 251.122/156/165 as of VIN A062281 up to VIN A083326
Jan 16, 2009	T-B-72.00/100c	Equipped with Keyless Go (SA Code 889) Outside Door Handle No Longer Returns to End Position Model 251.122/125/156/165/175/177
Jan 13, 2009	T-B-68.20/77	Center Console Storage Compartment Crash Lock Triggered and Cannot be Unlocked All Model 164 / 203 / 209 Vehicles, as of Model Year 2005 All Model 171 / 251 Vehicles, as of Model Year 2006 All Model 204 Vehicles, as of Model Year 2008 All Model 211 Vehicles, as of Model Year 2004, Equipped with COMAND (528 or 530) All Model 216 / 219 / 221 / 463 Vehicles, as of Model Year 2007 Equipped with iPod Interface System or Media Interface System (Option Code 518)
Jan 07, 2009 Jan 05, 2009 2008	S-B-82.60/629a S-B-80.00/53	Various iPod Issues: iPod Battery Discharge, No Data Display, Slow Reaction When Listening to Audio Books MY-All, Models All, Replace Battery in Transmitter Key Revision: Applicable Models Expanded (all Passenger and Light Trucks) All Passenger and Light Truck Models Garage Door Opener Cannot be Programmed Revision: Applicable Models Revised (BlueTEC Vehicles Only) as of January 5, 2009 Model 164.125/825, Model 251.125 Equipped with OM642 Engine with BlueTEC Selective Catalytic Reduction (SCR) System
Dec 19, 2008	S-B-68.05/47a	Diagnostic Enhancement: OM642 Diesel Enhanced Diagnostic Assistance Center "EDAC" Revision: Production Cut-off Added to First Paragraph All 164, 171, 203, 209 and 251 Vehicles, Equipped with Memory Seats (Code 275) All 211, 219 and 230 Vehicles
Dec 19, 2008	P-B-07.11/64g	Easy Entry/Exit Feature for Seat Position Not Functioning Revision: Warranty Information Updated All Models Equipped with 722.9 (7G-Tronic) Transmission
Dec 16, 2008	S-B-91.10/125c	Transmission in Limp Home Mode Revision: Applicable Models Updated
Dec 16, 2008	S-B-27.00/102b	Model 164.175/186, Fuel Filler Flap Loose
Dec 09, 2008	T-B-63.50/09a	

Dec 05, 2008	S-B-46.20/46a	<p>MY-All, Models 163, 164, 171, 203, 204, 209, 210, 211.... 221, 230, 251 Play in the Rack and Pinion Steering System Revision: Applicable Models Updated (251 Added) Model 164.122/172/175/177/186/822/866/871 Model 251.122/125/156/165/175/177</p>
Dec 04, 2008	T-B-62.25/09b	<p>Water Sloshing Noise Under Instrument Panel</p> <p>All Model Vehicles Equipped with 722.9 Transmission- 7G-Tronic (NAG2)</p>
Dec 04, 2008	S-B-27.00/112	<p>Hard 1-2 Shift and/or Hard Torque Converter Lockup Clutch Engagement</p> <p>MY-All, Models 164, 171, 203, 204, 209, 211, 216, 219, 221, 230, 251, and 463 (with Engine 272 or 273)</p>
Dec 02, 2008	S-B-09.10/30	<p>Installing Air Filters Revision: Parts and Warranty Information Updated All Model 164 and 251</p>
Dec 02, 2008	T-B-46.10/39c	<p>Chrome Plating Peeling on Decorative Caps on the Steering Wheel Spokes Revision: Content Updated, WIS Doc. Reference Included All Model 164 / 251 Vehicles</p>
Dec 02, 2008	T-B-46.10/32g	<p>Groaning/Cracking Noise When Steering Revision: Applicable Models Updated (Page 2 Chart)</p>
Nov 26, 2008	S-B-46.30/40b	<p>All Passenger and Light Truck Models, Flow Noises from Area of Power Steering Pump and/or Foaming of Power Steering Oil in Reservoir</p> <p>Model 164.122/172/175/177/186/822/871/886, MY 2006 - 2008 Model 171.454/456/473, MY 2005 - 2008</p> <p>All Model 203 Vehicles, MY 2005 - 2008 (Except 203.065 and 203.747) All Model 209 Vehicles, MY 2005 - 2009</p> <p>All Model 211 Vehicles, MY 2004 - 2008 with COMAND Head Unit (528 or 530) Model 216.371/376/377/379, MY 2007 - 2009 Model 219.372/377 2006 - 2008 Model 221.171/176/179/186/177 MY 2007 - 2009</p> <p>Model 230.470/471/472/474/475/476/477/479 MY 2005 - 2008 Model 251.122/156/165/175/177 MY 2006 - 2008 Model 463.249/271, MY 2007 - 2008</p>
Nov 24, 2008	S-B-82.70/666	<p>Apple iPhone or iPhone 3G Address Book Not Loading In vehicles Equipped With Hands-free Telephone and Blue Tooth Cradle (HFP-Puck)</p> <p>Model 164.122/172/175/177/186/822/871/886, as of MY 2006 Model 171.454/456/473, as of MY 2006</p> <p>Model 203.040/052/054/056/061/064/076/....264/281/284/740/764, as of MY 2005 Model 204.054/056/081, as of MY 2008</p> <p>Model 209.356/365/372/375/376/377/456/465/472/475/476/477, as of MY 2005</p> <p>Model 211.022/026/0...283/287 as of MY 2003 with COMAND Head Unit (528 or 530) Model 216.371/376/377/379, as of MY 2007 Model 219.372/377, as of MY 2007 Model 221.171/176/177/179/186, as of MY 2007 Model 251.122/156/165/175/177, as of MY 2006 Model 463.249/271, as of MY 2007</p>
Nov 24, 2008	S-B-82.60/643	<p>Equipped with iPod Interface System or Media Interface System (Option Code 518) Apple iPhone 3G or Newer iPod Generations Not Charging Model 164.122/172/175/177/186</p>
Nov 24, 2008	S-B-82.10/642	<p>All Model 211 Vehicles, as of Model Year 2007 Xenon Burner Inoperative or Flickers</p>
Nov 21, 2008	2008110009	<p>Service Campaign: Models 164, 164.8, 251, Model Year 2008 Update Rear SAM Software</p> <p>Revision: Applicable Models Updated (Added 230 Equipped with M113 Engine)</p> <p>All Model 163, 203, 209, 211 and 220, Equipped with M112 Engine</p> <p>All Model 163, 164, 171, 203, 209, 211, 215, 219, 220, 230 and 251, with M113 Engine</p> <p>All Model 164, 171, 203, 209, 211 and 251 Equipped with M272 Engine</p> <p>All Model 164, 209, 211, 216, 219, 221 and 251 Equipped with M273 Engine All Model 164 and 251, Equipped with M272/273 Engine</p>

		All Model 164, 211 and 251, Equipped with OM642 Engine All Model Years
Nov 20, 2008	S-B-83.55/87e	Replacement of Refrigerant Compressor Belt Pulley Due to Noise Complaints Revision: Content Revised, Software CD Part Numbers Included Model 164.122/125/172/175/177/186, Model Year 2009 Model 171.454/456/458/473, Model Year 2008 and 2009 Model 211.022/056/072/077/087/090/277/287, Model Year 2008 and 2009 Model 216.371/376/377/379/386, Model Year 2008 and 2009 Model 219.372/377, Model Year 2008 and 2009 Model 221.171/176/177/179/186, Model Year 2008 and 2009 Model 230.470/471/472/477/479, Model Year 2009 Model 251.125/156/165, Model Year 2009, Model 463.237/271, Model Year 2009
Nov 20, 2008	S-B-82.60/640a	Equipped with COMAND Head Unit and Satellite Radio System COMAND Software Update Required to Subscribe to Additional SIRIUS XM Channels Revision: Complete Procedure Revised
Nov 20, 2008	S-B-27.60/61j	All Models Equipped with 7G-Tronic Transmission (NAG2) Uncomfortable Shift Quality of 1-2, 3-2 and 2-1 Gear Shifts Revision: Applicable Models Updated Model 164.122/125/172/175/177/186/822/825/871/886 Model 251.122/125/156/165/175/177
Nov 20, 2008	T-B-88.70/62a	Equipped with SA Code 500 (Electric Folding Outside Mirrors) Electric Folding for the Exterior Mirrors Not Functioning Installation Bulletin Supplemental SCN and Variant Coding for COMAND/RSE MY2009, Model 251 and Model 164 with Option Code 866 RSE Pre-Wiring
Nov 19, 2008	SCN coding	Supplemental SCN and Variant Coding for COMAND and Rear Seat Entertainment System for WIS documents Revision: Production Cut-Off Added
Nov 19, 2008	S-B-54.35/193a	All Passenger and Light Truck Models Up to April 2008 Production Replacing the Fanfare Horns Revision: Note on Page 2 Updated (Ignition Coil Statement) Model 129.068, Model 163.154/157/172/175, Model 164.172/175/186/871/886 [...], Model 251.156/165/175, Model 463.249
Nov 19, 2008	S-B-07.61/72a	Diagnosis in DAS for Misfire Fault Codes Revision: Condition 2 Revised All Model 204, 164 and 251 Vehicles
Nov 18, 2008	S-B-72.00/42g	Door Seal Loose or Wind Noise from Door Model 164.122/175/177/186/822/871/886
Nov 14, 2008	T-B-27.00/111	Throttle Lift-Off Clunking Noise In Vehicle Speed Range Up To Approx. 50 MPH Revision: Parts Note Added Model 163.154/157/172/174/175, Model 164.175/186, Model 170.465/466 [...], Model 251.156/165, Model 463.246/249/271, All Model Years
Nov 11, 2008	S-B-14.30/15e	Check Engine Light with DTC P2003, P2047, P0810 and P0814 Stored in Engine ECU Service Campaign: Model 251 with Engine OM 642, Model Year 2008
Nov 07, 2008	2008100007	Install Exhaust Bracket Reinforcement at Transmission Revision: Content Revised
Nov 06, 2008	S-B-07.00/84a	All Models, Equipped with Engine M156, M272 and M273 Software Flash Requirements for ME 9.7 Control Units Revision: Technical Content Updated (Condition VIII Added) Model 164.122/172/175/177/186/822/886 Model 203.040/052/054/056/061/064/065....1/284/740/747/764 Model 209.356/365/372/375/376/377/456/465/472/475/476/477 Model 211.026/056/065/070/076/082/083/087/256/265/276/282/283/287 Model 219.375/376, Model 251.122/156/165/175/177
Nov 05, 2008	S-B-91.10/112e	Front Seat Noise Complaints
Nov 04, 2008	S-B-27.00/109	All Models Equipped with Transmission 722.9- 7G-Tronic (NAG2), Model Year 2009 Delayed Engagement of Reverse Gear All Model 164, 204, 209, 211, 219, 221 and 251 Vehicles
Nov 04, 2008	S-B-91.16/179	Active Head Restraints Cannot be Reset Installation Bulletins, MY2009

Nov 03, 2008	AN82.60-P-0013RT	<p>Model 251 with Code 866 (Preinstallation for Rear Entertainment System) Retrofit for Rear Entertainment System</p> <p>Revision: Note Removed (pertaining to Airmatic Control Module) / Part Number Updated</p>
Nov 03, 2008	T-B-32.22/66c	<p>Model 164.122/172/175/177/186/822/871/886, Up to VIN A331395 Thumping Noises from Area of Front Axle on Rough Roads Revision: Damage Code Revised Model 164.175/186</p> <p>Model Year 2006, Equipped with Rear Seat Entertainment System (RSES)</p>
Oct 30, 2008	T-B-82.60/478a	<p>No Audio Detected from Wireless Headphones, Display Will Not Power ON, Wavy or Flickering White Lines Through the LCD Display</p> <p>Revision: Applicable Models Updated (Model 164.871 Removed) Model 164.186, Up to Engine Serial No. 272 967 30 053879</p> <p>Model 171.454/456, Up to Engine Serial No. 272 9xx 30 058705</p> <p>Model 203.052/054/056/087/092, Up to Engine Serial No. 272 9xx 30 053555</p> <p>Model 209.356/456, Up to Engine Serial No. 272 9xx 30 053555</p>
Oct 30, 2008	S-B-00.00/80f	<p>Model 211.056/087/256/287, Up to Engine Serial No. 272 9xx 30 052208 Increased Engine Oil Consumption</p> <p>Revision: Parts Quantities Corrected to Match Information in Table / Note Added</p>
Oct 30, 2008	S-B-82.10/598a	<p>All Model 163, 164, 171, 203, 209, 211, 215, 219, 220, 230 and 251 Vehicles Replacing Exterior Light Bulbs Revision: Damage Code Revised</p>
Oct 28, 2008	T-B-80.20/45a	<p>Model 164.122/175/177/186/822/871 with SA Code 890 (Power Liftgate) Model 251.122/165/175/177 with SA Code 890 Power Liftgate Nonfunctional</p> <p>Model 163, 164, 170, 171, 203, 204, 209, 211, 215, 216, 219, 220, 221, 230, 251 and 463</p>
Oct 28, 2008	S-B-18.00/40	<p>AMG Vehicles, Equipped with Engine 112.96x, 113.98x, 113.99x, 156.98x or 275.98x Oil Consumption</p> <p>Revision: Work Instr. Pertaining to Spacer Revised / Diagram Included All Passenger and Light Truck Models</p> <p>Equipped with Engine M272 Up to Engine Number 272xxx 30 476520</p>
Oct 27, 2008	S-B-13.22/01e	<p>Equipped with Engine M273 Up to Engine Number 273xxx 30 085890 Noise Coming From Front of Engine Revision: Damage Type Revised - Step 7</p>
Oct 24, 2008	S-B-18.00/37d	<p>All Passenger and Light Truck Models Equipped with M156, M272, M273 or OM642 Engines Low Oil Level Symptoms</p> <p>Model 211.022, Model 164.122/822, Model 251.122, Equipped with Engine OM642</p>
Oct 22, 2008	S-B-03.20/10	<p>Intermittent Knocking/Ticking Noise at Idle (with mp3 sound file to help diagnosis) Revision: Added Mobile Training Coach Link</p>
Oct 20, 2008	T-B-72.20/68a	<p>Model 164.871, Up to VIN A126315 with Code 890 (Power Tailgate) Power Tailgate Does Not Function Correctly Revision: Warranty Information Updated Model 251.122/156/165/175/177, Up to VIN A062280</p>
Oct 20, 2008	T-B-72.10/95a	<p>Equipped with Infrared Reflecting Glass (Code 596) Laminated Side Window Glass Cracked</p>
Oct 17, 2008	T-B-83.00/123	<p>All Model 164 Vehicles, Produced up to 11/2005 Whistling Noises from Ventilation System</p> <p>Revision: Applicable Models and Warranty Info. Updated / SDS Flashing Info. Revised Model 164.122/822, Model 211.022, Model 251.122</p>
Oct 16, 2008	S-B-27.00/107a	<p>Uncomfortable Shift Quality in Partial Load Ranges Affecting Upshifts 1-2, 2-3 and Downshifts 3-2, 2-1 Revision: Damage Code Revised (Model 204 Only)</p> <p>Model 164.172/186/871/886, Model 171.454/456, 203.040/052/054/056/092/087/740 Model 204.054/056/081 Model 209.356/372/456/472</p> <p>Model 211.056/072/087/090/256/287 Model 215.376/379 Model 216.371/376/379</p> <p>Model 219.372 Model 220.176/179 Model 221.171/176/179/186 Model 230.471/476/477/479 Model 251.156/165</p>

Oct 16, 2008	S-B-49.00/12a	Engine Running Characteristics / Check Engine Light Activated Model 164.122/125/172/175/177/186/822/825/871/886
Oct 16, 2008	T-B-77.20/69	Tilting/Sliding Roof Water Leakage At End Cap
Oct 15, 2008	T-B-99.00/337	Distribution Notice, Introduction into Service Manual MY2009, Engine 642.8 BlueTEC with AdBlue
		All Models, as of Model Year 2008, Equipped with Satellite Radio
Oct 14, 2008	S-B-82.60/638	Audio Interruptions/Mutes on Certain Satellite Radio Channels Model 164.122/125/172/175/177/186/822/825/871/886
		Model 251.122/125/156/165/172/175/177
Oct 09, 2008	T-B-91.16/177	Active Head Restraints Activate for No Reason Revision: Applicable Models Updated Model 164.122/125/175/177/186/822/825/871
		Model 251.122/125/165/175/177
Oct 02, 2008	T-B-27.19/56d	Automatic Transmission Remains in "P" Position Revision: Applicable Models Updated
		All Model 164 and 251 Vehicles
		All Model 211 Vehicles, MY 04 as of Production 19.2.04 and Later All Model 219, MY 07 and Later
Oct 02, 2008	S-B-91.29/117a	Replacement of Weight Sensing Seat Sensors Revision: Applicable Models Updated
		Model 164.122/125/822/825, Model 211.022, Model 251.122/125
Oct 01, 2008	S-B-47.10/43a	Diesel Fuel Requirement for MY07 and Later Diesel Powered Vehicles Revision: Applicable Models Updated
		Model 164.122/125/822/825, Model 211.022/026, Model 251.122/125
Oct 01, 2008	S-B-47.10/30d	Procedure for When Diesel Fuel Tank is Filled with Incorrect Type Fuel Revision: WIS Screenshots Added (Figures 1 and 2)
		All Passenger and Light Truck Models Equipped with FSS / FSS+ or MB Maintenance System
Sep 26, 2008	S-B-18.00/17g	Approved Service Products
		Revision to Warranty information, Repair Procedure, Parts information, and Quality
Sep 26, 2008	2008050004	Assurance Certificate, Models 164 and 164.8, Model Years 2006 - 2008 Rework Trailer Hitch
		Revision: Applicable Models Updated / Note Added on Page 2 (cause and remedy)
Sep 17, 2008	P-B-54.65/86a	All Models Equipped with Parktronic (SA Code 220) Erroneous Parktronic Activation
		Model 164.122/822, Model 251.122
Sep 17, 2008	T-B-15.20/67	COMAND System Flickers or Switches Off Briefly, Fault Codes D011 and 9011 Displayed
		All Model 164, 171, 203, 204, 209, 211, 215, 216, 219, 220, 221, 230 and 251 Vehicles Equipped with Rain/Light Sensor (SA Code 345)
Sep 16, 2008	S-B-82.30/634M	Auto On/Off Driving Lights and/or Rain/Light Sensor not Functioning Properly Installation Bulletin
Sep 10, 2008	AN82.60-P-0013GZ	MY2009, Model 164 with Code 866 (Rear Seat Entertainment System Prewiring) Retrofit for Rear Entertainment System
		Revision: Part Number Updated
Sep 03, 2008	T-B-83.10/112a	All Model 164 Vehicles, Water Entry into Vehicle Interior Revision: Note Updated
		All Model 164, 171, 203, 204, 209, 211, 219 and 251 Vehicles
Sep 02, 2008	S-B-80.57/24c	Diagnosis and Replacement of DAS3 Components (Key, EIS, ESL)
		Service Campaign: Models 164, 164.8, and 251 (with code 489)
Aug 29, 2008	2008080001	Model Years 2006-2008 Check Air Suspension Compressor and Replace if Necessary Revision: Applicable Models Updated
		Model 164.122/172/175/177/186/822/825/866, with Chrome Trim
		Model 164.871, Model 251.122/125/156/165/175/177, with Chrome Trim
Aug 28, 2008	T-72.00/66a	Corrosion Spots on Chrome Trim on Doors
		Service Campaign: Revision: Update to parts information and Work Procedure
		Model 251 with Diesel Engine OM 642, Model Years 2008 and 2009
Aug 27, 2008	2008070004	Check Coolant Line, Replace if Necessary MY- All, Models All with Transmission 722.6 or 722.9

Aug 22, 2008	S-B-00.40/89	Operating Fluid Specification Changes for Automatic Transmission (236.14) All Model 164, 171, 203, 209, 211, 215, 216, 219, 220, 221, 230, 251 and 463 Vehicles Model Year 2004 to 2008 (excluding Model 204)
Aug 21, 2008	S-B-82.60/633	WGS Pre-Authorization for Satellite Radio Receiver (SDAR) Revision: Applicable Models Updated (164.122/172/175/177/186 and all 251's Added) Model 164.122/172/175/177/186, Model 251.122/156/165/175/177
Aug 21, 2008	T-B-72.10/65a	Aluminum Trim Strip on Interior Door Panels Makes a Creaking Noise Revision: Navi DVD part numbers updated, note added, revised in parts info Models 164, 171, 203, 209, 211, 215, 219, 220, 221, 230, 251, X164 Model Year 2005-2007
Aug 20, 2008	2006110005	Install Software for Navigation System MY-All Models All
Aug 19, 2008	S-B-97.30/05	Corrosion Protection Without Hexavalent Chromium VI Model 129.066/067/068/076 Model 163.154/172/174/175/157 Model 164.175 Model 170.465/466 Model 171.473 Model 202.029 Model 203.061/064/076/081/084/261/264/281/284 Model 208.365/370/374/465/470 Model 209.365/375/376/465/475/476 Model 210.065/070/072/074/082/083/265/282 Model 211.065/070/076/082/083/265/276/282/283 Model 215.375 Model 220.067/070/083/170/173/174/175/183/184 Model 230.472/474/475 Model 251.175 Model 463.246/249/271
Aug 18, 2008	S-B-15.30/66	Tip Start Cycle Ending Prior to Engine Starting Model 251.122/125/156/165/175/177
Aug 15, 2008	T-B-77.20/65	Top Sliding Roof Roller Blind Couplings Broken At Roller Blind Service campaign, Revision: Update to warranty information Models 164, 164.8, 171, 203, 209, 211, 216, 219, 221, 230, 251 with Engine 272 or 273 Model Years 2006-2007
Aug 15, 2008	2008070002	Replace V-Belt Upper Guide Pulley Models 164.172/186/871/886 Models 251.156/165 All Model Years
Aug 14, 2008	T-B-46.25/64	Fluid Flow Noise from the Power Steering High Pressure Hose Revision: Content Added for Model 163 Vehicles
Aug 13, 2008	T-B-98.10/18b	All Model 163 and 164 Vehicles, Paint Damage on Tailgate Model 164.122/172/175/177/186//822/871/886, as of Model Year 2006 Model 251.122/156/165/175/177, as of Model Year 2006
Aug 11, 2008	T-B-82.60/631	Equipped with Dealer Installed Rear Seat Entertainment System DVD Player not Recognizing US Region DVDs (Region 1) Revision: Warranty Policy Change as of August 15, 2008 All Model 164, 171, 211, 219, 230 and 251 Vehicles, Model Year 2009
Aug 04, 2008	S-B-82.85/627a	Diagnostic Enhancement: NTG 2.5 Telematics Enhanced Diagnostic Assistance Center (EDAC) Recall: 164, 164.8, 171, 203, 204, 209, 211, 215, 216, 219, 220, 221, 230, 251, 463 Model Years 2003-2009
Jul 30, 2008	2008070001	Re-code the Software Calibration Number (SCN) Revision: Warranty Policy Change as of August 15, 2008 Model 164.122/172/175/177/186
Jul 29, 2008	T-B-54.15/190a	Diagnostic Enhancement: Rear SAM Enhanced Diagnostic Assistance Center "EDAC" Revision: Note Pertaining to S-B-82.35/621 Added
Jul 29, 2008	S-B-82.30/366d	All Passenger Models All 164 / 251 Models, Adjusting Wiper Arms Model 164.122/172/175/177/186/822/871/886 Model 211.065/070/072/076/077/082/083/087/090/256/265/276/277/282/283/287 Model 219.372/375/376/377 Model 251.122/156/165/175/177 Equipped with SA Code U10
Jul 28, 2008	S-B-91.60/171	Fault Code 9A14 Stored in Weight Sensing System (WSS) Control Module
Jul 28, 2008	T-B-68.20/76	Model 251.122/156/165, Front Armrest Storage Compartment Latches Stick Model 164.122/822 Model 251.122

Jul 16, 2008	T-B-14.40/26	Check Engine Light Illuminated / DTCs 2306-002 and 2078-002 Revision: Warranty Information Updated Model 164.177 Model 251.177 Up to Engine Type 156.98x 60005808
Jul 16, 2008	T-B-09.20/27b	Check Engine Light On / Engine Shakes at Idle with Fault Codes 0745 and 0749
Jul 10, 2008	T-B-32.22/66	Model 164.122/172/175/177/186/822/871/886, Up to VIN A331395 Thumping Noises from Area of Front Axle on Rough Roads Revision: Tar Remover Solvent Information Added
Jul 09, 2008	S-B-98.30/22a	All Passenger Car and Light Truck Models Elimination of Adhesive Residues On Paint Work Revision: Reference to WIS Document Added Model 251.122/165/175/177, Up to VIN A049476
Jul 02, 2008	T-B-33.30/23a	Rattling Noise in Area of Front Axle with Approx. 180 Degrees of Steering Wheel Input MY-All (Including MY2009), Models All
Jul 01, 2008	S-SI-58/94e / 60/04e	Dedicated Straightening Equipment for Collision Repair All Model 164, 171, 211, 216, 219, 221 and 251 Vehicles Up to October 2006 Series Production
Jun 25, 2008	S-B-00.20/88	Erroneous Maintenance Displayed Via ASSYST Revision: Note Updated Model 164.122/822, Model 211.022, Model 251.122
Jun 17, 2008	S-B-07.16/69b	Engine Does Not Start or Runs Unevenly Model 251.122/156/165/175/177, Up to VIN A062280
Jun 16, 2008	T-B-72.10/95	Equipped with Infrared Reflecting Glass (Code 596) Laminated Side Window Glass Cracked Revision: Content Revised Model 164.122/175/177/186/871, Model 251.122/165/175/177
Jun 16, 2008	T-B-72.00/73b	Door Lock Knobs Jumping Up and Down Model 164.122/172/175/177/186/822/871/886 Model 251.122/165/172/175/177
Jun 16, 2008	T-B-32.22/65	Discharge Noise from Airmatic Compressor Revision: Replacement Procedure & Applicable Models Updated All Model 124, 129, 140, 163, 164, 170, 171, 201, 202, 203, 208, 209, 210, 211, 215, 216, 219, 220, 221, 230, 251 and 463
Jun 04, 2008	S-B-32.25/19e	Replacement Procedure of Shock Absorbers and Suspension Struts Model 251.122/165/156/175/177, Up to VIN A079166
Jun 04, 2008	T-B-72.00/93	Creaking Noises in Area of Door Seal on Rough Roads Model 164.122/822, Model 211.022, Model 251.122, Equipped with Engine 642
Jun 04, 2008	S-B-09.20/29	Oil Leak at the Engine Air Intake Duct Revision: Work Procedure for Front Axle and Parts Information Updated Model 164.122/175/177/186/822/871 Model 251.122/165/175/177
Jun 04, 2008	T-B-42.10/80b	Model Year 2006 - 2007 Front / Rear Brakes Squeal When Braking Revision: Part Number Corrected Model 164.122/172/175/177/186/822/871/886, Model 251.122/156/165/175/177
May 23, 2008	T-B-33.15/34a	Grunting / Creaking Noises from Area of Front Axle Revision: Symptom and Remedy Added
May 23, 2008	T-B-91.22/152a	Model 164.822/871/886, Inoperable / Noisy Third Row Seat Motor Revision: AGA Fax and E-Mail Information Updated
May 22, 2008	S-SI-58.20/93f	All MODELS, ORIGINAL, APPROVED PROTECTIVE COVERS FOR FENDERS, SEATS, AND FRONT AND REAR FASCIA Revision A: for Model Engines
May 21, 2008	S-B-18.00/36a	MY-All, All Models with Engines 111, 112, 113, 137, 271, 272, 273, 275, 285, 642, and 648 Display and Measurement of Engine Oil Level MY-All, Models-All
May 21, 2008	S-B-82.35/621	Windshield Washer System: Maintaining Wiping Quality and Controlling Noise Revision: Symptom and Remedy Updated Model 164.175/186 Model 251.165/175
May 16, 2008	T-B-72.20/43f	Power Closing Assist on the Tailgate Intermittently Nonfunctional
May 15, 2008	S-B-49.10/11	MY-All, Models-All with Chrome Tail Pipe Finisher, The Care of Tail Pipe Finishers Model 164.822/871, up to VIN A268285, Equipped with SA code 845 (3rd Row Seat Folding Down Electrically) and SA code 847 (3rd Row Seat with Folding Individual Seats)

May 09, 2008	T-B-91.12/148	Easy Exit Strap for Second Row Seat Backrest Release Too Short Service campaign: Models 164 and 251 with Engine 156, Model Years 2007 - 2008
May 09, 2008 May 03, 2008	2008040003 S-B-40.10/60	Recode Engine Type In ASSYST (Maintenance System) Control Module MY-All, Models All, Nitrogen Use in Tire Inflation Revision: PMC Agreement (Page 3 and 4) Updated
May 02, 2008	S-B-58.30/45a	ALL MODELS, VEHICLE WHEEL ALIGNMENT EQUIPMENT COMPLIANCE Revision: Note Pertaining to Radial Play (Between Step 2 and 3) Revised All Model 164 / 251 Vehicles, Rattling / Thumping Noise on Rough Roads
Apr 22, 2008	T-B-46.20/61a	and/or Knocking Noise When Moving Steering in Both Directions
Apr 18, 2008	S-B-00.00/87	MY-All, Models All, General Overview of Documents in WIS-net and Locating Component Function Descriptions in WIS-net
Apr 15, 2008	S-B-68.30/75	All Passenger Car and Light Truck Models, Surface Damage Caused by Scent Dispenser Model 164.122/175/177/186/822/871, Model 251.122/165/175/177 Incorrect Air Distribution or Temperature Control Malfunction of LIN bus / Teach-in Process of Actuator Motors not Possible
Apr 14, 2008	T-B-83.00/117	DTC 9401, 9402, 9403, 9404, 9405, 9406, 9407, 9408, 9409, 9501, 9502, 9503 and 9505 Model 164.122, Up to VIN A277429, Model 211.022, Up to VIN B150432 Model 251.122, Up to VIN A060265
Apr 11, 2008	S-B-14.40/25	Engine Changes to Limp-Home Mode with DTC 2082-008 All Model 129, 140, 163, 164, 170, 171, 202, 203, 204, 208, 209, 210, 211, 215, 216, 220, 221, 230, 251 and 463 Vehicles
Apr 08, 2008	S-B-68.05/74	Garage Door Opener Cannot Be Programmed and/or Range is Too Short Models 164, 211, 251 with Engine 642, Model Years 2007-2008
Apr 05, 2008	S-B-01.45/21	Oil Leakage in Area of Oil Pan All 164, 171, 203, 204, 209, 211, 215, 216, 219, 220, 221, 230 and 251 Vehicles
Apr 04, 2008	S-B-83.00/116	AC Control Module / Control Functions Model 164.122/822 Model 211.022 Model 251.122
Apr 02, 2008	S-B-27.00/105	Harsh Activation of Torque Converter Lockup Clutch Model 164.122/822 Model 211.022 Model 251.122
Apr 02, 2008	S-B-27.00/104	Slow Acceleration with Gas Pedal Hesitation Revision: VIN Range Include and Remedy Amended All Model 164 Vehicles, Up to VIN A359047, All Model 251 Vehicles, Up to VIN A074553
Mar 26, 2008	T-B-88.70/72b	Equipped with Electric Folding Mirrors (SA code 500) Exterior Mirror Does Not Fold Completely In or Out All Model 164, 171, 203, 204, 209, 211, 215, 216, 219, 220, 221, 230 and 251 Vehicles
Mar 26, 2008	S-B-83.00/115	Unpleasant Odor from Air Conditioning Vents Model 164.122/172/175/177/186, Model 203.052/054/076/087/092 Model 209.356/372/377/456/472/477, Model 211.022/056/072/077/087/090/277/287 Model 219.372/377, Model 230.471/472/477/479, Model 251.122/156/165/175/177 As of Model Year 2007, Equipped with Cellular Telephone System
Mar 26, 2008	S-B-82.70/619	Driver Cannot Hear the Calling Party During a Hands-Free Call or Calling Party Volume Very Low Revision: Combination of DTBs, Model 164.186/871, Model 251.165 Equipped with M272 Engine Up to Serial No. 2729..30 468993 or M273 Engine Up to Serial No. 2739..30 088611
Mar 26, 2008	T-B-03.30/09a	Check Engine Light On / Fault Codes FC1200 / FC1208 Stored in ME-SFI Control Unit Revision: Technical Content Revised Model 164.122/175/177/186/822/871, Up to VIN A258966 Model 251.122/165/175/177, Up to VIN A058266
Mar 25, 2008 Mar 24, 2008	T-B-91.10/132a S-B-91.18/151	Head Restraint and/or Seat Adjustment Nonfunctional and/or SRS Illuminated All Passenger and Light Truck Models, Dirty Seats
Mar 24, 2008	T-B-91.12/149	All Model 251 Vehicles, Cracking Noises from Second Row Seat Backrest Model 164.122/172/175/177/186/822/871/886

		Except Vehicles Equipped with the Off-Road Package (SA code 430)
Mar 24, 2008	T-B-68.10/73	Storage Compartment in Center Console Does Not Open / Sticks Revision: Combination of DTBs, All Model 163/164 and 251 Vehicles
Mar 14, 2008	T-B-46.00/50a	Conditions Concerning the Steering System MODELS 164, 171, 203, 204, 209, 211, 215, 216, 219, 220, 221, 230, 251, 463
Mar 12, 2008	S-B-82.60/617	Satellite Radio General Activation Information Revision: Combination of DTBs, Model 164.122/186/822/871 Model 251.165
Mar 11, 2008	T-B-15.40/61a	Returning Alternators and Regulators Equipped with BSS or LIN Communication Customer 1 Action: Models 164, 164.8, 171, 204, 209, 211, 216, 219, 221, 230, 251, 463
Mar 07, 2008	C1A 080301	Model Year 2008 Digital Tele Aid Reprogramming Models 129, 140, 163, 164, 170, 171, 199, 202, 203, 204, 208, 209, 210, 211, 215,
Mar 03, 2008	S-B-46.25/37a	216, 219, 220, 221, 230, 251, 463, Processing of Steering System Complaints
Feb 22, 2008	T-B-97.00/04	All Model 164 / 251 Vehicles, Replacement Parts with Seam Seal Model 163.154/157/172/174/175 164.172/175/186/871/886 251.156/165/175 + others
Feb 12, 2008	S-B-46.30/21a	Noise from the Area of the Steering System / Power Steering Pump
Feb 08, 2008	S-B-40.10/18a	All Models, Chrome Plating of Mercedes-Benz Light Alloy Wheels Recall: Models 164, 164.8, 211, 251 with Diesel Engine OM 642 Model Years 2006 - 2008
Feb 01, 2008	2008010005	Replace Crankshaft Position Sensor Model 164.122/172/175/177/186/822/871/886, as of MY 2006 Model 251.122/156/165/175/177, as of MY 2006 Equipped with Option Code 819
Feb 01, 2008	T-B-82.64/608	CD Changer Cannot Be Operated / CDs Not Drawn In or Ejected, Jumps, Skips or Sets Over Temperature Fault Codes Revision: Document Discontinued Model 164 Model 251, As of MY 07 Equipped with Navigation System Code 530
Jan 15, 2008	T-B-82.85/593d	Navigation Database Update At Pre-Delivery Inspection Revision: Reference to Figure Revised Model 164 with code 489 (Airmatic suspension) Model 251
Jan 15, 2008	T-B-32.22/50a	Airmatic Inoperative / "Visit Workshop" Displayed in Instrument Cluster Revision: New Cause and Remedy Added Model 164 Model 251 Model Year 2006 with Option Code 810 (Sound Amplifier)
Jan 11, 2008	T-B-82.62/594a	Audio Not Available During Start Up or Sound Amplifier Not Visible During Quick Test
Jan 09, 2008	T-B-80.57/47	All Model 164 and 251 Vehicles, Diagnosis and Replacement of DAS3 Components Model 164.177 Model 251.177
Jan 09, 2008	T-B-14.30/24	Check Engine Lamp Illuminated / DTC Codes 0817 or 0821 Model 164.175/186 Model 251.165/175 Model Year 2006 (SA code 806)
Jan 07, 2008	T-B-82.30/583a	Rear Window Wiper Fails to Function or Stops Intermittently All Model 164 Vehicles Equipped with Sales Code 477 - Tire Loss Warning System (indirect ESP based) with Run Flat Tires, Model Year 2005 to 2007
Jan 03, 2008	T-B-42.45/87	"Tire Pressure Monitoring Inactive" Displayed in Instrument Cluster Model 164.871, Up to and Including VIN A150065
Jan 03, 2008 2007	T-B-14.30/20b	Check Engine Light On / Fault Codes 0810, 0814 (P0410) Stored in Engine ECU
Dec 26, 2007	T-B-83.00/93	Model 164.122/175/177/186/822/871, Reduced Climate System Performance Service Campaign Models 164, 164.8, 251 Model Years 2007 - 2008
Nov 30, 2007	2007110002	Install Rear Entertainment Software
Nov 12, 2007	T-B-54.15/190	Model 164.122/172/175/177/186 Rear SAM Enhanced Diagnostic Assistance Center Model 164.122/172/175/177/186/822/871/886, Up to VIN A258996 Model 251.122/156/165/175/177, Up to VIN A058266
Nov 09, 2007	T-B-72.12/87	Knocking Noise in Rear Door When Operating Power Window Service campaign. Models 211, 164, 164.8, 251, with OM 642 MY 2006 - 2007

Nov 02, 2007	2007100003	Update Engine Control Module Software, about 200 affected
Oct 26, 2007	T-B-42.45/82	Model 164.175, Up to VIN A038732 ESP Visit Workshop Displayed in Instrument Cluster Model 164.122/175/177/186/822/871/886 Model 251.122/165/175/177
Oct 17, 2007	T-B-91.60/93g	Restraints - SRS Lamp ON and or DTC's 9200 and or 9210 Set Model 164 VIN Range A249659 to A315197 Model 251 VIN Range A057022 to A064910 Model Year 2008 Equipped with Option Code 864 (Rear Seat Entertainment)
Oct 05, 2007	T-B-82.60/596	Rear Seat Entertainment Systems Displays Do Not Power On, No Picture or Completely Inop Recall: Model X164 (GL320 CDI) Model Year 2007
Oct 01, 2007	2007080003	Replace Charge Air Hoses (OM642 Engine) Model 164.122/822, Model 251.122 (turbo Diesels)
Sep 28, 2007	T-B-27.60/99a	Automatic Transmission Occasionally Shifts Too Late or Does Not Shift Up Model 164.172/186/871/886 Model 251.156/165
Sep 28, 2007	T-B-07.61/79	Check Engine Light Illuminated / Fault Code P0217 Stored in Engine Control Unit Service Campaign: Models 164, 164.8, 251 (with mechanical mirrors) Model Years 2006-2007
Sep 28, 2007	2007090001	Lubricate Folding Mechanism of Right and Left Outside Mirrors with A000 989 3860
Sep 24, 2007	T-B-83.00/98b	All Light Truck Models, Air Conditioning Not Cooling, Leak Test Using Fluorescent Dye Service Campaign: Model 164 Model Year 2006
Sep 18, 2007	2007070002	Rework Stainless Steel Under-Ride Guards on Front and Rear Bumpers
Sep 10, 2007	T-B-47.20/52	MY-All Models 164, 251 Procedure for Replacing Fuel Pump and Fuel Filter Modules Model 164.871, Equipped with ORP Code 430 to June 2006 Production, VIN A152125
Sep 10, 2007	T-B-28.60/08	Message Low Range Service Required with DTC 2950 Stored in Transfer Case Control Module Model 164.122/822 Model 251.122
Sep 04, 2007	T-B-07.16/77	Leaking High Pressure Fuel Pump / Possible Fuel Loss / Odor
Aug 28, 2007	T-B-83.00/106	Model 164 Model 251 AC Compressor Not Operating at Cold Temperatures MY All Models All With Transmissions 722.4/5/6/9
Aug 21, 2007	S-B-27.00/101	Do Not Operate the Accelerator Pedal and Brake Pedal Simultaneously Model 164.122/822 Model 251.122
Aug 20, 2007	T-B-14.20/22	Engine Changes to Limp-Home Mode and/or Has Insufficient Power Models 164/ 203/ 209/ 211/ 216/ 219/ 221/ 251 Model Year-All
Aug 17, 2007	S-B-68.00/54b	One-Time Use of Expansion Rivet with Sealing Function Reusing expansion rivets may cause water leakage Technical Literature Announcement, Electrical Troubleshooting Manual,
Aug 15, 2007	T-B-99.00/326	Starting Model Year 2006, Model 251, Volume 1 & 2, Supplement 1 released
Aug 14, 2007	S-B-07.16/68	MY-ALL, Models 164, 164X, 211, 251 with Engines 642, 648, Notes On Diesel Engines All Model 164/ 251 Vehicles, As of Model Year 08 (SA code 808) and
Aug 9, 2007	T-B-82.15/691	Headlamp Washing System (SA code 600): Headlamp Washer Switch
Aug 7, 2007	T-B-83.40/77a	Climate System Temperature Too Cold or Too Warm Compared to Panel Setting
Aug 1, 2007	T-B-97.00/02	MY-All Models 163, 164, 251 Introduction of Replacement Parts with Seam Sealant
Aug 1, 2007	S-B-91.00/37	Model Year - All Models All Repairs for Noise Complaints Regarding Seats
Jul 25, 2007	T-B-47.25/45	Model 164.177, Up to VIN A185373 Engine Ticking Noise at Idle Equipped with Engine M112 / M113 / M272 or M273
Jul 19, 2007 Jun 27, 2007	T-B-07.61/75 T-B-91.60/135	Diagnosis in DAS for Purge System Codes / Check Engine Light Illuminated Model 164.122/175/177/186 SRS Initial Startup Faults MY-All Models 164, 216, 221, 251 and Model 211 as of January 2007
Jun 26, 2007	S-B-33.20/27	Disassembling of Ball Joints with Race Star Service Manual on DVD for R-Class (W251) released: part number P-2700-251-07
Jun 21, 2007	S-B-99.00/222L	includes OM642 diesel engine info
Jun 21, 2007	T-B-46.20/58	All 163, 164 and 251 Models Equipped with Rack-and-Pinion Steering

Jun 18, 2007	T-B-82.35/588	Model 164.122/175/177/186/822/871, Model 251.122/165/175/177 Washer Fluid Level Sensor Not Functioning Correctly All Model 164 and 251 Vehicles, Model Year 2006 through 2007
Jun 14, 2007	T-B-83.00/104	Vehicle Heating, Ventilation, Air Conditioning (HVAC) Manual available for troubleshooting Model 164.122/175/177/186/822/871, as of Model Year 2006 Up To VIN A213513 Model 251.122/165/175/177, as of Model Year 2006 Up To VIN A051176
Jun 12, 2007	T-B-82.60/582	Equipped with Option Code 864 (Rear Seat Entertainment System) Service Campaign: Models 164, 209, 211, 219, 251 AMG Model Year 2007
Jun 8, 2007	2007020004	Install Support for Intake Manifold Switchover Flap (M156 Engine) Service Campaign: Model 164.177 AMG, Model Year 2007
Jun 1, 2007	2007040007	Replace Left Engine Oil Line (M156 Engine) Model 164.122/175/177/186/822/871 Model 251.122/165/175/177 Model Year 2007
May 22, 2007	T-B-91.60/134	SRS High Resistance for Side Airbag / DTC 9290 and/or 92A0: replace squid connector All Model 164 and 251 Vehicles, Work on Electrical Connectors: Disconnect battery only when needed Test and Inspection of Charging System Regulator
May 22, 2007	T-B-54.18/185	
May 22, 2007	S-B-15.40/58a	When alternator fails test/replace failed regulator instead of replacing alternator
May 21, 2007	T-B-88.70/49a	All Light Truck Models, Moisture in Additional Turn Signal Lamp(s) in Rearview Mirrors Model 164.122/175/177/186 Model 251.122/165/175/177 Model Year 2006
May 14, 2007	T-B-72.20/43d	Power Closing Assist on the Tailgate Intermittently Nonfunctional
May 8, 2007	T-B-83.30/91b	All Model 164 and 251 Vehicles, Air Conditioning Musty/Moldy Odor Complaints Model 164 Noises at the Instrument Panel
May 7, 2007	T-B-68.10/67	Describes how to remove 4 different noises if present on instrument panel All Model 164 / 251 and 463 Model Year 2004 to 2007
Apr 27, 2007	P-B-82.60/426b	Diagnostic Enhancement: Satellite Radio (SDARS) Enhanced Diagnostic Assistance Service campaign: Models 164, 211, 251, X164, Model Year 2007
Apr 27, 2007	2007040003	Replace Engine Oil Filler Neck Seal (OM642 Engine) Revised Instruction for Siemens Systems
Apr 18, 2007 Apr 17, 2007	T-B-40.15/56b T-B-88.20/63	All Light Truck Models with Tire Pressure Control, Tire Pressure Control (TPC) Repairs Corrosion of Mercedes Star in Distronic Plate Up to June 30, 2005 Production Date, VIN Range A000826 to A026114
Apr 10, 2007	T-B-41.10/03a	Vibration at Front Driveshaft While Driving at Highway Speeds Campaign: Model X164 (GL) Model Year 2007
Mar 30, 2007	2007020007	MB determined affected vehicles had no roof crossbars All Light Truck Vehicles Equipped with Transmission 722.9
Mar 29, 2007	T-B-27.00/96	Trans. in Limp-Home Mode or Harsh Engagement After Programming / SCN Coding Revision: Applicable Models Updated All Light Truck Models Equipped with 7G-Tronic (722.9) Transmission
Mar 28, 2007	T-B-27.60/65a	Learning in Selection Range Sensor Not Possible After EHS Replacement All Light Truck Models Equipped with 7G-Tronic (722.9) Transmission No Transfer of Power from Transmission Installing Electric Trailer Brake Controller
Mar 28, 2007 Mar 9, 2007	T-B-27.35/97 T-B-31.19/07d	
Mar 5, 2007	T-B-83.30/91a	All 164/251, Air Conditioning Musty/Moldy Odor Complaints: Use MB Contra Sept cleaner
Mar 2, 2007 Mar 1, 2007	2007010004 T-B-82.85/545	Campaign: X164, Check Intake Manifold and Replace if Necessary, update M273 software Model 164/251 as of MY 06 Equipped with iPod Interface Kit
Feb 26, 2007	T-B-18.40/30b	Warranty info updated: Leakage Between Oil Level Sensor and Oil Pan
Feb 20, 2007	2007010001	Campaign: MY2007 AMG: Replace Poly V-Belt and Tensioner (M156 Engine)
Feb 13, 2007	T-B-30.16/64a	Revision: Testing of Throttle Valve Sensor, M113 ME2.8, M272/273 engines
Feb 10, 2007	T-I-82.70/571	Preliminary draft: Voice control installation MY2007 Model GL450 (up to VIN A150126)

Feb 9, 2007	T-B-83.00/89	Climate System Temperature Setting Not Possible/LED Indicator wont Change: update SW
Feb 9, 2007	T-B-27.60/93	722.9 (7G-Tronic) Adaptation Values of the 6-5 Downshift Close to the Negative Limit
Feb 9, 2007	2007010008	Campaign - MY2007 Check/update 722.9 transmission software Update M273 SW if required
Feb 6, 2007	T-B-07.00/53c	Engines M113 (ME2.8) M156, M272, M273 Control Unit: all returned units will be tested
Feb 5, 2007	T-B-40.15/57	Display "Tire Pressure Monitor Unavailable" and Fault Lamp Flashes: fuel pump interferes
Feb 5, 2007	T-B-46.10/39a	Chrome Plating Peeling on Decorative Caps on the Steering Wheel Spokes: replace caps
Feb 5, 2007	T-B-98.10/18	Paint Blistering / Loss of Adhesion on Liftgate: strip and refinish
Feb 2, 2007	T-B-72.00/76	Model 251 Up to VIN A051018 Interior Door Handle Noises: apply spray 000 989 3560
Feb 1, 2007	T-B-83.00/81	Malfunctions of Various Control Units and/or On-Board Power Supply Problems: moisture
Feb 1, 2007	T-B-54.65/182	Parktronic Triggers Without Obvious Cause at Front Bumper Due to License Plate Width
Jan 31, 2007 Jan 12, 2007 Jan 10, 2007 Jan 10, 2007	T-B-82.00/261b 2006120008A T-72.20/43C T-18.00/33A	MY2000 through current model year, light trucks: CDs and DVDs May Not Be Ejected Recall - Accelerator Pedal Mounting Body - Power Tailgate Closing Assist Intermittently Inop Engine - Oil Level is Too Low
Jan 4, 2007 Jan 4, 2007 2006 Dec 12, 2006 Dec 1, 2006 Dec 1, 2006 Nov 29, 2006 Nov 29, 2006 Nov 29, 2006 Nov 28, 2006 Nov 27, 2006 Nov 27, 2006 Nov 27, 2006 Nov 27, 2006 Nov 22, 2006 Nov 7, 2006 Nov 7, 2006 Nov 7, 2006 Nov 6, 2006 Oct 31, 2006 Oct 27, 2006 Oct 27, 2006 Oct 26, 2006 Oct 24, 2006 Oct 19, 2006 Oct 12, 2006 Oct 2, 2006 Oct 2, 2006 Sep 27, 2006 Sep 27, 2006 Sep 13, 2006 Sep 1, 2006 Aug 30, 2006 Aug 29, 2006 Aug 29, 2006 Aug 15, 2006 Aug 1, 2006 Aug 1, 2006 Aug 1, 2006 Jul 21, 2006 Jul 20, 2006 Jul 19, 2006 Jul 14, 2006	S-B-99.00/222J T-05.20/21 T-72.12/69 2006110005B 2006120004 T-88.70/56 T-88.79/57 P-82.85/532A T-15.40/61 T-32.22/45 T-54.30/180 T-27.60/89 T-B-27.60/62e 2006110005A T-27.60/68E T-32.22/44 T-72.10/72 T-09.20/27 T-46.10/48 T-27.60/68D 2006060005A S-27.56/83 S-27.19/82 2006100003 T-91.40/129 T-91.60/122 T-83.10/80A T-82.60/456B T-47.00/41 S-68.00/54 2006090001 T-27.60/81 T-67.39/21 T-91.30/103A T-27.60/55B 2006060005 2006080003 S-67.00/20 T-46.00/45 2006040002 T-82.60/508 T-27.60/62D	Engine - Sporadic Noise On Warm Start Up Body - Stone Chips in Area of Rear Doors Campaign - Install Software for Navigation System Campaign - Replace Trailer Hitch Body - Creaking Noise When Mirrors Folded Out Body - Exterior Mirror Cannot Be Adjusted Diagnostic Enhancement - MCSII EDAC Charging System - Returning Alternators & Regulators Suspension - Cracking, Knocking or Thumping Noises Instruments - After SCN Coding IC Shows No Menus Transmission - 722.9 - Fault Codes 2502, 2505, P0894 or P2711 Equipped with 7G-Tronic Transmission (NAG2) Rough Shift Quality: Readapt, SW upgrade, check circlip Campaign - Navigation DVD Update Auto Trans - Uncomfortable 2-1 Coastdown Downshift Traction Control - Acceleration Sensor Elimination Body - Wind Noise From Upper Rear of Front Door Engine - Shakes at Idle and or MIL ON and or Codes 0745 and or 0749 Steering Wheel - Multi-Function Buttons Inoperative Auto Trans - Uncomfortable 2-1 Downshift When Coasting and or Braking Campaign - Exhaust System Modification Transmission - Filter Part Number and or Replacement Information; pan magnets Auto Trans - Electrohydraulic Control Unit Part Numbers Campaign - Starter Wiring Harness routing Restraints - 'PRE-SAFE Not Available' Message Displayed Restraints - SRS Lamp ON and or Codes 90C6 and or 90D6 and or 90E6 & 90F6 Air Conditioning - Water Leaks Into The Interior Entertainment System - iPod(R) Interface Errors Instruments - Fuel Gauge Drops To 'EMPTY' Restraints - Poor Rear Seat Belt Fit and or Head Restraint Inop Campaign - Sluggish Auto Trans Shifting Engine, Auto Trans Controls - DTC 061B After Reprogramming Body - Rear Window Express Feature Inoperative Interior - Front Seat Heaters Inoperative Transmission - Noises When Using 'Direct Select' Mode (Normal) Campaign - Exhaust System Shim Plate Installation Campaign - COMAND(R) and or Navigation Software Update Body - Laminated Glass Chip and or Crack Repair Information Steering - Power Steering Fluid Requirements Recall - Model 251, MY2006 Repair or Replace Starter Wiring Harness Entertainment System - No Audio From iPod(R) Transmission - Harsh 1-2, 3-2 and 2-1 Shifts

Campaign: Model 164 MY2006

Jul 13, 2006	2006060002	Inspect Air Suspension Compressor and Replace if Necessary (AMK air compressor)
Jun 30, 2006	T-46.10/39	Interior - Chrome Peeling Off Steering Wheel Spokes
Jun 15, 2006	T-88.20/47	Parktronic(R) System - Activates By Itself
Jun 14, 2006	T-72.10/65	Interior - Door Trim Panel Creaking Noise
Jun 13, 2006	T-88.70/49	Lighting - Moisture In Turn Signals in The Mirrors
Jun 8, 2006	T-32.20/39	Suspension - Rear End Creaking and or Grunting Noise On Bumps
Jun 6, 2006	T-88-80-51	Body - Windshield Water Deflector Protrudes Upwards
Jun 1, 2006	2006040007	Campaign - Spare Tire Inspection and or Replacement
Jun 1, 2006	T-63.50/09	Body - Fuel Filler Flap Is Loose
		Model 164, Model Year 2006 Model 251, Model Year 2006
		Head Unit Not Turning ON or Intermittently Locking Up
May 26, 2006	T-82.85/506	Message "TeleAid Visit Workshop" Displayed In the Instrument Cluster
		MODEL 163.154/157/172/175 (starting with MY2001)
		MODEL 164.175 MODEL 251.175 MODEL 463.249
		Troubleshooting Fault Codes Related to:
		- Adaptation Limits of Lambda Control
May 5, 2006	S-B-07.61/039c	- Mass Air Flow Sensors / Intake Air Temperature Sensor
Apr 26, 2006	T-00.00/81C	Engine - Increased Oil Consumption
Apr 20, 2006	T-54.30/136D	Instruments - SCN Coding for Components R & R
Apr 11, 2006	T-83.40/77	Air Conditioning - Actual Temperature Differs From Setting
Apr 11, 2006	T-05.20/17A	Engine Controls - MIL ON and or DTC P2034 Set
Apr 10, 2006	T-27.60/68C	Auto Trans - Harsh 2-1 Downshift When Braking or Coasting
		Installation Bulletin
		Model 164.175/186 (Models with Tele Aid*) Model Year 2006
Apr 07, 2006	T-I-82.70/435C	Cellular Telephone Installation (5 MB)
Apr 3, 2006	T-82.95/501	Cell Phone - TeleAid(R) Calls Will Not Connect
		Recall - Model 251 Model Year 2006 2nd Row Seat Inspection and or Replacement
Apr 1, 2006	2006040003	Entertainment System - Rear Seat System Installation
Apr 1, 2006	T-82.60/440A	Cellular Phone - Installation Instructions
Apr 1, 2006	T-82.70/435C	Audio System -Poor Audio Quality When Using Cell Phone
Mar 23, 2006	T-82.70/493	Cell Phone - Digital TeleAid(R) Calls Won't Connect
Mar 20, 2006	T-82.95/495	Suspension - Strut and or Shock Replacement Guidelines
Mar 15, 2006	T-32.25/20A	Body - Rear Engine Compartment Cover Broken
Mar 3, 2006	T-88.30/43	Brakes - Multiple Warnings Displayed on Instrument Panel
Mar 3, 2006	T-42.45/63A	Campaign - Strut Tower Reinforcement
Mar 1, 2006	2006010005	
Feb 28, 2006	T-91.30/103	Interior, Air Conditioning - Driver and or Passenger Seat Heaters Inop.
Feb 24, 2006	T-72.20/43B	Body - Power Tailgate Closer Intermittently Inoperative
Feb 1, 2006	2006010002	Campaign - Spare Wheel Bolt Package Inspection
Jan 20, 2006	T-27.60/68	Auto Trans Controls - Uncomfortable and or Harsh 2-1 Coast Downshift
Jan 10, 2006	T-82.30/453A	Wipers - Noisy and or Chattering After Wiper Blade Replacement
Jan 2, 2006	T-61.30/04	Body and or Suspension - Rubbing Noise From Rear
2005		
		Installation Bulletin
		Model 251.165/175 (Models with Tele Aid*), Model Year 2006
Dec 22, 2005	T-I-82.70/454A	Cellular Telephone Installation (6MB)
Dec 21, 2005	T-94.10/04	Body and or Restraints - Noise From C-Pillar Area
Dec 19, 2005	T-27.60/67	Engine Controls - Incorrect Software Loaded
Dec 13, 2005	T-27.60/65	Auto Trans Controls - No Range Sensor Learning After EHS R & R
Dec 12, 2005	T-91.60/93	Air Bag System - SRS Lamp ON and or DTC's 9200 and or 9210 Set
Dec 1, 2005	T-82.95/480	Cell Phone - Can't Connect Call and or FC D662 in TeleAid Unit
Nov 29, 2005	T-07.00/56	Engine Controls - Engine Hesitation and or Stalling on Start-Up
Nov 21, 2005	T-54.30/151	Instruments - Entering Total Mileage Into Cluster
Nov 21, 2005	T-77.20/41	Body - Sunroof Wind Deflector Glass Panel Interference
Nov 17, 2005	T-41.10/03	Drivetrain - Highway Speed Front Driveshaft Vibration
Nov 17, 2005	T-82.60/474	Audio System - ESN Number Missing From Display
Nov 7, 2005	T-72.20/53	Body - Tailgate Cannot Be Opened
Nov 7, 2005	T-82.62/470	Audio System - No Reception in AM-FM and or Weather Bands
Nov 5, 2005	T-54.21/154A	Antitheft System - ATA Fault Code 90C7 in Rear SAM
Aug 1, 2005	T-82.85/441C	Navigation System - DVD Navigation Installation
May 1, 2005	2005050004	Recall - Power Steering Hose Clamp Replacement
Apr 1, 2005	T-82.60/440	Entertainment System - Rear Seat Entertainment System
Apr 1, 2005	T-82.85/441B	Navigation System - DVD System Installation and or Setup
Mar 30, 2005	T-82.60/442	Instruments - Phone Menu Messages Displayed
Mar 18, 2005	AP00.20-P-0	Reset Service Indicator Model 251 (also Model 164)
Mar 01, 2005	T-82.60/438	Entertainment Systems - iPod(R) Integration Kit
Feb 28, 2005	S-B-99.00/300	INTRODUCTION INTO SERVICE MANUAL (PRELIMINARY)
		STARTING MODEL YEAR 2006 MODEL 164