

14:39 07APR15

16:08 07APR15

LIST

NET

TOTAL

LINE OPCODE TECH TYPE HOURS

A CUSTOMER STATES CUSTOMER STATES CENTER CONSOLE LEATHER GETTING VERY LOOSE AND STRETCHED. DIAG PLEASE. SOP PART INSTALL

CAUSE: 685705 COVER ON STOWAGE BOX/TRAY BETWEEN FRONT SEATS REPLACE

1 221-680-00-96-8L50 COVER 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: 0.00

38807 CHECKED VEHICLE. FOUND CENTER CONSOLE COMPARTMENT COVER LEATHER RIPPLED AND LOOSE. NECESSARY TO REPLACE. REPLACED CENTER CONSOLE COMPARTMENT COVER. CHECKED OPERATION - GOOD.

B CUSTOMER WAITING!!!

XX SEE R.O. DETAIL 1218 C 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE B: 0.00

38807 JA

C RBM COURTESY VEHICLE INSPECTION (GLASS, LIGHTS, TIRES) MPI-GLT RBM COURTESY VEHICLE INSPECTION (GLASS, LIGHTS, TIRES)

1218 C 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE C: 0.00

38807 PERFORMED GLT INSPECTION.

D COMPLIMENTARY CAR WASH WITH VACUUM AND TIRE SHINE (\$19.95 VALUE) CCW COMPLIMENTARY CAR WASH WITH VACUUM AND TIRE SHINE (\$19.95 VALUE)

1215I-DET 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE D: 0.00

38807 PERFORMED COMPLIMENTARY CAR WASH. VACUUMED INTERIOR AND ADDED TIRE SHINE TO ALL TIRES.