



DTB

Date: November 19, 2008
Order No.: S-B-54.35/193a
Supersedes: S-B-54.35/193 dated Feb. 21, 2008
Group: 54

Revision History

Revision	Date	Purpose
a	11/19/08	Production Cut-Off Added
-	2/21/08	Initial issue

**SUBJECT: All Passenger and Light Truck Models
Up to April 2008 Production
Replacing the Fanfare Horns**

If you receive customer reports in the above model vehicles of the horn not functioning correctly, and it is due to corrosion, replace both the tweeter (510 Hz) and the woofer (420 Hz) even if only one horn is defective. Refer to vehicle specific WIS documentation for replacement instructions.

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.