Countermeasure for WSS sensor noises

Topic number LI91.10-P-057042

Version 1

Design group 91.10 Front seats

Date 10-14-2013

Validity Model series 221 with code 494 (USA) or U10 (Front pas-

senger seat with weight sensing)

Reason for change Damage code and validity adapted

Supersedes P-B-91.10/160

Complaint:

Noises from seat frame during relative movement.

Cause:

Creaking noise from the spherical bearing of the WSS sensors installed on the door side.

Remedy:

Treat door-side spherical bearings with lubricants (see attachment) from the noise kit (Noise Damping Service Kit).

Attachments					
File	Designation				
WSS Lager schmieren.pdf	Spherical bearing				

Symptoms
Body / Seat / Seat noises / Cracking
Body / Seat / Seat noises / Grunting
Body / Seat / Seat noises / Metallic noise
Body / Seat / Seat adjustment / Noise
Body / Seat / Seat noises / Creaking

Parts							
Part number	ES1	ES2	Designation	Quantity	Note	EPC	Other ma-ke
A0009893660			Special antifriction agent, fluid	1	Either of the two lubricants listed can be used (not claimable under warranty as these are part of the noise dampening kit)		X
A0029890751			Multipurpose grease, metal	1	Either of the two lubricants listed can be used (not claimable under warranty as these		Х



		are part of the noise dampe-	
		ning kit)	

Work units								
Op. no.	Operation text	Time	Damage code	Note				
			82149 36	Weight sensor - Noise				