



**DTB**

Date: June 4, 2008  
 Order No.: P-B-91.10/165  
 Supersedes:  
 Group: 91

**SUBJECT: Model 221.171/176/177/179/186**  
**Noises from Front Seat Storage Container Area**

If you receive customer reports in the above model vehicles of noises from the front of the driver/passenger seats, this may be caused by the locking system of the storage container in the front of the seat. To correct, apply the special lubricant oil (A000 989 36 60) to the striker (Figure 1, circle). The special lubricant oil is also included in the Noise Dampening Service Kit (A000 580 03 50).



Figure 1 P-B-91.10/165

**Parts Information**

Qty.	Part Name	Part Number
1	Special lubricant oil	A000 989 36 60 <sup>1</sup>

<sup>1</sup>Sufficient for 30 cars, Submit as Local Purchase – MLD00142, Qty 1, handling is included

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.



**Note:** The following allowable labor operations should be used when submitting a warranty claim for this repair. This information has been generated on June 4, 2008. Please refer to Netstar → Star TekInfo → Star Time for the most current labor time allowance.

**In Case of Warranty**

**Operation:** Lubricate storage compartment lock (68-0000)

<b>Damage Code</b>	<b>Operation Number</b>	<b>Time (hrs.)</b>	<b>Model Indicator (s)</b>
68353 11	68 0000	0.1 hrs. *	AA, AB, AC, AD, AE

\* Maximum time allowed with a separate time punch. Ensure that punches are labeled as NON time.