



**DTB**

Date: September 26, 2008  
Order No.: P-B-72.00/57b  
Supersedes: P-B-72.00/57a dated May 23, 2008  
Group: 72

**Revision History**

Revision	Date	Purpose
b	9/26/08	Warranty Information Updated
a	5/23/08	Applicable Models Updated (216 Added)
-	3/30/06	Initial issue

**SUBJECT: Model 216.371/376/377/379  
Model 221.171, VIN Range A009500 to A027500  
Door Stop Is Loose**

If you receive customer reports in the above model vehicles that either the front or rear door stop is loose because the plastic retainer (Figure 1) at the rod end has broken, the plastic retainer is now available as a spare part. Carefully align the new retainer with the socket when installing. It is no longer necessary to replace the complete front or rear door stop.



Figure 1

P-B-72.00/57

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.

**Parts Information**

Qty.	Part Name	Part Number
1	Retainer	A221 727 12 14



**Note:** The following allowable labor operations should be used when submitting a warranty claim for this repair. This information has been generated on September 26, 2008. Please refer to Netstar → Star TekInfo → Star Time for the most current labor time allowance.

**In Case of Warranty**

**Operation:** Retainer – door stop (specify location), replace (72-0000)

Damage Code	Operation Number	Time (hrs.)	Model Indicator (s)
72027 38	72 0000	0.2 hrs. *	DA, DB, DC, DD
and/or	72 0000	0.2 hrs.	DA, DB, DC, DD
72A0S 38 (left front) and/or 72N0S 38 (right front)	72 0000	0.2 hrs. *	AA
73A0R 38 (left rear) and/or 73N0R 38 (right rear)	72 0000	0.2 hrs. *	AA

\*Separate time punch required. Ensure that punches are labeled as NON time.