
AR32.22-P-8100SX **Check AIRmatic for leaks** 3.5.12

MODEL 221.0/1 **MODEL** 216

With 4MATIC



P32.22-2406-09

#### Illustrated on model 221.056

Central reservoir (pressure reservoir)

#### Pressure line connections:

4SP To central reservoir (black) 5VL To left front suspension strut (green)

6P To AIRmatic compressor unit (brown)

2 Central reservoir (pressure

reservoir)

3 Electrical connector

### Pressure line connections:

To central reservoir (black) 4SP 5VL To left front suspension strut (green)

To AIRmatic compressor unit

6P (brown)

To right rear suspension strut

7HR (red)

To left rear suspension strut

8HL

(blue) 9VR To right front suspension strut

(yellow)


A9/1 AIRmatic compressor unit AIRmatic pressure sensor R7 Y36/6 Level control valve unit

7HR To right rear suspension strut (red) 8HL To left rear suspension strut (blue) 9VR To right front suspension strut (yellow) 10 Front suspension strut 11 Right rear suspension strut

Left rear suspension strut

12

A9/1 AIRmatic compressor unit B7 AIRmatic pressure sensor Y36/6 Level control valve unit



P32.22-2398-05

$\Xi$	Removing		
⚠ Danger!	Risk of death caused by vehicle slipping or toppling off of the lifting platform	Align vehicle between columns of vehicle lift and position four support plates at vehicle lift support points specified by vehicle manufacturer.	AS00.00-Z-0010-01A
i	Notes on AIRmatic		AH32.22-P-1000-02SX
1	Remove front section of lower engine compartment paneling	Vehicles without code (Z07) Top protection	AR61.20-P-1105SX

		Vehicles with code (Z07) Top protection	AR61.20-P-1105SXS
2	Remove fender liner in front fenders		
4	Checking		
3	Spray pressure line connections with leak detector spray	Cover objects (rear shelf, head restraints etc.) in the vicinity of the spraying area with a clean rag.  i Spray the following pressure line connections: Connections (4SP, 5VL, 6P, 7HR, 8HL, 9VR) on valve unit (Y36/6), connection (4SP) of compressor unit (A9/1), connection (4SP) on central reservoir (2), connections (5VL, 9VR) and areas of adhesive on front suspension struts (10), connections (7HR, 8HL) and areas of adhesive on rear suspension struts (11, 12).  i Wait for approx. 10 to 15 min. after spraying the pressure line connections with leak detection spray. This allows smaller leaks to be detected (bubbles form). Larger leaks are visible immediately.	
1		Leak detection spray	*BR00.45-Z-1002-03A
		for USA	*BR00.45-Z-1004-03A
		If pressurized line connection fitting is defective:  ↓ Repair AlRmatic pressure line connection.  Im  Im  Im  Im  Im  Im  Im  Im  Im  I	AR32.22-P-2001-02SX *BA32.22-P-1002-03D *BA32.22-P-1004-03D *BA32.22-P-1006-03D *BA32.25-P-1003-04L *BA32.25-P-1006-04L *000589122800 *211589000900 *BR00.45-Z-1002-03A
77	Inetall	for USA	*BR00.45-Z-1004-03A
X	Install		
4	Install fender liner in front fenders	V 1 : 1 : 1 : 1 : 1 : 1 : 1 : 1 : 1 : 1	A DO 4 00 D 44050);
5	Fit front section of lower engine compartment paneling	Vehicles without code (Z07) Top protection  Vehicles with code (Z07) Top protection	AR61.20-P-1105SX AR61.20-P-1105SXS

## Nm Air suspension


Number	Number Designation		Model 216	Model 221
BA32.22-P-1002-03D	Pressure line air suspension to pressure reservoir	Nm	5	5
BA32.22-P-1004-03D	Pressure line, air suspension to compressor	Nm	5	5
BA32.22-P-1006-03D	Pressure line of air suspension to valve unit	Nm	3	3


# Nm Suspension struts

Number	Designation	Model 216 with 4MATIC	Model 221 without 4MATIC and without code 487, Z07/ Z07+Z19
BA32.25-P-1003-04L	Air suspension pressure line to suspension strut Nm	5	5
BA32.25-P-1006-04L	Air suspension pressure line to rear air spring Nm	5	5

# Nm Suspension struts

Number	Designation	Model 221 with code 207/Z07+Z19	Model 221 with 4MATIC
BA32.25-P-1003-04L	Air suspension pressure line to suspension strut Nm	5	5
BA32.25-P-1006-04L	Air suspension pressure line to rear air spring Nm	5	5





Slitting knife

Wrench socket

### Repair materials

Number	Designation	Order number
BR00.45-Z-1002-03A	Leak detection spray	Christof Fischer GmbH, Augsburger Str. 289-293, 70327 Stuttgart Germany Tel. +49 711 30502-0 Fax +49 711 30502-10 www.kaeltefischer.de
BR00.45-Z-1004-03A	Leakage spray for USA	LIQUI MOLY Gary Boyd 1820 Clark Avenue Long Beach, CA 90815 USA Tel. +1 562 5975519 Fax + 1 562 5975269 www.liqui-moly.com