

Fitting of fuel filler door

Topic number	LI88.60-P-059886
Version	1
Design group	88.60 Exterior flaps
Date	10-06-2014
Validity	222
Reason for change	

Complaint:

Improper alignment of fuel filler door

Cause:

Misalignment of the fuel door or filler cover

Remedy:

For special repair solution, please see attachment

Attachments	
File	Description
Repair solution, 222 fuel filler flap alignment.pdf	Fuel door alignment

Parts							
Part number	ES1	ES2	Designation	Quantity	Note	EPC	Other make part
08935003			Replast easy 2-component fast plastic adhesive	1	Wurth Plastic adhesive for Example 1, step 7		X
HENKEL			Teromix 6700	1	Loctite Plastic adhesive for Example 1, step 7		X
A 001 987 47 40			Rubber bumper	1		X	
A 001 983 23 10			Felt	1	1 strip approx. 20x8 mm	X	