

Noise from seat belt height adjustment

Topic number	LI91.40-P-057018
Version	2
Design group	91.40 Seat belts, emergency tensioning retractors
Date	11-18-2013
Validity	Model series 176, 242, 246, 204, 117, 222
Reason for change	Validity updated

Complaint:

Creaking noise from left or right front seat belt height adjustment mechanism.

Cause:

Belt height adjuster.

Remedy:

Replace belt height adjuster.

Symptoms

Body / Safety system / Seat belt / Seat belt extender / Noise

Parts

Part number	ES1	ES2	Designation	Quantity	Note	EPC	Other make part
A 000 860 03 88			Belt height adjuster	1	The belt height adjuster can be installed on the left or right.	X	

Work units

Op. no.	Operation text	Time	Damage code	Note
			91A58 36	Left belt height adjuster
			91N58 36	Right belt height adjuster