

Map pocket on front seat backrest trim does not close

Topic number	LI91.10-P-063347
Version	1
Design group	91.10 Front seats
Date	02-12-2016
Validity	222
Reason for change	

Complaint:

The tensioning strap for the map pocket on the front seat backrest trim does not exhibit any tensile stress so that the map pocket no longer closes automatically.

Attachments	
File	Description
Pic. 1.jpg	Map pocket no longer closes

Cause:

Loss of tensile force caused by embrittlement of elastic band because of high heat level in the vehicle.

Remedy:

Replacement of affected backrest trim.

Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note
91-5832	LEFT BACKREST TRIM PANEL		81A34 38	Stowage net/magazine pocket in left front seat backrest
91-5852	RIGHT BACKREST TRIM PANEL		81N34 38	Stowage net/magazine pocket in right front seat backrest

WIS-References			
Document number	Title	Note	Allocation
AR91.10-P-1910LF	Remove/install seat-back lining on front seat backrest		Remedy