

Night performance of 360° camera too dark

Topic number	LI54.65-P-059114
Version	1
Design group	54.65 Parking assist
Date	05-27-2014
Validity	166 with code 501 produced up to 07/2014 212 with code 501 produced up to 07/2014 222 with code 501 produced up to 20 May 2014
Reason for change	

Complaint:

At night, the picture from the 360° camera in the display on the head unit can appear too dark.

Cause:

Image processing software

Remedy:

Model series 222

Software update with optimized parameters is available for XENTRY via the add-on 3644 DVD 03/2014.

Model series 166/212

A software update will be provided for XENTRY via an add-on after 08/2014.

Symptoms

Communication/information / Warning and control system / Parking assist / 360° camera / Picture unsharp

Control unit/fault code

Control unit	Fault code	Fault text
360° camera - 360° camera (N148) (SVS166) (E (212),M (166))	-	-
360° camera - 360° camera (N148) (SVS222) (S (222))	-	-

Work units

Op. no.	Operation text	Time	Damage code	Note
54-0650	BATTERY CHARGER C&D		8207T 90	

XENTRY

54-1011	SHORT TEST			
54-0991	INSTALL S/W			