

## Rattling/clattering noise from trunk lid control (KDS) drive unit

Topic number	LI88.50-P-062539
Version	1
Design group	88.50 Trunk lid
Date	11-03-2015
Validity	MODEL 217
Reason for change	

**Complaint:**

Trunk lid control (KDS) drive unit rattles on rough roads.

**Cause:**

Due to accumulative tolerances between the ball head (1) and the ball socket (2) of the KDS drive unit (3), excessive play can occur (see picture).

This can cause noises while driving.

Attachments	
File	Description
Bild.JPG	Picture

**Remedy:**

Apply felt (4) onto ball head (1) (see picture).

Parts						
Part number	ES1	ES2	Designation	Quantity	Note	EPC
A 001 983 23 10			Felt	1		X