

## Charging behavior of iPhone 14 with the mobile phone cradle for driver's side (MTAS-D) WMI\_7

---

Topic number	LI82.70-P-075967
Version	1
Function group	82.70 - Telephone, Voice-control-system(VCS)
Date	3/2/23
Validity	Model series 206, 254, 223, 294, 295, 296, 297, 232 with WMI_7
Reason for change	

---

### Complaint

Wireless charging start/charging behavior of iPhone 14 is not optimal

### Cause

Change in iPhone software (iOS)

### Remedy

There will be optimized software for iPhone 14 iOS (target date 05/2023).

This LI will be updated when the software becomes available.

A software update with currently available iOS software will not be effective for the iPhone 14.

Symptoms				
Communication/information > Communication > Mobile phone > Telephone > Telephone/cell phone is not detected				
Communication/information > Communication > Mobile phone > Telephone > Device error				
Communication/information > Communication > Mobile phone > Telephone > Telephone is not charged				
Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note

---