

SUBJECT: DEALER TECHNICAL BULLETIN 80/00

80/00-2 GROUP 88 - ALL 129 MODELS TO CHASSIS NUMBER F200000, TRUNK LID NOT OPENING: In case of a complaint of the trunk lid not opening after exposure to high temperatures or direct sunlight, replace the lock assembly with modified part number 129 750 03 84 05.

For warranty, please use Damage Code: 75021 16

Service Engineering

ENcm

12-05-00

064346