
Preceding work:

Carrier of viscous fan clutch removed (20-3140) Belt pulley/vibration damper removed (03-3420).

Operation no. of operation texts and work units or standard texts and flat rates 20-1270




P20-5299-57

Coolant hoses (4), (5) and (6)	detach, attach.
Connection cover at top (2) with engine	
lifting eye (1)	. unbolt, bolt on (21 Nm).
Gasket (2a)	replace.
Model 210 with secondary air injection: retaining plate with switchover valve for secondary	
air injection	unbolt at coolant pump (3), bolt on.
Coolant pump (3)	
	\triangle
	Coolant pump housing, see Note.
Sealing surfaces	clean.
Gasket (3a)	replace.

Coolant pump (3) fit on, bolt on (21 Nm).

Pay attention to different bolt lengths, see bolt diagram.


Cooling system...... check for leaks (20-0170).



P20-5300-55

A	Engine 119.96	В	Engine 119.97/98
10	M8x60 bolt+washer	10	M8x60 bolt+washer
11	M8x65 bolt+washer	11	M8x65 bolt+washer
13	M8x85 bolt+washer	12	M8x75 bolt+washer
14	M8x90 bolt+washer	13	M8x85 bolt+washer
	(together with fan clutch carrier)	14	M8x90 bolt+washer
15	M8x135 bolt+washer		(together with fan clutch carrier)
		15	M8x135 bolt+washer

Special tool



Tightening torque in Nm


Bolts of cover at top to coolant pump	21
Bolts of coolant pump to crankcase	21

Note

Engine 119.97

The coolant pump must not touch the timing case cover at the bottom (arrows) otherwise the attaching hose and the gasket may not be aligned and the top attaching eye may shear off.

Check position of coolant pump and grind off coolant pump housing, if necessary, in the area of the arrows by about 1 mm.



P20-5337-15