Practical hints

What to do if ...

Left display	Right display	Possible cause	Possible solution
ESP	Display malfunction Visit workshop	The ESP or the ESP display is malfunctioning.	► Continue driving with added caution.
			► Have the system checked at an authorized Mercedes-Benz Center as soon as possible.
			Failure to follow these instructions increases the risk of accident.
	Unavailable See Oper. Manual	The ESP is deactivated because the power supply has been interrupted.	Synchronize the ESP. With the vehicle stationary, turn the steering wheel com- pletely to the left and then to the right.
		The SBC brake system is still functioning normally but without the ESP available.	, ,
			► Continue driving with added caution.
			► Have the system checked at an authorized Mercedes-Benz Center as soon as possible.
			Failure to follow these instructions increases the risk of an accident.

!

When sychronizing the ESP, make sure you can turn the steering wheel in both directions as far as it will go without the

wheels hitting any objects, e.g. a road curb.