





Date: July 20, 2011

Order No.: S-B-07.61/89a, S-B-54.21/244a

Supersedes S-B-07.61/89, S-B-54.21/244, July 8, 2011

Group: 07, 54

Revision a: Revised with SDS instruction.

SUBJECT: MY-AII, Models AII

Engine Control Module (N3/10) Flashing

Do not flash the engine control module (N3/10), unless specifically instructed to do so in a technical document, such as a LI, Service Bulletin, Campaign, or Diagnostic Tree; or the SDS Diagnostic System indicates to do so.

Failure to adhere to this policy will result in rejected warranty claim or a debit. Unnecessary flashing could have an adverse effect on vehicle functionality.

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Records.