

Mercedes-Benz MHI Approved Phones

| Handset Model | Carrier | Software Level Tested | Adapter |
|--------------------------------|--------------------|--|----------------------------------|
| Apple iPhone | AT+T | v1.0.2, v1.1.1, v1.1.2, v1.1.3, v1.1.4, v2.0, v2.0.1 | B67875878 |
| Apple iPhone 3G | AT&T | SW2.2 | |
| Apple iPhone 3GS | AT&T | SW3.0 | |
| Blackberry 7250 | Verizon | V4.0.0.204 | |
| Blackberry 7290 | Cingular/ T-Mobile | V4.0.2.32 | |
| Blackberry 7100g | Cingular /T-Mobile | V4.0.0.219 | |
| Blackberry 8703e | Verizon | 4.1.0.344 | |
| Blackberry 8700g | T-Mobile | 4.1.0.346 | |
| Blackberry 8700c | Cingular | 4.1.0.377 | |
| Blackberry 8800 | Cingular | V4.2.1.72 | |
| BlackBerry Curve 8300 | AT&T | 4.2.2.89 2.4.0.39 | |
| BlackBerry Curve 8310 | AT&T | 4.2.2.170 , 4.2.2.184 | |
| BlackBerry Flip 8220 | T-Mobile | v4.6.0.160 | |
| BlackBerry 9000 Bold | AT&T | v4.6.0.167 | |
| BlackBerry 9530 Storm | Verizon | v4.7.0.75 | |
| BlackBerry 8900 Javelin | AT&T | v4.6.1.101 | |
| BlackBerry 8830 | Verizon /Sprint | 4.2.2.66 | |
| BlackBerry 8120 | At&T/T-Mobile | 4.3.0.91 | |
| BlackBerry 8110 | AT&T | 4.3.0.93 | |
| BlackBerry Tour | Verizon | 4.7.1.40 | |
| Kyocera Strobe K612B | Alltel | SL1.0.00 | |
| LG VX5500 | Verizon | VX550V02 | |
| LG versa VX9600 | Verizon | VX960V02 | |
| LG VX8100 | Verizon | T81VZV05 | |
| LG Chocolate VX8500 | Verizon | T85VZ03 | |
| LG VX9800 | Verizon | T98VZV01 | |
| LG VX 8800 Venus | Verizon | VX880V02 | |
| LG Chocolate 3 VX 8560 | Verizon | VX8560V05 | |
| Motorla A455 Rival | Verizon | RUSH01_01.29.15P | either adapter will work fine |
| Motorola VE 20 | Sprint | VEGAS2_00.60.00R | |
| Motorola V950 | Sprint | WATER2_00.59.01P | |
| MB Motorola V710 | Verizon | MB proprietary SW | |
| Motorola E815 | Verizon | 1.17.03, 01.1E.00 | |
| Motorola V3c | Verizon | 01.0F.03, 01.15.04 | |
| Motorola V3c | Alltel | GATW_04.06.00R | |
| Motorola V3m | Verizon | NEWC_01.05.0A, NEWC_01.09.02 | |
| Motorola V325i | Verizon | MLNBT1_01.07.00R | |
| Motorola RAZR ² V9m | Alltel | SPARK0_X_02.0B.09P | |
| Motorola RAZR ² V9m | Verizon | PARS_01.15.0D | |
| Motorola RAZR ² V9 | AT&T | U_9C.13.37R_1 | |
| Motorola K1m | Verizon | 24.1_00.25.0C | B67876131 |
| Motorola Q | Verizon | 04.08.04P, 06.07.03P, 06.0B.11P | |
| Motorola Q9m | Verizon | C_03.20.0EP | |
| Motorola RAZR V3 | Cingular /T-Mobile | 0E.42.09R, 0E.42.0ER, 0E.40.57R, 0E.41.C3R_B, 0E.CO.15R, | |
| Motorola V3i | Cingular | R47A_G_08.D9.3DR | |
| Motorola V3t | T-Mobile | R3443U5_G_0E.C8.0DR | |
| Motorola ROKR E1 | Cingular | 30.34R_A | |
| Motorola V330 | T-Mobile | 8.18.1DR | |
| Motorola PEBL U6 | T-Mobile | 08.83.76R, 08.83.76R_A | |
| Motorola RIZR Z3 | T-Mobile | R452B_G_08.01.02R | |
| Motorola V551 | Cingular | 8.18.16R_OA | |
| Motorola V557 | Cingular | 08.28.3DR_A3, 08.28.40R | |
| Motorola SLVR L7 | Cingular | 08.C4.1ER, 08.C4.25R | |
| Motorola V3xx | Cingular | R26111LD_U_96.71.95R | |
| Motorola K1 | Cingular | R4527_G_08.42.0BR_A | |
| Motorola Rokr Z6 | Verizon | PARS_01.16.0C | |
| Motorola KRAVE ZN4 | Verizon | BLAZE1_01.19.0AP | |
| Motorola ZINE ZN5 | T-Mobile | R6637_G_81.11.17R_128 | |
| Motorola W755 | Verizon | COOL01_00.30.08P | |
| Motorola Vu30 | Verizon | CHARL1_01.30.06P | |
| Nokia 5300 | T-Mobile | V05.02 | |
| Nokia 6133 | T-Mobile | V05.23 | |
| Nokia 6102i | Cingular | 4.63 | |
| Nokia 6555 | AT&T | V03.31 | |
| Palm Centro | Sprint | CENTRO-1.00 | |
| Samsung Roque U960 | Verizon | V. u960.CG022 | |
| Samsung Jack | AT&T | CE OS 5.2.20293 Build 20293.1.3.10 | |
| Samsung M800 | Sprint | ES.M800 BH 29 | |
| Samsung U470 Juke | Verizon | u470.AH23 | |



either adapter
will work fine

