

2018 Mercedes Benz E63S AMG 4MATIC Sed (213.089) V8-4.0L Turbo (177.980)

Vehicle > Technical Service Bulletins

A WELCOME IMAGE IS NOT SHOWN ON THE INSTRUMENT CLUSTER.



Mercedes-Benz

- A welcome image is not shown on the instrument cluster. -

Topic number	LI54.30-P-069433
Version	1
Function group	54.30 Instrument cluster, display instruments, hazard warning device
Date	02-20-2019
Validity	Model series 205/213/217/222/238/253 with code 809 and code B01 (48 V technology) Model series 205/213/217/222/238/253 with code 808 and code 058 (Modification year 17/2) and code B01 (48 V technology)
Reason for change	

Complaint

The instrument cluster does not show a welcome image.

Cause

In vehicles with 48 V on-board electrical system, the animation is disabled.

Remedy

This is by design and there will be no further changes that will be made to incorporate the welcome message.

Symptoms

Symptom

Communication/information / Information display / Displays / Multifunction display / Multifunction display, menu / Menu items missing

Communication/information / Information display / Displays / Multifunction display / Multifunction display, menu / Incomplete display

Communication/information / Information display / Displays / Multifunction display / Multifunction display, menu / Faulty display

Control unit/fault code

Control unit	Fault code	Fault code description
A1 - Instrument cluster (IC) (IC213) (E (213),S (217),S (222),C - (205),E (238))	-	

