

2018 Mercedes Benz E63S AMG 4MATIC Sed (213.089) V8-4.0L Turbo (177.980)

Vehicle &gt; Technical Service Bulletins

## ADS INDICATOR LAMP ILLUMINATED AFTER INSTRUMENT CLUSTER REPLACEMENT OR SOFTWARE UPDATE



Mercedes-Benz

### - ADS indicator lamp illuminated after Instrument Cluster replacement or software update -

Topic number	LI54.30-P-070378
Version	1
Function group	54.30 Instrument cluster, display instruments, hazard warning device
Date	10-29-2019
Validity	Model series 213
Reason for change	

## Complaint

After the instrument cluster has been replaced, or the instrument cluster (A1) software has been updated, the indicator lamp for the ADS suspension system may be illuminated.

**File**

ADS indicator lamp.JPG.jpg

**Designation**

ADS indicator lamp illuminated

## Cause

Previous software releases for the Instrument Cluster (A1) and Adaptive Damping System suspension control unit (N51/5) are not compatible.

## Remedy

After replacing or performing a software update on the Instrument Cluster (A1), update the ADS suspension control unit (N51/5) software.

## Symptoms

**Symptom**

Communication/information / Information display / Displays / Multifunction display / Function / Malfunction

**ADS indicator lamp**

