

2018 Mercedes Benz E63S AMG 4MATIC Sed (213.089) V8-4.0L Turbo (177.980)

Vehicle > Technical Service Bulletins

DISPLAY OF SUSPENSION SETTING IN HEAD UNIT IMPLAUSIBLE



Mercedes-Benz

- Display of suspension setting in head unit implausible -

Topic number	LI54.30-P-068430
Version	1
Function group	54.30 Instrument cluster, display instruments, hazard warning device
Date	07-20-2018
Validity	213.#88 / #89 from modification year February 2017 to modification year January 2018
Reason for change	

Complaint

Display of suspension setting in head unit does not match actual suspension setting, the display in the switch is correct

Cause

Air Body Control (SPC) control unit software

Remedy

Update software for Air Body Control (SPC) control unit using Xentry as of version 05/18

Symptoms

Symptom

Communication/information / Information display / Displays / Multifunction display / Multifunction display, menu / Faulty display