

Trunk Lid Electronic Closing Function Inoperative

Topic number	LI80.40-P-075378
Version	2
Function group	80.40 - Power locking
Date	2/21/23
Validity	MODEL 213.0, MODEL 213.1, MODEL 257, MODEL 238 all with code 881 from manufacturing date April 1, 2021.
Reason for change	Update of remedy requirements for TIPS case
Reason for block	Update of remedy requirements for TIPS case

Complaint

The trunk lid is not latching into the closed position with the help of the trunk lid power closing function after the electric closing process.

There is a loud rattling from the trunk or from the trunk lid power closing unit (M14/31).

Cause

Under Analysis

Remedy

Please create a TIPS case before attempting repair on the vehicle

- Within case attach a video showing the concern
- Attach CUL for N121

Symptoms
Body > Door/Flap > Hood/flap > Trunk lid/liftgate > Does not close
Body > Door/Flap > Power closing > Malfunction

Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note