

2018 Mercedes Benz E63S AMG 4MATIC Sed (213.089) V8-4.0L Turbo (177.980)

Vehicle > Technical Service Bulletins

TIME IN INSTRUMENT CLUSTER AND ON ANALOG CLOCK CHANGES CONTINUOUSLY AND AT RANDOM



Mercedes-Benz

- Time in instrument cluster and on analog clock changes continuously and at random -

Topic number	LI54.30-P-067251
Version	3
Function group	54.30 Instrument cluster, display instruments, hazard warning device
Date	04-05-2018
Validity	Model series 213/238 with code 464 up to and including production date, March 2017
Reason for change	Cause, remedy, AN and validity adapted.

Complaint

The time in the instrument cluster and on the analog clock changes continuously and at random. The clock in the display shows the correct time. See Attachment A.

File	Designation
A.mp4	A

Cause

Damaged processor in the IC through electrostatic discharge in production process.

Remedy

Please replace the instrument cluster.

WIS references

Document number	Title	Note	Allocation
AR54.30-P-6015LWE	Remove/install instrument cluster	Valid for vehicles up to production year 2016! Validity: Model 213, 238	Remedy

Symptoms

Symptom

Communication/information / Information display / Displays / Clock / Malfunction

Communication/information / Information display / Displays / Clock / Too fast

Communication/information / Information display / Displays / Clock / Too slow

Communication/information / Information display / Displays / Clock / Synchronization with navigation system nonfunctional

Communication/information / Information display / Displays / Clock / Remains stationary

Control unit/fault code

Control unit	Fault code	Fault code description
A1 - Instrument cluster (IC) (IC213)	-	-

Operation numbers/damage codes

Op. no.	Operation text	Time	Damage code	Note
			5440T50	Cockpit clock shows incorrect readings