

2018 Mercedes Benz E63S AMG 4MATIC Sed (213.089) V8-4.0L Turbo (177.980)

Vehicle > Technical Service Bulletins

SPLITTING OF SEAT COVERS



Mercedes-Benz

- Splitting of Seat Covers -

Topic number	LI91.10-P-063393
Version	4
Function group	91.10 Front seats
Date	05-03-2018
Validity	All Models
Reason for change	Remedy Adapted

Complaint

Splitting of seat covers

Cause

Currently being investigated.

Note: Please see pictures for examples of what above damages looks like.

File	Designation
CIMG3870.JPG.jpg	Splitting 3
CIMG3875.JPG.jpg	Splitting 2
CIMG3876.JPG.jpg	Splitting 1
Pictures.pdf	Splitting 4

Remedy

Note: Please observe if outside influence such as improper cleaning agents or sharp cutting devices were the cause of splitting. This type of damage will not be covered under warranty. Please reference WIS document AP68.00- P-1000ZZ for proper cleaning instructions.

Replace Seat Covers as needed.

Symptoms

Symptom

Body / Seat / Seat cover / Detaches

Parts

Part number	ES1	ES2	Designation	Quantity	Note	EPC
A 001 986 25 71					Example of approved MB TEX cleaner	X

A 001 986 59
71

Example of
approved
leather
cleaner X

CIMG3870




CIMG3875



CIMG3876



LI91.10-P-063393_4



Mercedes-Benz