

2018 Mercedes Benz E63S AMG 4MATIC Sed (213.089) V8-4.0L Turbo (177.980)

Vehicle > Technical Service Bulletins

CHROME SURFACE DETACHING FROM STOWAGE BOX/ASHTRAY



Mercedes-Benz

- Chrome surface detaching from stowage box/ashtray -

Topic number	LI68.20-P-068649
Version	3
Function group	68.20 Center console
Date	02-21-2019
Validity	Valid for vehicles of model series 205/253/213/238 with automatic transmission. Not valid for vehicles with world manufacturer code LE4.
Reason for change	Title clarification

Complaint

Surface of border of stowage box is detaching

File

IMG_0102.jpg

IMG_0103.jpg

Designation

Frame of stowage box/ashtray

Damage to frame of stowage box/ashtray

Cause

Insufficient connection of base material to surface material.

Remedy

Replacement of damaged frame with optimized component parts.

The optimized frames are available individually as a replacement part.

The replacement is done as per WIS document AR68.20-P-0002LWE.

WIS references

Document number	Title	Note	Allocation
AR68.20-P-0002LWE	Remove/install center console stowage compartment trim element		Remedy

Symptoms

Symptom

Body / Interior equipment / Stowage box/tray / Warped/twisted/distorted

Body / Interior equipment / Stowage box/tray / Broken

Body / Interior equipment / Stowage box/tray / Scratched

Body / Interior equipment / Ashtray / Does not open

Body / Interior equipment / Ashtray / Does not close

Parts

Part number	ES1	ES2	Designation	Quantity	Note	EPC
A 205 683 09 00			Trim strip	1	Valid for model series 205/253	X
A 205 683 10 00			Trim strip	1	Valid for model series 205 with WMI (Wireless phone charging, available as of facelift)	X
A 213 683 06 00			Trim strip	1	Valid for model series 213/238	X

IMG_0102



IMG_0103

