



 Immediate Attention
***REPL SERPENTINE BEL**

\$1,829.15

Technician's comments:

INSPECTED SERPENTINE BELT AND TENSIONER FOUND THAT BELT IS WALKING OUT FROM TENSIONER. RECOMMEND TO REPLACE SERPENTINE BELT PULLEYS AND BELT TENSIONER.

Price Breakdown

Labor **\$1,112.99**

Parts

Qty	Part Number	Part Description	Price
1	003-993-85-96	V-RIBBED BELT	\$103.43
1	276-202-01-19	GUIDE PULLEY	\$133.80
1	276-200-03-70	BELT TENSIONER	\$366.55

\$603.78

Miscellaneous

Misc Code	Description	Price
SS	ENVIRONMENTAL CHARGES/SUP	\$71.84

\$71.84

Tax **\$40.54**

Total **\$1,829.15**

 **ADD TO CART**

[!\[\]\(56549452e01ca28bdf2500ced9653143_img.jpg\) BACK TO INSPECTION](#)