COMAND Online: Address book of mobile phone is not transferred

Topic number	LI82.70-P-066766
Version	1
Design group	82.70 Telephone, Voice-control-system(VCS)
Date	07-19-2017
Validity	Model 205 with code 531 and code 807
	Model 217 with code 531 and code 807
	Model 222 with code 531 and code 807
	Model 253 with code 531 and code 807
Reason for change	

Complaint:

The address book of the mobile phone is not transferred. The message "Data being read … Please wait" is shown on the display (A40/8) of the COMAND Online (A40/3, A26/17).

This can occur irrespective of the mobile phone used.

Cause:

Software release of COMAND Online (A40/3, A26/17).

Remedy:

Please make sure that automatic address book download is activated in the menu settings of the COMAND Online (A40/3, A26/17).

Repeat commissioning of COMAND Online (A40/3, A26/17) with Regio ECU software 07/2017 or newer.

After the software update, the number is E229.7, 17/12.05.

Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note
			8210R 50	