P82.86-5361-09

1	Covering	5 Bolt	8 Electrical connector (for code
2	Bolts	6 Bolts	(864) Rear entertainment
3	Cover frame	7 Electrical connectors	system)
4	Cover		
			A40/3 COMAND control unit

⟨⟩ ⟨⟩		Remove/install		
⊙		Information on preventing damage to electronic components due to electrostatic discharge		AH54.00-P-0001-01A
1.1		Temporarily store basic data of COMAND control unit (A40/3) in STAR DIAGNOSIS	When replacing COMAND control unit (A40/3). ⓘ **Installation:** Copy temporarily stored basic data to new COMAND control unit (A40/3).	
☞AD		Connect STAR DIAGNOSIS and read out fault memory		AD00.00-P-2000-04A
			STAR DIAGNOSIS diagnosis system	*WH58.30-Z-1048-13A
2		Switch off ignition and remove transmitter key or Keyless Go start/stop button from EIS [EZS] control unit	ⓘ Keyless Go start/stop button only for vehicles with code (889) Keyless Go.	
3		Unclip panel (1)	🛠	*115589035900
4		Unscrew bolts (2)	Rechargeable drill / screwdriver	*WH58.30-Z-1007-20A
5		Open cover frame (3) and fold covers (4) of bolts (5) inwards and up		
6		Undo bolts (5) and close covers (4)	Rechargeable drill / screwdriver	*WH58.30-Z-1007-20A
7		Close and remove cover frame (3)		
8		Undo bolts (6) and remove COMAND control unit (A40/3), until the electrical connectors (7) are accessible	Rechargeable drill / screwdriver ⓘ The bolts (6) remain on the COMAND control unit (A40/3). ⊙ **Installation:** Carefully slide in COMAND control unit (A40/3) to avoid damage to electrical lines and fiber optic cables.	*WH58.30-Z-1007-20A
9 ⊙		Disconnect electrical connectors (7) Notes on avoiding damage to fiber optical cables during repair work		AH82.60-P-0001-05AK
10.1		Disconnect electrical plug (8)	For vehicles with code (864) Rear entertainment system	
11		Remove COMAND control unit (A40/3)		
12		Install in the reverse order		

115 589 03 59 00

Long wedge

Commercially available tools

Number	Designation	
WH58.30-Z-1048-13A	STAR DIAGNOSIS diagnosis system, Compact Passenger Car	6511 1801 00
WH58.30-Z-1007-20A	Cordless drill/driver	