

**MERCEDES-BENZ USA, LLC**

One Mercedes Drive, P.O. Box 350, Montvale, NJ 07645-0350  
Phone (201) 573-0600  
Fax (201) 573-0117  
MBUSA.com



Mercedes-Benz

---

To: All Mercedes-Benz Dealer Sales, Service and Parts Managers

---

From: After-Sales Business Development

---

Date: June 29, 2007

---

Re: Bluetooth Cradle Replacer Launch Announcement

---

## **Available Now**

The Bluetooth Cradle Replacer enables MY 2003/2004 E-Class and MY 2004 S/CL-Class cars for Bluetooth Hands-Free use, even if the vehicle was never equipped with a phone system. This is possible because these vehicles are equipped with the CP211 TeleAid module already featuring Hands-Free support from the factory.

This product is an attractive Hands-Free solution that delivers the following benefits:

- Low cost - Takes advantage of existing CP211 phone functionality
- Fully featured - even provides phone book download with a range of popular, approved, retail handsets
- Simple installation - simply connects to cradle connector prewired in center console
- Easy to sell opportunity to upgrade preowned vehicles to state-of-the art Bluetooth technology for customers who want to use a new, current approved handset
- Provides flexibility for future approved retail handset upgrades

MSRP for the Bluetooth Cradle Replacer (B67875855) is \$388.00







See the list published at the end of this announcement for complete details on compatible handsets, and handset software levels. Note that updating the vehicle's audio head unit software to the latest version is also recommended to ensure certified system performance.

**MERCEDES-BENZ USA, LLC**

One Mercedes Drive, P.O. Box 350, Montvale, NJ 07645-0350  
 Phone (201) 573-0600  
 Fax (201) 573-0117  
 MBUSA.com



Mercedes-Benz

 <b>Bluetooth Cradle Adaptor/Replacer compatible Handset listing</b>				
Cradle	Handset model	Image	Carrier	Required Software Level
<b>B6 787 5856</b> 	Motorola V330		T- Mobile	8.18 1 DR
	Motorola V551		Cingular	8.1816R_OA
	Motorola V557		Cingular	08.28.3DR_A3, 08.28.40DR
<b>B6 787 5855</b> 	Motorola E815		Verizon	1.17.03.01.1E.00
	Motorola V710		Verizon	MB Proprietary SW
	Motorola SLVR L7		Cingular	08.C4.1ER, 08.C4.25R
	Motorola RAZR V3 V3c V3m		Verizon Alltel Verizon	01.0F.03.0115.04 GATW_04.06.00R NEWC_01.05.0A
	Motorola PEBL U6		T- Mobile	08.63.76R.08.83.76R_A
	Motorola Q		Verizon	04.08.04P, 06.07.03P
	Motorola V3i		Cingular	R47A_G_08.D9.3DR
	Motorola K1m		Verizon	24.1_00.25.0C
	Motorola K1		Cingular	R4527_G_08.42.0BR_A
	Blackberry 8100		Cingular	v4.2.0.69