

MY '04, '05, & '06 SIRIUS Installation Kits & Required Parts



Mercedes-Benz

Updated 2/09/06

If a vehicle is not listed here it isn't compatible with SIRIUS

MY 2006	Model Number	Installation Kit	Receiver	Antenna	Splitter	Additional Parts Required	Note
S-Class	V220	B6 783 0086	B6 783 0060	See Antenna Chart	None	None	Splitter is no longer required if B6 783 0060 Receiver is used
CL-Class	C215	B6 783 0067	B6 783 0085	B6 783 0015	None	None	Gen 2 antenna not required, B6 783 0085 will be replaced with new part number
CLK Coupe	C209	B6 783 0071	B6 783 0060	See Antenna Chart	None	None	Splitter is no longer required if B6 783 0060 Receiver is used
E-Class Sedan until June 05 production	W211	B6 783 0069	B6 783 0060	See Antenna Chart	None	None	If vehicle is produced June 05 or later it is not prewired for Sirius; Splitter is no longer required if B6 783 0060 Receiver is used
E-Class Sedan with Panorama Sunroof	W211	B6 783 0069	B6 783 0060	See Antenna Chart	None	None	Splitter is no longer required if B6 783 0060 Receiver is used
E-Class Wagon (until June 05 prod.)	S211	B6 783 0070	B6 783 0060	See Antenna Chart	None	B6 783 0038 and B6 783 0040 - Cutting and drilling templates	Prewire ends in June 05 production; Splitter is no longer required if B6 783 0060 Receiver is used
CLS	W219	B6 783 0062	B6 783 0060	See Antenna Chart	None	None	Splitter is no longer required if B6 783 0060 Receiver is used
G	G463	B6 783 0077	B6 783 0013	See Antenna Chart	B6 783 0058	None	D2B-bus receiver

MY 2005	Model Number	Installation Kit	Receiver	Antenna	Splitter	Additional Parts Required	Note
S-Class	V220	B6 783 0086	B6 783 0060	See Antenna Chart	None	None	Splitter is no longer required if B6 783 0060 Receiver is used
CL-Class	C215	B6 783 0067	B6 783 0085	B6 783 0015	None	None	Gen 2 antenna not required, B6 783 0085 will be replaced with new part number
E-Class Sedan	W211	B6 783 0069	B6 783 0060	See Antenna Chart	None	None	Splitter is no longer required if B6 783 0060 Receiver is used
E-Class Wagon	S211	B6 783 0070	B6 783 0060	See Antenna Chart	None	B6 783 0038 and B6 783 0040 - Cutting and drilling templates	Splitter is no longer required if B6 783 0060 Receiver is used
SL-Class	R230	B6 783 0068	B6 783 0060	See Antenna Chart	None	Early MY05 SL may require the retrofit of bracket A 230 545 41 40	Splitter is no longer required if B6 783 0060 Receiver is used
SLK	R171	B6 783 0078	B6 783 0060	See Antenna Chart	None	None	Splitter is no longer required if B6 783 0060 Receiver is used
C-Class Sedan	W203	B6 783 0073	B6 783 0060	See Antenna Chart	None	None	Splitter is no longer required if B6 783 0060 Receiver is used
C-Class Wagon	S203	B6 783 0074	B6 783 0060	See Antenna Chart	None	B6 783 0037 and B6 783 0039 - Cutting and drilling templates	Splitter is no longer required if B6 783 0060 Receiver is used
C-Coupe	CL-203	B6 783 0075	B6 783 0060	See Antenna Chart	None	None	Splitter is no longer required if B6 783 0060 Receiver is used
CLK Coupe	C209	B6 783 0071	B6 783 0060	See Antenna Chart	None	None	Splitter is no longer required if B6 783 0060 Receiver is used
CLK Cabriolet	A209	B6 783 0072	B6 783 0085	B6 783 0015	None	None	Gen 2 antenna not required, B6 783 0085 will be replaced with new part number
ML	W163	B6 783 0076	B6 783 0013	See Antenna Chart	B6 783 0058	B6 783 0024 CDC Bracket (if no CDC in vehicle)	D2B-bus receiver
G	G463	B6 783 0077	B6 783 0013	See Antenna Chart	B6 783 0058	None	D2B-bus receiver

MY 2004	Model Number	Installation Kit	Receiver	Antenna	Splitter	Additional Parts Required	Note
S-Class	V220	B6 783 0086	B6 783 0060	See Antenna Chart	None	None	Splitter is no longer required if B6 783 0060 Receiver is used
CL-Class	C215	B6 783 0067	B6 783 0085	B6 783 0015	None	None	Gen 2 antenna not required, B6 783 0085 will be replaced with new part number
E-Class Sedan	W211	B6 783 0069	B6 783 0060	See Antenna Chart	None	None	Splitter is no longer required if B6 783 0060 Receiver is used
E-Class Wagon	S211	B6 783 0070	B6 783 0060	See Antenna Chart	None	B6 783 0038 and B6 783 0040 - Cutting and drilling templates	Splitter is no longer required if B6 783 0060 Receiver is used
SL-Class	R230	B6 783 0068	B6 783 0013	See Antenna Chart	B6 783 0058	B6 783 0027 - Adaptor cable and B6 783 0021 Bracket	D2B-bus receiver
C-Class Sedan	W203	B6 783 0073	B6 783 0013	See Antenna Chart	B6 783 0058	None	D2B-bus receiver
C-Class Wagon	S203	B6 783 0074	B6 783 0013	See Antenna Chart	B6 783 0058	B6 783 0037 and B6 783 0039 - Cutting and drilling templates	D2B-bus receiver
CLK Coupe	C209	B6 783 0071	B6 783 0013	See Antenna Chart	B6 783 0058	None	D2B-bus receiver
CLK Cabriolet	A209	B6 783 0072	B6 783 0013	B6 783 0015	None	None	Gen 2 antenna not required; D2B-bus receiver
ML	W163	B6 783 0076	B6 783 0013	See Antenna Chart	B6 783 0058	B6 783 0024 CDC Bracket (if no CDC in vehicle)	D2B-bus receiver
G	G463	B6 783 0077	B6 783 0013	See Antenna Chart	B6 783 0058	None	D2B-bus receiver

Antenna Chart

Gen 2 Antenna:	Part Number
Black	B6 783 0080
Pewter	B6 783 0081
Iridium Silver	B6 783 0082
Alabaster White	B6 783 0083
Primed, Unpainted	B6 783 0084