



6 LEDs missing




Both positions circled.

Resistors in this area are going to be difficult to mount. May try to salvage donor surface mount resistors marked "4701."




Six resistors needed.





Notice the orientation of the LEDs for polarity. The dark “dot” goes towards the outside edge of the PCB.



This how I would solder the 1/8 watt resistors