

Mercedes Benz Of Sugar Land Repair Estimate

SAFETY ISSUES				
Description Of Repair	Labor	Parts	Tax	Total
	-	-	-	-
	-	-	-	-
	-	-	-	-
	-	-	-	-
	-	-	-	-
	-	-	-	-
	-	-	-	-
	-	-	-	-
	-	-	-	-
	-	-	-	-

MECHANICAL ISSUES, LEAKS, SCHEDULED MAINTAINENCE				
Description Of Repair	Labor	Parts	Tax	Total
DIAGNOSIS CHECK ENGINE LIGHT ON	4,879.20	720.00	59.40	5,658.60
FAULT CODE 1200,1208			-	-
REMOVE & REINSTALL ENGINE			-	-
DISASSEMBLE & REASSEMBLE ENGINE			-	-
REPLACE ENGINE BALACE SHAFT (GEAR WORN)			-	-
			-	-
			-	-
			-	-
			-	-
			-	-

COSMETIC AND APPEARANCE				
Description Of Repair	Labor	Parts	Tax	Total
			-	-
			-	-
			-	-
			-	-
			-	-
			-	-
			-	-
			-	-
			-	-
			-	-



TOTALS	
Safety	-
Maint.	5,658.60
Cosmetic	-
Total	5,658.60

Customer Name [REDACTED]

VIN Number [REDACTED]

Phone Number [REDACTED]

Year / Make 2006 C230

Mileage 82572

[Handwritten signature and scribbles]