
| STEERING TESTING & REPAIR 203 CHASSIS | |
|---------------------------------------|--|
| aps | Fig. 12: Identifying Steering Angle Sensor Remove/Install Components - Illustrated On Model 209.342 2006 Mercedes-Benz C280 4Matic |

1 Inspection window 2 Locking pin

A45 Clock spring contact N49 Steering angle sensor



P46.10-2351-11

Sunday, December 26, 2010 10:56PM

Page 1

© 2005 Mitchell Repair Information Company, LLC.