


CDI 3 - Common Rail Diesel Injection 3				- F -
MB number	HW version	SW version	Diagnosis version	Pin
0014465440	44.2003	11.2005	66/20	7
FW number		FW number (data)	FW number (boot SW)	
0034482540		0034482540		
Code	Text			Status
1664-004	Check component N33/2 (Heater booster control module). Signal line is interrupted.			Current and stored

ETC - Electronic transmission control				i
MB number	HW version	SW version	Diagnosis version	Pin
0325454232	03.2001	36.2003	2/2	101
Event	Text			Status
P2311	One or more messages from the engine control unit are not available on the CAN bus. (CAN timeout fault)			Event STORED
P2312	One or more messages from the engine control unit are not available on the CAN bus. (CAN timeout fault)			Event STORED

ESP - Electronic stability program				- f - i
MB number	HW version	SW version	Diagnosis version	Pin
0345457032	30.2003	47.2003	1/6	101
Code	Text			Status
C1038	Engine control module not identified or incorrect control module			STORED
Event	Text			Status
C1022	CAN communication with the engine system is faulty. 			Event STORED

SAM-F - Signal acquisition and actuation module front				i
MB number	HW version	SW version	Diagnosis version	Pin
2035452901	38.2003	39.2003	0/19	101
Event	Text			Status
B1036	The input signal 'circuit 61' is not o.k.			Event STORED

REAR SAM - Rear signal acquisition and actuation module				- F -
MB number	HW version	SW version	Diagnosis version	Pin
2035453201	15.2003	37.2003	3/17	101
Code	Text			Status