

B1078	Fault in communication with component H3/1 (Alarm signal siren with additional battery) or there is a cable fault.	Current and stored
-------	--	--------------------

ICM - Instrument cluster with maintenance interval display				i
MB number 2035405047	HW version 10.2004	SW version 44.2003	Diagnosis version 17/1	Pin 101
Event	Text			Status
9102	CAN communication with the engine system is faulty.			Event STORED

SCM [MRM] - Steering column module				i
MB number 2035401145	HW version 50.2003	SW version 50.2003	Diagnosis version 1/0	Pin 101
Event	Text			Status
9348	Communication over engine CAN bus is faulty.			Event STORED

Battery voltage	13.05 V
------------------------	---------

Filename: F:\Programme\DAS\bin\..trees\pkw\main\kt\kt203.s
Cell co-ordinate: 1 , 3