

Telefon:

CARSOFD Diagnosis-report
Vehicle tvpe:
License plate:
Customer:

24.05.2016

Single diagnosis ME - Status: ERROR !

P201D-001 Self-adaptation from the mixture forming (rich) (P0172)

P2039-001 Air recirculation flap (P0243)

P200B-001 Hot film Mass Air Flow sensor: Short circuit to plus (P0103).