

Mercedes WIS

Čeština Dansk Deutsch Ελληνικά English Español Suomi Français Magyar Italiano 日本語 한국어  
 Nederlands Polskie Português Română Русский Slovenščina Svenska Türkçe 简体中文


|                  |                                |            |
|------------------|--------------------------------|------------|
| AR83.10-P-4501LW | Remove/install side air nozzle | 21.01.2016 |
|------------------|--------------------------------|------------|

|       |     |
|-------|-----|
| Model | 205 |
| Model | 213 |
| Model | 253 |

Shown on model 205.### 1#

|   |                  |
|---|------------------|
| 1 | Left side vent   |
| 2 | Instrument panel |

P83.10-2874-04



|   |   |   |               |
|---|---|---|---------------|
|   | Remove/install  |   |               |
| 1 | Adjust the steering column backwards and downwards into its final position  | Model 205.### 1# , 213.### 1# , 253.### 1#  |               |
| 2 | Insert extraction hook into side notches (arrows) of left side air vent (1) and pull left side air vent (1) out of instrument panel (2) | Installation: "Make sure that ""TOP"" marking on left side air vent (1) is pointing upwards." |               |
|   |   | Extraction hook   | *140589023300 |
| 3 | Install in the reverse order  |   |               |

Extraction hook

140 589 02 33 00

