
AR01.20-P-5014-03MR	Bolt tightening procedure for cylinder head	
	cover	

ENGINE 274

 $\overline{\rm Nm}$ Crankcase ventilation, cylinder head cover, camshaft bearing housing

Number	Designation			ENGINE 274
BA01.20-P-1001-01R	Bolt, cylinder head cover to cylinder head	Stage 1	Nm	10
		Stage 2	۷°	90



P01.20-2311-09

- $\fbox{\ensuremath{\underline{i}}}$ Tighten cylinder head cover bolts in the numerical sequence. Replace screw/bolts.
 - Tighten screw/bolts (1 to 26) according to Stage 2.
- Tighten screw/bolts (1 to 26) according to Stage 1.