


## - Parts list -

|                          |               |                           |  |
|--------------------------|---------------|---------------------------|--|
| <b>Mode</b>              | MD mode       | <b>Mod. des. overview</b> | PASSENGER CAR,SEDAN,<br>-W- MODEL YEAR '98 UP TO IDENT<br>NO. WDBHA33G.W F 757883..... |
| <b>FIN/MD</b>            | 202033        | <b>Catalog</b>            | 44W  |
| <b>VIN</b>               |               | <b>Major assembly:</b>    |  |
| <b>Sales designation</b> | C 43 AMG USA  | <b>Major assembly MD</b>  |  |
| <b>Assortment class</b>  | Car           | <b>Group</b>              | 63 - SIDE PANELS   |
| <b>Market</b>            | North America | <b>Subgroup</b>           | 015 - SIDE PANELS  |

| Item no. | Part number     | Designation/description   | Quantity | Version |
|----------|-----------------|---|----------|---------|
| 5        | A 202 630 07 10 | <b>PILLAR</b><br><b>Replaced by:</b> A 202 630 03 10<br>+001 A 202 630 09 31  | -        |         |
| 5        | A 202 630 03 10 | <b>PILLAR</b><br>A-PILLAR,INSIDE LEFT   | 001      |         |
| 5        | A 202 630 08 10 | <b>PILLAR</b><br><b>Replaced by:</b> A 202 630 04 10<br>+001 A 202 630 10 31  | -        |         |
| 5        | A 202 630 04 10 | <b>PILLAR</b><br>A-PILLAR,INSIDE RIGHT  | 001      |         |
| 6        | A 202 630 09 31 | <b>CONSOLE</b><br>LEFT  | 001      |         |
| 6        | A 202 630 10 31 | <b>CONSOLE</b><br>RIGHT   | 001      |         |
| 8        | A 202 630 07 07 | <b>PANELLING</b><br>A-PILLAR,LEFT   | 001      |         |
| 8        | A 202 630 08 07 | <b>PANELLING</b><br>A-PILLAR,RIGHT  | 001      |         |
| 11       | A 208 637 01 40 | <b>. COVERING</b>   | 001      |         |
| 11       | A 208 637 02 40 | <b>. COVERING</b><br>RIGHT  | 001      |         |
| 17       | A 202 637 09 21 | <b>PILLAR</b><br>A-PILLAR,TOP INSIDE LEFT   | 001      |         |
| 17       | A 202 637 10 21 | <b>PILLAR</b><br>A-PILLAR,TOP INSIDE RIGHT  | 001      |         |
| 20       | A 202 637 01 46 | <b>ROOF RAIL</b><br>LATERAL LEFT  | 001      |         |
| 20       | A 202 637 02 46 | <b>ROOF RAIL</b><br>LATERAL RIGHT   | 001      |         |
| 23       | A 202 630 35 01 | <b>SIDE PANEL</b><br>C-PILLAR,INSIDE LEFT   | 001      |         |
| 23       | A 202 630 36 01 | <b>SIDE PANEL</b><br>C-PILLAR,INSIDE RIGHT  | 001      |         |
| 26       | A 202 637 03 23 | <b>. PILLAR</b><br>LEFT CONNECTOR   | 001      |         |
| 26       | A 202 637 04 23 | <b>. PILLAR</b><br>RIGHT CONNECTOR  | 001      |         |
| 29       | A 202 630 03 13 | <b>. PILLAR</b><br>C-PILLAR,OUTSIDE LEFT  | 001      |         |
| 29       | A 202 630 04 13 | <b>. PILLAR</b><br>C-PILLAR,OUTSIDE RIGHT   | 001      |         |
| 32       | A 202 637 01 76 | <b>. WHEELHOUSE</b><br>REAR OUTSIDE LEFT  | 001      |         |
| 32       | A 202 637 06 76 | <b>. WHEELHOUSE</b><br>REAR OUTSIDE RIGHT   | 001      |         |
| 33       | A 202 984 01 22 | <b>SHEET METAL NUT</b>  | 002      |         |
| 35       | A 202 630 07 11 | <b>PILLAR</b><br><b>Replaced by:</b> A 202 630 11 11<br>+001 A 140 821 05 97<br> [009] Up to ident. no.: | -        |         |
| 35       | A 202 630 11 11 | <b>PILLAR</b><br><b>Replaced by:</b> A 202 630 19 11  | -        |         |

|    |                 |  |     |
|----|-----------------|--|-----|
| 35 | A 202 630 19 11 | <b>PILLAR</b><br>B-PILLAR ON THE LEFT<br>☐ [010] As of ident. no.  | 001 |
| 35 | A 202 630 08 11 | <b>PILLAR</b><br><b>Replaced by:</b> A 202 630 12 11<br>+001 A 140 821 05 97<br>☐ [009] Up to ident. no.:                        | -   |
| 35 | A 202 630 12 11 | <b>PILLAR</b><br><b>Replaced by:</b> A 202 630 20 11   | -   |
| 35 | A 202 630 20 11 | <b>PILLAR</b><br>B-PILLAR ON THE RIGHT<br>☐ [010] As of ident. no.   | 001 |
| 38 | A 202 730 01 37 | <b>HINGE</b><br><b>Replaced by:</b> A 202 730 09 37<br>+001 A 202 730 11 37<br>+004 A 202 990 04 17<br>☐ [006] Up to ident. no.: | -   |
| 38 | A 202 730 09 37 | <b>HINGE</b><br><b>Replaced by:</b> A 202 730 17 37<br>☐ [007] As of ident. no.  | -   |
| 38 | A 202 730 17 37 | <b>HINGE</b><br>REAR DOOR,TOP LEFT<br>☐ [011] IF NECESSARY, THE CUTOUT IN THE B-PILLAR MUST BE REWORKED                          | 001 |
| 38 | A 202 730 02 37 | <b>HINGE</b><br><b>Replaced by:</b> A 202 730 10 37<br>+001 A 202 730 12 37<br>+004 A 202 990 04 17<br>☐ [006] Up to ident. no.: | -   |
| 38 | A 202 730 10 37 | <b>HINGE</b><br><b>Replaced by:</b> A 202 730 18 37<br>☐ [007] As of ident. no.  | -   |
| 38 | A 202 730 18 37 | <b>HINGE</b><br>REAR DOOR,TOP RIGHT<br>☐ [011] IF NECESSARY, THE CUTOUT IN THE B-PILLAR MUST BE REWORKED                         | 001 |
| 41 | A 202 730 03 37 | <b>HINGE</b><br><b>Replaced by:</b> A 202 730 11 37<br>+001 A 202 730 09 37<br>+004 A 202 990 04 17<br>☐ [006] Up to ident. no.: | -   |
| 41 | A 202 730 11 37 | <b>HINGE</b><br><b>Replaced by:</b> A 202 730 19 37<br>☐ [007] As of ident. no.  | -   |
| 41 | A 202 730 19 37 | <b>HINGE</b><br>REAR DOOR,BOTTOM LEFT<br>☐ [011] IF NECESSARY, THE CUTOUT IN THE B-PILLAR MUST BE REWORKED                       | 001 |
| 41 | A 202 730 04 37 | <b>HINGE</b><br><b>Replaced by:</b> A 202 730 12 37<br>+001 A 202 730 10 37<br>+004 A 202 990 04 17<br>☐ [006] Up to ident. no.: | -   |
| 41 | A 202 730 12 37 | <b>HINGE</b><br><b>Replaced by:</b> A 202 730 20 37<br>☐ [007] As of ident. no.  | -   |
| 41 | A 202 730 20 37 | <b>HINGE</b><br>REAR DOOR,BOTTOM RIGHT<br>☐ [011] IF NECESSARY, THE CUTOUT IN THE B-PILLAR MUST BE REWORKED                      | 001 |
| 42 | A 202 990 04 17 | <b>SCREW</b><br>HINGE TO CENTRAL PILLAR<br>☐ [007] As of ident. no.  | 008 |
| 44 | A 202 637 01 47 | <b>ROOF RAIL</b><br>OUTSIDE LEFT   | 001 |
| 44 | A 202 637 02 47 | <b>ROOF RAIL</b><br>OUTSIDE RIGHT  | 001 |
| 47 | A 202 630 01 40 | <b>SUPPORT</b><br><b>Replaced by:</b> A 202 637 01 35<br>+001 A 202 630 03 31  | -   |
| 47 | A 202 637 01 35 | <b>SIDE MEMBER</b><br>LEFT   | 001 |

|    |                 |   |     |
|----|-----------------|---|-----|
| 47 | A 202 630 02 40 | <b>SUPPORT</b><br><b>Replaced by:</b> A 202 637 02 35<br>+001 A 202 630 04 31 | -   |
| 47 | A 202 637 02 35 | <b>SIDE MEMBER</b><br>RIGHT   | 001 |
| 50 | A 202 630 03 31 | <b>CONSOLE</b><br>LEFT,TO JACK  | 001 |
| 50 | A 202 630 04 31 | <b>CONSOLE</b><br>RIGHT,TO JACK   | 001 |
| 70 | A 000 991 76 32 | <b>BLIND RIVET</b><br>REPAIR SOLUTION FOR SPOT WELDS                          | NB  |