

Brake squeal just before standstill

Topic number	LI42.10-P-051397
Version	2
Design group	42.10 Service brake
Date	09-05-2012
Validity	212.074/ 077/ 274/ 277 without code B07 (without AMG ceramic brake system) 218.374 without code B07 (without AMG ceramic brake system) 204.077 / 277 / 377
Reason for change	Update because of current complaints

Complaint:

Brake squeal

Note:

Brake squeal can occur frequently with cold and cooling brakes.

This can also occur in isolated case with brake systems at operating temperature.

Cause:

Frictional vibrations

Remedy:

Note:

The noise comes from the rear axle.

Replacing the brake pads may not provide a remedy.

We will shortly make a remedy available to you and update this TIPS.

Until then, do not perform any other work.

Symptoms
Chassis/suspension / Brake system / Service brake / Brake noise / Squeaking
Chassis/suspension / Brake system / Service brake / Brake noise / Whirring/howling

Work units				
Op. no.	Operation text	Time	Damage code	Note
			42214 36	