

## - Parts list -

<b>Mode</b>	BM mode	<b>BM overview</b>	C 63 AMG
<b>VIN/mod. des.</b>	C204077	<b>Catalog</b>	62P
<b>VIN</b>		<b>Major assembly</b>	Chassis
<b>Assortment class</b>	PC	<b>Major assy. mod. des.</b>	C204077
<b>Market</b>		<b>Group</b>	20 ENGINE COOLING
		<b>Sub-group</b>	015 WATER PUMP























Image ID: drawing\_B20015000473

Item	Part number	Designation/additional information	Qty
10	A 156 200 02 01	<b>TS WATER PUMP</b> Replaced by: A 156 200 05 01 [697] PART IS ONLY OR ALSO SUPPLIED AS RECONDITIONED PART Fault location 20001 Alternative parts are available	1

Copyright 2020-07-28 Daimler AG

Item	Part number	Designation/additional information	Qty
10	A 156 200 05 01	<b>WATER PUMP</b> Replaced by: A 156 200 06 01 +1 A1562020819 GUIDE PULLEY Replaces: A1562000201  [697] PART IS ONLY OR ALSO SUPPLIED AS RECONDITIONED PART  Fault location 20001  Alternative parts are available	1
10	A 156 200 06 01 	<b>WATER PUMP</b> Replaces: A1562000501 +1 A1562020819 Replaces: A1562000201  [697] PART IS ONLY OR ALSO SUPPLIED AS RECONDITIONED PART  Fault location 20001  Alternative parts are available	1
15	A 000 993 12 02 	* <b>CATCH SPRING</b> SCB36 46.4MM  Fault location 5001W	1
17	A 156 201 02 80 	* <b>GASKET</b> WATER PUMP TO TIMING CASE  Fault location 20009	1
19	A 000 990 09 92 	* <b>EXPANSION RIVET</b> WATER PUMP TO TIMING CASE	2
20	A 156 205 00 10	<b>BELT PULLEY</b> AT WATER PUMP  Fault location 20211	1
25	N 000000 001144	<b>HEXALOBULAR BOLT</b> PULLEY TO WATER PUMP; M6X10	4
30	N 000000 001502	<b>HEXALOBULAR BOLT</b> WATER PUMP TO TIMING CASE COVER AND TO CRANKCASE,RESP.; M8X100	1
33	N 000000 002047	<b>HEXALOBULAR BOLT</b> WATER PUMP TO TIMING CASE COVER AND TO CRANKCASE,RESP.; M6X80	1
35	N 000000 001433	<b>HEXALOBULAR BOLT</b> WATER PUMP TO TIMING CASE COVER AND TO CRANKCASE,RESP.; M8X80	3
40	N 000000 001422	<b>HEXALOBULAR BOLT</b> WATER PUMP TO TIMING CASE COVER AND TO CRANKCASE,RESP.; M6X30	6
45	A 156 203 02 75	<b>THERMOSTAT</b> AT TIMING CASE Replaced by: A 156 203 04 75  Fault location 20102, 2030T	1
45	A 156 203 04 75 	<b>GOVERNOR ELEMENT</b> AT TIMING CASE Replaces: A1562030275  Fault location 20102, 2030T	1
50	A 000 993 12 02 	* <b>CATCH SPRING</b> SCB36 46.4MM  Fault location 5001W	1
55	A 156 203 03 80 	* <b>GASKET</b>  Fault location 20105	1

Item	Part number	Designation/additional information	Qty
60	N 000000 002439	<b>HEXALOBULAR BOLT</b> THERMOSTAT TO TIMING CASE; M6X25	2
65	N 000000 001433	<b>HEXALOBULAR BOLT</b> THERMOSTAT TO TIMING CASE; M8X80	1
80	A 156 203 01 64 	<b>VALVE</b> SHUT-OFF VALVE	1
85	A 013 997 24 45 	* <b>SEALING RING</b>	2
90	A 272 993 00 02 	* <b>CATCH SPRING</b>	1
95	N 000000 001146	<b>HEXALOBULAR BOLT</b> VALVE TO CYLINDER HEAD; M6X16	3
100	A 156 203 01 15	<b>PIPING</b> AT CYLINDER CRANKCASE	1
105	N 000000 001151	<b>HEXALOBULAR BOLT</b> MOUNTING PIPE LINE; MBN 10226-M8X12-8.8	2
900	A 211 545 13 28	<b>HOUSING</b> THERMOSTAT Y110; 2-PIN MLK1.2	1
900	A 211 545 13 28	<b>HOUSING</b> HEATER SYSTEM SHUTOFF VALVE Y16/2; 2-PIN MLK1.2	1
901	A 000 982 28 26	<b>CRIMP CONNECTOR CONTACT</b> 0.22-0.35 MM2 MLK1.2S	NB
901	A 001 545 50 80	<b>SINGLE-WIRE SEAL</b> YELLOW; 0.22-1.0 MM2 MLK1.2	NB