

AP AP		ENGINE 156 in MODEL 204 ENGINE 156 in MODEL 212	AP13.22-P-1352CW AP13.22-P-1352EW
6	Check guide pulleys (7, 8, 9, 10) and replace if necessary	Nm Guide pulley to coolant pump housing (between power steering pump and guide pulley with grooved channel profile) Nm Guide pulley to coolant pump housing (between alternator and smooth guide pulley) Nm Guide pulley (between poly-V belt tensioning device and coolant pump) Nm Guide pulley between A/C compressor and vibration damper	*BA13.25-P-1003-01U *BA13.25-P-1004-01U *BA13.25-P-1005-01U *BA13.25-P-1006-01U
	Carry out operation steps 7 and 8 only if removing/installing the poly-V belt tensioning device (6)		
7	Remove screw/bolts (5) and poly-V belt tensioning device (6)	Nm Screw/bolt, poly-V belt tensioning device to timing case cover	*BA13.25-P-1001-01U
	Check		
8	Check poly-V belt tensioning device (6) for damage and soiling; replace if necessary		
9	Install in the reverse order		
Danger !	Risk of accident from vehicle starting off by itself when engine running. Risk of injury (bruises and burns) resulting from working on the engine while it is being started or when it is running.	Secure vehicle to prevent it from starting off by itself. Wear closed and snug-fitting work clothes. Do not touch hot or rotating parts.	AS00.00-Z-0005-01A
10	Carry out an engine test run		

Nm Belt tensioning device

Number	Designation		ENGINE 156, 159
BA13.25-P-1005-01U	Guide pulley (between poly-V belt tensioning device and coolant pump)	Nm	20

9

Nm Belt tensioning device

Number	Designation		ENGINE 156, 159
BA13.25-P-1004-01U	Guide pulley to coolant pump housing (between alternator and smooth guide pulley)	Nm	20

7

Nm Belt tensioning device

Number	Designation		ENGINE 156, 159
BA13.25-P-1003-01U	Guide pulley to coolant pump housing (between power steering pump and guide pulley with grooved channel profile)	Nm	30

8

Nm Belt tensioning device

Number	Designation		ENGINE 156, 159
BA13.25-P-1001-01U	Screw/bolt, poly-V belt tensioning device to timing case cover	M8 Nm	20

5

Nm Belt tensioning device

Number	Designation		ENGINE 156, 159
BA13.25-P-1006-01U	Guide pulley between A/C compressor and vibration damper	Nm	30

10