

Report ID: 61489 | 2016 MERCEDES-BENZ CLA L4, 2.0L; DOHC; 16V; DI; Turbo | VIN: WDDSJ4EB9GN327832 | ODO: 67711 Mi

**Additional Vehicle Information**

Module No: N/A  
CallID: 2709011700154547 | 0009022328300001  
CVN: 91 0B 7F 93 | EB 42 9A EE

**Customer Information**

Date/Time: 09/11/2022 04:59 PM  
First Name:  
Last Name:  
Phone:  
Email:

**Emission Readiness Monitor**



Ready

**Failed Modules**

13


**Battery Life**



14.67V

Good

**TPMS**



**Warranty**



Expired

**Scheduled Maintenance**

17

due at 70,000 miles

**Predicted Failures**

6  
predictions

**Passed Modules**

42

**TSBs**

13

**OBD2 DTCs**

No Powertrain DTCs or Freeze Frame Data is presently stored in the vehicle's computer.

**Fix for DTCs**

**Most Likely Fix**

We do not currently have a Likely Fix for this issue, but our certified technicians are working hard to provide one as soon as possible.

**Monitor Status**

- MIS Misfire
- CCM comprehensive component
- CAT Catalyst
- O2S Oxygen Sensor
- FUE Fuel System
- EGR EGR System
- EVA Evaporative System
- HTR Oxygen Sensor Heater

ABS

**DTC**                      **Status**

C015000	Current Stored MIL	Component 'A7/3b1 (Front Axle Brake Pressure Sensor)' Has An Internal Fault.
C015100	Current Stored MIL	Component 'A7/3b1 (Front Axle Brake Pressure Sensor)' Has An Internal Fault.

SAM - Signal Acquisition and Actuation Module

**DTC**                      **Status**

B21059A	Current Stored
---------	----------------

DKG - Electronic Transmission Control for Double-plate Clutch Transmission

**DTC**                      **Status**

056200	N/A	The Power Supply Of Circuit 87 Has Undervoltage.
267F00	N/A	The Temperature Sensor Of The Control Unit Has A Malfunction.
C10487	N/A	Communication With Control Unit 'Cruise Control' Has A Malfunction. The Message Is Missing.
D40800	Current Stored	An Implausible Signal From Switch 'Brake Lights' Was Received.
D44D00	Current Stored	The Torque Request From Control Unit 'Combustion Engine' Was Not Received.

DCU-LF - Left Front Door

**DTC**                      **Status**

B18B113	Stored	The Output For Central Motor Has Malfunction. There Is A Break.
---------	--------	---

PSD - Control Module 'Panoramic Sliding Roof'

DTC	Status	
B184951	Current Stored	The Actuator Motor 'Roof System' Has A Malfunction. The Component Is Not Programmed.
B184953	Current Stored	The Actuator Motor 'Roof System' Has A Malfunction. The Component Is Deactivated.

#### SG-AWF - COLLISION PREVENTION ASSIST

DTC	Status	
U0416FD	Current Stored	Chassis CAN Bus : No CAN Message Was Received From Control Unit 'Electronic Stability Program'.
U1422FA	Current Stored	Chassis CAN Bus : CAN Signal 'Braking Torque' From Control Unit 'Electronic Stability Program' Is Implausible.
U142200	Current Stored	Chassis CAN Bus : CAN Signal 'Braking Torque' From Control Unit 'Electronic Stability Program' Is Implausible.

#### EFB - Electric Parking Brake

DTC	Status	
U012100	Current Stored	Communication With ESP Has A Malfunction.

#### ES - Electrical Power Steering

DTC	Status	
U041600	Current Stored	Implausible Data Were Received From Control Unit 'Traction System'.

#### AAC - Air Conditioning

DTC	Status	
912749	Current Stored	The Air Quality Sensor Has A Malfunction. There Is An Internal Electrical Fault.
A17E13	Stored	The Power Supply To The LIN Bus Subscribers Has A Malfunction. There Is An Open Circuit.

#### ME - Motor Electronics

DTC	Status	
P06DA00	Current	The Actuation Of The Valve Of The Oil Pump In The Combustion Engine Has An Electrical Fault Or Open Circuit.

#### COU [ZBE] - Audio/COMAND Operating Unit

DTC	Status	
B15562A	Stored	The Controller Sticks In The Depressed Position. There Is No Signal Change.

#### DCU-RF - Right Front Door

DTC	Status	
B18B113	Stored	The Output For Central Motor Has Malfunction. There Is A Break.

#### IC - Instrument Cluster

DTC	Status	
U012187	Stored	Communication With ESP Has Malfunction.

**Passed Modules**

SRS

---

RFK - Backup Camera

---

PARK - Parking System

---

ZAN - Audio/COMAND Display

---

KG - Keyless Go

---

IRS-HLA - Outer Left Rear Intelligent Radar Sensor System

---

ATA - ATA [EDW]/Tow-away Protection/Interior Protection

---

ESA 'Front Passenger' - Electric Seat Adjustment 'Front Passenger'

---

VG - All-wheel Drive

---

TPM - Tire Pressure Monitor

---

SOUND - Sound System

---

Control Unit for Telematics Services

---

PTCU - Control Unit 'Powertrain'

---

Drive Kit Plus - Drive Kit for Iphone

---

MIF - Media Interface

---

KAB - Camera Cover

---

NAV - Navigation Module

---

FSCU07 - Control Unit 'Fuel Pump'

---

SG-SW - Headlamp

---

EZS - Electronic Ignition Lock

---

SG-MSND - Engine Sound

---

DAB - Digital Audio Broadcasting

---

IRS-HRA - Outer Right Rear Intelligent Radar Sensor System

---

ESA 'Driver' - Electric Seat Adjustment 'Driver'

---

HKS - Tailgate Control

---

AMG DRVU - AMG DRIVE UNIT

---

FSCU05 - Control Unit 'Fuel Pump'

---

TV - TV Tuner

---

STH - Stationary Heater

---

MFK - Multifunction Camera

---

ADS - Adaptive Damping System

---

DTR - Distronic

---

SDAR - Satellite Radio

---

REVETR-LF - Left Front Reversible Emergency Tensioning Retractor

---

Trailer Recognition Module

---

REVETR-RF - Right Front Reversible Emergency Tensioning Retractor

---

Head-up Display - Head-up Display

---

SG-SW-R - Right Headlamp

---

SCM - Steering Column Module

---

Audio - Audio or COMAND

---

Multifunction Control Unit

---

SG-SW-L - Left Headlamp

**Next Service: 70000**

**Inspect Body & Paint for Damages/Corrosion**

---

**Inspect Parking Brake Operation & Tension**

---

**Measure Brake Linings, Rotor Thickness and Runout**

---

**Inspect Horn, Lights, A/C & Heater For Proper Operation**

---

**Inspect Brake System, Friction Material and Hydraulic System.**

---

**Change Engine Oil and Filter**

Engine Oil	\$8.18	x7
Engine Oil Filter	\$15.95	x1

---

**Inspect Wiper & Washer System**

---

**Inspect First Aid Kit Expiration Date**

---

**Inspect Interior/Exterior Lights & Electrical Components**

---

**Inspect Driving Aid System Operation (if Equipped)**

---

**Inspect Spare Tire**

---

**Activate Tire Pressure Monitoring System**

---

**Inspect Cooling System**

---

**Inspect Warning System Operation**

---

**Inspect Tire Wear and Adjust Tire Pressure**







---

**Inspect Windshield**

---

**Inspect Tire Sealant Expiration Date**

## Predicted Failures

Predicted Failure(s) within 12 months	Probability of Failure	Price
Inspect for Loose Fuel Tank Cap and Tighten or Replace as Necessary	 21%	\$72.00
Replace Ambient Air Temperature Sensor	 19%	\$103.72
Replace Thermostat	 17%	\$605.81
Replace Ignition Coil(s) and Spark Plug(s)	 15%	\$328.03
Perform Engine De-Carbon Procedure and Replace Spark Plug(s)	 13%	\$360.55
Perform Engine De-Carbon Procedure	 7%	\$181.15



